

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKD9705P/1801029

02nd February 2018

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 30th January 2018
Location : TPE Slip Road To Pasir Ris Road
Third Party Claim Vehicle No : SLG 5860 Y
Repair Cost For Vehicle No : SKD 9705 P (Volvo V50 2.4)

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper fsacia <i>de</i>	1	2,050.00	\$ 2,050.00
2	Rear bumper sponge <i>?</i>	1	210.00	\$ 210.00
3	Rear bumper reinforcement beam <i>?</i>	1	1,540.00	\$ 1,540.00
4	Rear end panel <i>?</i>	1	392.00	\$ 392.00
5	Rear bumper tow cover <i>mis</i>	1	50.00	\$ 50.00
6	Rear bumper reflector RH <i>scr</i>	1	53.00	\$ 53.00
7	Rear bumper reserve sensor <i>DM</i>	1	224.00	\$ 224.00
8	Rear bumper side bracket RH <i>MC</i>	1	56.00	\$ 56.00
9	Rear lamp lower bracket RH <i>?</i>	1	56.00	\$ 56.00
10	Rear inner panel garnish <i>?</i>	1	350.00	\$ 350.00
11	Rear lamp RH <i>?</i>	1	560.00	\$ 560.00
				<u>\$ 5,541.00</u>

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKD9705P/1801029

02nd February 2018

Balance b/f	\$ 5,541.00
<u>Labour Charges :-</u>	<u>Amounts</u>
Remove & refit, knocking & welding straighten & re-align rear end panel, all affected parts & etc	\$ 850.00 <i>200-400</i>
Spray painting on damage parts	\$ 900.00 <i>400</i>
Check all lighting after repairs	\$ 65.00 <i>30</i>
Labour Charge	<u>\$ 1,815.00</u>
Total Amount	<u>\$ 7,356.00</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

3 Days.

part by part.

before paint photos.

Em. Qiang - 82880282

01/2/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: