



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

PC 4873 R

Parts	(a) Cost / List Price Items	\$	600.50
	Plus/Less 30%	\$	180.15
	Total of Cost / List	\$	420.35
	(b) Nett Price Items	\$	666.60
	Less 10%	\$	66.66
	Total of Nett Item	\$	599.94
	(c) Special Nett Items	\$	35.00
Total Parts Cost		\$	1,055.29
Labour		\$	2,530.00
Total		\$	3,585.29

The above total will be subjected to 7% G.S.T.

Not Authorized
11 Sep @ ?
Recovery After Pain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 13/12/18 at 10:00am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Lc

Date: 13/12/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **PC 4873 R**
Make & Model : **NISSAN NV350**
Chassis No : **JN1MC2E26Z0006646**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>Build</i>	1	\$600.50		✓
2	Rear bumper clip <i>Ne</i>	10	\$35.00	S.N	✓
3	Rear bumper side retainer RH <i>Dir</i>	1	\$36.60	N	✓
4	RH rear panel <i>R1</i>	1	\$411.80	N	✓
5	RH rear hub cab <i>nd/1/1x</i>	1	\$218.20	N	✓
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are
will be charged accordingly under supplementary.

