

ESTIMATE

DATE OF ACCIDENT : 31/01/2018
VEHICLE : SLV331
MAKE & MODEL : TOYOTA SIENTA
INSURANCE : AIG ASIA PACIFIC INSURANCE PTE LTD
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	REAR BOOT / <i>Buc</i>		\$ 1450 <i>1200</i>
2.	REAR BOOT LOCK <i>BT</i>		\$ 280 <i>/</i>
3.	REAR BOOT HINGE <i>X NN</i>		\$ 180 <i>X</i>
4.	REAR BOOT WEATHERSTRIP <i>X</i>		\$ 315 <i>X</i>
5.	REAR BUMPER <i>/ Re</i>		\$ 750 <i>380</i>
6.	REAR BUMPER DIFFUSER <i>/ List</i>		\$ 390 <i>2250</i>
			<i>25% 1687.5</i>
SPECIAL NETT			
1.	CLIPS x 45 <i>/</i>		\$ 58 <i>40</i>
2.	WINDSCREEN SEALANT <i>/ MCL</i>		\$ 150 <i>50</i>
			<i>90</i>
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	<i>400</i>	\$ 750
2.	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	<i>300</i>	\$ 720
3.	TO CHECK WIRING & REWIRING	<i>20</i>	\$ 180
4.	TO REMOVE AND REINSTALL REAR WINDSCREEN	<i>120 100</i>	\$ 150
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	<i>60</i>	\$ 180
		<i>900</i>	<i>2677.5</i>



	PARTS - 25%:	\$ 2,523.75
	LABOUR :	\$ 1,980
	TOTAL :	\$ 4,503.75
	7% GST :	\$ 315.26
	GRAND TOTAL :	\$ 4,819.01

3 Days .
part by part .
before paint photos .
Guo Qiang - 82880282
07/2/18 .

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: