

T/ADIM

INS. CASE OWNER

CC 6 UR
1800 2203, U Y63LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

Specialist

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
6/12/18	Non-Reporting ltr (1st):	
6/12/18	Non-Reporting ltr (2nd):	
6/12/18	Non-Reporting ltr (Final):	
6/12/18	Notification ltr (if non-pickup):	
6/12/18	Call OI:	6/12/18 email.
6/12/18	After call ltr to OI:	6/12/18 email.
6/12/18	Documentation Check List:	Handler Typist
6/12/18	Notification ltr (if non-pickup)	
6/12/18	After call ltr to OI:	
6/12/18	Authorisation To Act:	
6/12/18	Release Voucher:	
6/12/18	Final Repair Bill:	
6/12/18	Car Rental Invoice:	
6/12/18	Towing Invoice:	
6/12/18	LTA / GIA:	
6/12/18	Medical Bill:	
6/12/18	PIR:	
6/12/18	Mandate/Reject Instruction:	
6/12/18	LOD:	
6/12/18	Payment Breakdown Form:	
6/12/18	Post-Repair Photos:	
6/12/18	Others:	
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost: SS (days) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/>		
FINAL SETTLEMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL		
Repair Cost: 4651 SS 5877.48		
Loss of Rental (LOR): SS (days)		
Loss of Use (LOU): SS 400.00 (5 100 x 4 days)		
Loss of Income (LOI): SS (5 x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)		
GIA/LTA Search: SS -		
Medical: SS -		
Disbursement: SS (e.g. Tow/ Independent)		
Legal Cost: SS -		
Total: SS 6277.48 Global Sum SS:		
FINAL PAYMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: SS 6277.48 Name 1: Specialists Motor Pte Ltd		
Payee 2: (Strike if N.A.) SS Name 2:		
Payee 3: (Strike if N.A.) SS Name 3:		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18002203/wb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 05-02-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 8792A	Veh. Inspected	SKB 6880X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/02/2018	Inspection Date		
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Not Advised
see
take photo when going
4 days.
6/2/18

Date of Accident : 01st February 2018

Location : 37A Cambridge Rd Multi Storey Car Park

Third Party Claim Vehicle No : SLJ 8792 A

Repair Cost For Vehicle No : SKB 6880 X (BMW Z4)

1/1/18 5492.97

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>see/70.1</i>	1	1,054.65	\$ 1,054.65
2	Front bumper clips <i>see</i>	1 set	50.00	\$ 50.00
3	Front bumper side retainer L&RH <i>all same</i>	2	45.70	\$ 91.40
4	Front bumper sensor LH <i>check</i>	1	236.85	\$ 236.85
5	Front bumper reinforcement beam <i>11</i>	1	626.35	\$ 626.35
6	Front bumper sponge <i>11</i>	1	57.55	\$ 57.55
7	Front bumper lower garnish LH <i>11</i>	1	55.50	\$ 55.50
8	Front bumper emblem <i>see</i>	1	67.80	\$ 67.80
9	Headlamp LH <i>see</i>	1	2,425.30	\$ 2,425.30
10	Headlamp ballast LH <i>11</i>	1	846.70	\$ 846.70
11	Headlamp lower bracket LH <i>11</i>	1	218.95	\$ 218.95
12	Headlamp bulb LH <i>11</i>	1	372.20	\$ 372.20
13	Headlamp washer cover <i>11</i>	1	41.10	\$ 41.10
14	Headlamp washer nozzle jet assy <i>see</i>	1	152.10	\$ 152.10
15	Front fender cowling LH <i>70.1</i>	1	118.40	\$ 118.40
16	Bonnet lock <i>11</i>	1	171.60	\$ 171.60
				\$ 6,586.45

5%

1- 4592.6
52
4362.97

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

Balance b/f \$ 6,586.45

Labour Charges :-

Amounts

Cut out, renew, knocking & welding, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body

\$ 1,280.00

500

Tuff-kote on damage parts

11 \$ 40.00

2

Spray painting on damage parts

\$ 1,080.00

600

Check lighting after repairs

\$ 60.00

30

Labour Charge

\$ 2,460.00

Total Amount

\$ 9,046.45

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 01st February 2018
Location : 37A Cambridge Rd Multi Storey Car Park
Third Party Claim Vehicle No : SLJ 8792 A
Repair Cost For Vehicle No : SKB 6880 X (BMW Z4)

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Sensor wire	1	181.75	\$ 181.75
				\$ 181.75

GST will be reflected in the final bills.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

*Not about
the photo change
4/2/18*

Date of Accident : 01st February 2018
Location : 37A Cambridge Rd Multi Storey Car Park
Third Party Claim Vehicle No : SLJ 8792 A
Repair Cost For Vehicle No : SKB 6880 X (BMW Z4)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>de/roin</i>	1	1,054.65	\$ 1,054.65 —
2	Front bumper clips <i>neu</i>	1set	50.00	\$ 50.00 —
3	Front bumper side retainer L&RH <i>ru/sino</i>	2	45.70	\$ 91.40 <i>pac</i>
4	Front bumper sensor LH <i>shock</i>	1	236.85	\$ 236.85 ✓
5	Front bumper reinforcement beam <i>17</i>	1	626.35	\$ 626.35 X
6	Front bumper sponge	1	57.55	\$ 57.55 ?
7	Front bumper lower garnish LH	1	55.50	\$ 55.50 ?
8	Front bumper emblem <i>neu</i>	1	67.80	\$ 67.80 —
9	Headlamp LH <i>cm</i>	1	2,425.30	\$ 2,425.30 —
10	Headlamp ballast LH <i>17</i>	1	846.70	\$ 846.70 X
11	Headlamp lower bracket LH	1	218.95	\$ 218.95 ?
12	Headlamp bulb LH	1	372.20	\$ 372.20 ?
13	Headlamp washer cover <i>17</i>	1	41.10	\$ 41.10 —
14	Headlamp washer nozzle jet assy	1	152.10	\$ 152.10 ?
15	Front fender cowling LH <i>to-in</i>	1	118.40	\$ 118.40 —
16	Bonnet lock <i>17</i>	1	171.60	\$ 171.60 X
				\$ 6,586.45

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

Balance b/f \$ 6,586.45

Labour Charges :-

Amounts

Cut out, renew, knocking & welding, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body

\$ 1,280.00

500

Tuff-kote on damage parts

11 \$ 40.00

x

Spray painting on damage parts

\$ 1,080.00

600

Check lighting after repairs

\$ 60.00

30

Labour Charge

\$ 2,460.00

Total Amount

\$ 9,046.45

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0681C
Vehicle Details	
Vehicle No.:	SKB6880X
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	B.M.W.
Vehicle Model:	Z4 SDRIVE 23i 2.5L AT D/AB 2WD HID NAV
Primary Colour:	Yellow
Manufacturing Year:	2011
Engine No.:	10767785N52B25AF
Chassis No.:	WBALM32090E494505
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$47,209.00
Original Registration Date:	22 Jun 2011
First Registration Date:	22 Jun 2011
Transfer Count:	2
Actual ARF Paid:	\$47,209.00 23604
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2021
PARF Rebate Amount:	\$30,685.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$56,300.00
COE Rebate Amount:	\$18,969.00
Total Rebate Amount:	\$49,654.00

The information contained herein is correct as at 08 Feb 2018

OK



UP TO
64% OFF*
CAR INSURANCE

Starting from
\$411.69*
Receive \$50
CapitaVouchers*

BUY NOW

T&Cs apply.

income

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2011 Audi A5 @ \$75,800.



Extended Warranty From QRC
Lowest Depreciation Free 10
Full Servicing
Starlet

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [VIEW OUR CARS](#)

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

bmw z4

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw z4	Any	Any	2011	Any	Any	Any	Available
	BMW Z4 sDrive23i	\$79,898	\$17,500 /yr	06-May-2011	2,497 cc	79,500 km	Sports	Available
Well Maintained, Spacious 2 Seater Hard Top Convertible. Cheapest Depreciation In The Market. Black On Blue Exterior. Low Depreciation Compared To Other Models! High And Flexible Loan Available! High ...								
Tay Motor & Credit Pte Ltd								
Posted: 29-Jan-2018 Topic: 2011 BMW Z4, BMW Z4, BMW Z4, BMW Z4, Used BMW								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads								
20 results/page								

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, ask up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw z4, bmw z4 Singapore, used bmw z4 Singapore, used bmw z4, used vehicles Singapore or even buy used bmw z4 Singapore. We have now car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

LKK - Marcus

SM/SKB6880X/1802033

13th February 2018

WITHOUT PREJUDICE



The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

RE: ACCIDENT INVOLVING VEHICLES SKB 6880 X AND SLJ 8792 A ON 01ST FEBRUARY 2018 AT 0945 HRS AT 37A CAMBRIDGE ROAD MULTI STOREY CARPARK

Dear Sirs,

We refer to the above matter.

Our Client Tan Zhen Yi, Sheena the registered owner of SKB 6880 X.

You are the insurer of motor vehicle no. SLJ 8792 A, which was involved in the above accident. Please be informed that the collision was caused by the negligent owner/driver of the motor vehicle no. SLJ 8792 A, in consequence of which our client has suffered damages and consequential loss.

Attached a few documents for your reference:

- a) Repair bill
- b) GIA report & Police report
- c) An authorisation letter from the owner (SKB 6880 X)

We are claiming as follows: -

Repair bill	SS 5,877.48
Loss of use	SS 400.00

SS 6,277.48

Dollar: Six Thousand Two Hundred Seventy Seven And Cents Forty Eight Only.

Kindly let us know whether you are prepare to settle the claim within the next ten (10) days from the date herewith.

Please remit the cheque in favour to "Specialists Motor Pte Ltd" as soon as possible.

Thank you,

Yours faithfully,


Karen Ong

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 6 February, 2018 2:47 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLJ 8792A & SKB 6880X ON 01/02/2018

Our Ref: CC6/LCR18002203/wb3

06 February 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 8792A & SKB 6880X ON 01/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ACCIDENT INVOLVING VEHICLE

SKB 6880X and SLJ8792A on 31st Jan 2018
at 37A Cambridge Road multi-story carpark

Letter Of Authority And Undertaking

I/We Tan Zhen Yi, Sheena (NRIC NO) 58830681C of
81K37 Cambridge Road #19-149 Singapore 210037

the owner/driver of Vehicle No. SKB 6880X hereby authorise your
esteem company specialists motor pte ltd


as my repairer for my Damaged Vehicle involved in the above accident and to
claim against the negligent party and/or insurance company.

I/We hereby agreed to be bound by the following:-

1. You are authorised to use my/our name to claim against the negligent party and/or insurance company pertaining to the above accident including any other incidental losses. All payments/settlement monies shall be made in favour of your company M/S specialists motor pte ltd
2. All documents receive by me from third party or insurance company will be sent to your office for follow-up action.
3. Any offer of settlements by the insurer and/or negligent party will be accepted only with your concurrence and approval.
4. Throughout the process of claim, I/We will be obligated to assist and to provide your company with accurate and correct information.
5. I/We agree that I/We shall pay to your company all cost/expenses/damages incurred or suffered by you as a result of the unsuccessful recovery of the claims for the full repair cost and any other incidental cost/expenses by you on my/our behalf.
6. I/We warrant and undertake that all information and statement provided by me/us to you are true and accurate.

Thanking you in anticipation.

Yours faithfully



Date: 02.02.2018

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Specialists Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 5877.98 (Repair Cost), S\$ 400.00 (Loss of rental/use), S\$ NIL (Disbursement), for vehicle no. SKB 68802 that was damaged pursuant to the accident which occurred on 31/01/18 (date) along CP of Pixel Building (location) involving vehicle no/s SLJ 8792A. This is pursuant to the inspection conducted on 8/2/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tan Zhen Yi Sheena ("the third party claimant") of vehicle no. SKB 68802 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKB 68802 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of 03 (month) 2018 (year)

(Signature)


Signed by appointed surveyor


(Signature)

Signed by "the workshop" (with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2018 Edit Reg		08 Feb 2018 00:00 Edit Adj Rpt	S\$5,492.97 Edit Estimates	S\$5,492.97 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		LCRF Pte Ltd, Co. Reg. No.: NA							
Main Claimant:		TAN ZHEN YI SHEENA, ID: S8830681C							
Vehicle Reg. No.:		SKB6880X	Date of Loss:	31/01/2018 12:00 - :59					
Claim Type:		TP / 8646448210SG	Policy/Cover Note No.:	999995006 (Comprehensive)					
Vehicle Reg. No. (Insured):		SLJ8792A	Policy No. (Claimant):	MT20173117					
		Excess:							
Repairer:		Specialists Motor Pte Ltd (HQ) Bldg 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]							
Claimant's Insurer:		Great American Insurance Company (HQ) - Tel: 6804 6047							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/02/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (06/02/2018): Conflicting DOA 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB6880X (8646448210SG)
[SLJ8792A]
TP
TAN ZHEN YI SHEENA
Jan 31 2018 12:10PM
[LCRF Pte Ltd]
Specialists Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	08/02/18 16:19	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
2	08/02/18 16:19	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
3	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>

33	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	08/02/18 16:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	09/02/18 20:25	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 14:34	TP GIA REPORT	1	Load PDF	
2	09/02/18 11:37	TP ESTIMATE- MARKED	1	Load PDF	
3	23/03/18 10:08	WORKSHOP INVOICE	1	Load PDF	
4	23/03/18 10:08	AUTHORISATION TO ACT FORM	1	Load PDF	
5	23/03/18 10:08	Release Voucher	1	Load PDF	
6	23/03/18 10:08	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/02/18 09:24	OI GIA report	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ8792A (Insd veh)	Model:	BMW Z4 2.0 (A)
	SKB6880X (TP veh)		
Date of Accident:	31/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	9,874.17	
Final Repair Cost	: \$	5,877.48	
Loss of Use	: \$	400.00	4.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	6,277.48	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Specialists Motor Pte Ltd	: \$	6,277.48
2)		: \$	

JOANNE LEE KHANG MIN

23 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18002203/UWB3Q2

Date: 23/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

999995006

Claimant Vehicle No: SKB6880X

Insured Vehicle No:

SLJ8792A

Date of Loss: 31/01/2018

Nature of Claim:

TP

Claim No: 8646448210SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB6880X

Make & Model: BMW Z4, 2.0 (A)

Engine No: 10767785N52B25AF

Reg. Date: 22/06/2011 (Man. Year: 2011)

Chassis No: WBALM32090E494505

Colour: Yellow

Odometer: 85842 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18

Rear Tyre Size:

255/35ZR18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,768.20	4,362.97	2,405.23	35.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,130.00	1,330.00	54.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,228.20	5,492.97	3,735.23	40.48
+ GST 7.00/7.00% (S\$)	645.97	384.51	261.46	40.48
Nett Amount (S\$)	9,874.17	5,877.48	3,996.69	40.48
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		6,277.48		

INSPECTION

Date of Assignment: 08/02/2018

Date Inspected: 08/02/2018 Inspected At:

Specialists Motor Pte Ltd (HQ)

Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Deformed / Torn	1,054.85 F	*1,054.85 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE RETAINER L&RH	N/S Cracked	91.40 F	*45.70 FL
4	1		*FRONT BUMPER SENSOR LH	Shorted	236.85 F	*236.85 FL
5	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	626.35 F	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	57.55 F	*- FL
7	1		*FRONT BUMPER LOWER GARNISH LH	Not Necessary	55.50 F	*- FL
8	1		*FRONT BUMPER EMBLEM	Necessary	67.80 F	*67.80 FL
9	1		*HEADLAMP LH	Cracked	2,425.30 F	*2,425.30 FL
10	1		*HEADLAMP BALLAST LH	Not Necessary	846.70 F	*- FL
11	1		*HEADLAMP LOWER BRACKET LH	Necessary	218.95 F	*218.95 FL
12	1		*HEADLAMP BULB LH	Not Necessary	372.20 F	*- FL
13	1		*HEADLAMP WASHER COVER	Twisted	41.10 F	*41.10 FL
14	1		*HEADLAMP WASHER NOZZLE JET ASSY	Necessary	152.10 F	*152.10 FL
15	1		*FRONT FENDER COWLING LH	Torn	118.40 F	*118.40 FL
16	1		*BONNET LOCK	Not Necessary	171.60 F	*- FL
17	1		*SENSOR WIRE	Torn	181.75 F	*181.75 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,768.20	4,592.60
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	229.63
Total Parts (\$\$)	6,768.20	4,362.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT ,RENEW ,KNOCKING & WELDING ,FRONT BONNET ,FRONT SUPPORT PANEL,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	1,280.00	500.00
2	TUFF-KOTE ON DAMAGE PARTS	New	40.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,080.00	600.00
4	CHECK LIGHTING AFTER REPAIRS	New	60.00	30.00
Gross Labour Cost (\$\$)			2,460.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >