

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

*not about
the photo showing
4 Lg.
8/2/18*

Date of Accident : 01st February 2018
Location : 37A Cambridge Rd Multi Storey Car Park
Third Party Claim Vehicle No : SLJ 8792 A
Repair Cost For Vehicle No : SKB 6880 X (BMW Z4)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>De/To. in</i>	1	1,054.65	\$ 1,054.65 —
2	Front bumper clips <i>ren</i>	1 set	50.00	\$ 50.00 —
3	Front bumper side retainer L&RH <i>mlsine</i>	2	45.70	\$ 91.40 <i>WC</i>
4	Front bumper sensor LH <i>shub</i>	1	236.85	\$ 236.85 ✓
5	Front bumper reinforcement beam <i>17</i>	1	626.35	\$ 626.35 X
6	Front bumper sponge	1	57.55	\$ 57.55 ?
7	Front bumper lower garnish LH	1	55.50	\$ 55.50 ?
8	Front bumper emblem <i>ren</i>	1	67.80	\$ 67.80 —
9	Headlamp LH <i>cm</i>	1	2,425.30	\$ 2,425.30 —
10	Headlamp ballast LH <i>17</i>	1	846.70	\$ 846.70 X
11	Headlamp lower bracket LH	1	218.95	\$ 218.95 ?
12	Headlamp bulb LH	1	372.20	\$ 372.20 ?
13	Headlamp washer cover <i>tm</i>	1	41.10	\$ 41.10 —
14	Headlamp washer nozzle jet assy	1	152.10	\$ 152.10 ?
15	Front fender cowling LH <i>To. in</i>	1	118.40	\$ 118.40 —
16	Bonnet lock <i>17</i>	1	171.60	\$ 171.60 X
				\$ 6,586.45

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKB6880X/1801033

03rd February 2018

Balance b/f \$ 6,586.45

Labour Charges :-

Amounts

Cut out, renew, knocking & welding, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body

\$ 1,280.00

500

Tuff-kote on damage parts

11 \$ 40.00

2

Spray painting on damage parts

\$ 1,080.00

600

Check lighting after repairs

\$ 60.00

30

Labour Charge

\$ 2,460.00

Total Amount

\$ 9,046.45

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: