

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 346S

DATE 1/2/2018 16:43

MAKE :

MODEL : HYUNDAI i40

AIG/LKK

FRONT RIGHT

L/Sump

FZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (RH)			\$ 1,388.00
	Front Fender (RH)			\$ 619.00
	Front Fender Shield (RH) ?			\$ 169.80
	Front Fender Retainer ✓			\$ 9.20
	Front fog lamp cover (RH) ✓			
	SUB TOTAL			\$ 3,847.40
	LESS 20%			\$ 769.48
	DISCOUNTED TOTAL			\$ 3,077.92
	Labour Charge			\$ 400
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	R/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,210.00
	ESTIMATE TOTAL			\$ 4,287.92

Kali LKK

2/2/18 1040 hrs
2071L/S
After Repair

LKK A: ... notify

the Re ... of

- To res ...
- To dis ...
- Parts prices ...
- Third party ...
- No ill ...
- Supp ...
- is sub ...

Acknowledged ...

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.