

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1010D

DATE 2/2/2018 10:20

Jumani

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✕			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✕			\$ 43.60
	Boot Lid Hyundai Plate ✕			\$ 24.20
	Boot Lid 'H' Emblem ✕			\$ 26.10
	Boot Lid CRDI Plate ✕			\$ 22.70
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕		\$ 38.00	\$ 76.00
	Rear Panel ✕			\$ 391.80
	Rear Panel Garnish ✕			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker ✕			\$ 30.00
	Rear Bumper Reverse Sensor =			\$ 135.70
	Rear Bumper Rubber Mat =			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) -		\$ 100.00	\$ 200.00
				\$ 415.70
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,470.00
	ESTIMATE TOTAL			\$ 4,853.62

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.