

**COMFORT DELGRO
ENGINEERING**

45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : **SGV156K**
 Make & Model : **TOYOTA / CAMRY 2.0 A**
 Year of Manufacture : **2007**
 Chassis No. : **MR053BK4107008409**
 Engine No. : **1AZE029178**
 Policy No. :
 Time of Accident : **15.20 P.M**

Ins Company : **AXA INS**
 Excess :
 Date of Accident : **10.01.2018**
 Suggested Days of Repair : **6 DAY**

In-house Vehicle Assessor

Name : **Wong Chee Wei**
 Signature :
 Contact No : **68676919**
 HP : **97239882**

Repair Estimates

Parts (a) Cost / List Price Items **\$1,205.00**
 Plus/Less 15 % **\$180.75**
 (b) Nett Price Items
 Less %
 (c) Special Nett Items **\$260.00**
Total Parts Cost (Appendix A) **\$1,645.75**
Labour (Appendix B) **\$1,910.00**
Total Repair Cost **\$3,555.75**

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : **Tan Jiah** **97495749**
 Company : **LKK**
 Survey conducted on : **7/2/18** at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice. **WP**
 (b) Recommended Days of Repair : **02** day(s) **Lumpsum**
 (c) Resurvey : **Required / Not Required** **Resurvey After repair**
 (d) Excess : \$
 (e) Signature of surveyor : **Tan Jiah** Date: **7/2/18 @ 12pm**

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare PartsVehicle No. : **SGV156K**Submit By : **Wong Chee Wei**Make & Model : **TOYOTA CAMRY 2.0 A**Year Manufacture : **2007**Chassis No. : **MR053BK4107008409**Engine No. : **1AZE029178****TP****S/Order**

S/No	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
1	REAR BUMPER	1 PC	\$280.00				del
2	REAR BUMPER CLIP	10 PC	\$25.00				del
3	REAR BUMPER SIDE RETAINER RH	1 PC	\$30.00				?
4	REAR BUMPER SIDE RETAINER LH	1 PC	\$30.00				?
5	REAR BUMPER BRACKET RH	1 PC	\$35.00				x
6	REAR BUMPER BRACKET LH	1 PC	\$35.00				x
7	REAR BUMPER REINFORCEMENT	1 PC	\$180.00				?
8	REAR BUMPER SPONGE	1 PC					?
9	REAR END PANEL	1 PC	\$250.00				RY
10	REAR END PANEL GARNISH	1 PC	\$180.00				x
11	REVERSE SENSOR SET	1 SET				\$200.00	?
12	FENDER LINER RHR	1	\$150.00				x
13	FENDER LINER CLIP	5	\$10.00				x
14	SEALANT - BODY	1				\$60.00	x
15		1					
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)

Appendix B

Vehicle No. : **SGV156K**

Submit By : : Wong Chee Wei

Make & Model : TOYOTA

Year of Manufacture : 2007

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.