

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002391

Date : 05/02/2018

Vehicle Num. : GW5253A

Make/Model : NISSAN URVAN-2003

Chassis/Eng# : JN1MG4E25Z0710216/ZD30030216

Accident Date : 31/01/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BONNET		2,101.40 BT
2.	1	REAR BONNET LOCK		323.60 JAM
3.	1	REAR BONNET HANDLE OUTER		195.80 CR
4.	1	REAR DOOR WEATHERSTRIP		345.20 RE
5.	1	REAR BUMPER		683.60 DE
6.	2	BUMPER SIDE BRACKET	76.40	152.80 RE
7.	1	REAR END PANEL		347.60 BT
8.	1	REAR END PANEL INNER		395.10 BT
9.	1	STEP PANEL		325.50 BT
10.	2	REAR LAMP	233.50 CR	467.00 RH-X
11.	1	SIDE PANEL, LHS		2,011.10 RE
12.	1	REAR LAMP PANEL		395.20 BT
13.	1	FRONT BUMPER		784.10 DE
14.	1	FRONT GRILLE		458.20 CR
15.	2	BUMPER SPOTLAMP, GARNISH	115.20	230.40 SC
16.	2	BUMPER SIDE BRACKET	95.20	190.40 X
17.	1	FRONT CROSSMEMBER		495.20 ?
18.	2	HEADLAMP	521.70 CH	1,043.40 REAR
19.	2	SIDE LAMP	185.20 CH	370.40 RH
20.	1	CORNER PANEL, LHS		495.20 X
21.	1	EXHAUST REAR PIPE		562.10 BT
22.	1	NISSAN LOGO		115.20 RE
List Total S\$:				12,488.50
25.00% Discount S\$:				3,122.13
				9,366.37

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002391

Date : 05/02/2018

Vehicle Num. : GW5253A

Make/Model : NISSAN URVAN-2003

Chassis/Eng# : JN1MG4E25Z0710216/ZD30030216

Accident Date : 31/01/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|--|--|--|
| 1. | 1 | NETT ITEMS : | | |
| 2. | 1 | REVERSE SENSOR | | |
| 3. | 1 | REAR WINDSCREEN SEALANT | | |
| 4. | 1 | 70 KM/H SIGN | | |
| 5. | 1 | NUMBER PLATE | | |
| 6. | 1 | REAR BONNET ALUMINIUM PARTITION, INNER | | |

Nett Total S\$:

10.00% Discount S\$:

LABOUR :

TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS

TO PANEL BEAT/REPAIR FR/RR BODY

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY NEW LOGO

LOSS OF USE : 12 DAYS @ \$ 120/DAY

Labour Total S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SIN SHENG ENGINEERING SERVICES

Total S\$: 13,198.37

=====

Ram

Hp 20010068

10 days

4/5

06/02/18 @ 1120

Resy after

resurvey

250.00 2200

40.00

20.00

20.00

350.00

680.00

68.00

612.00

120.00

1,700.00 1200

950.00 800

450.00 300

3,220.00