

INS. CASE OWNER:

TEVachal

CC 4 / ASM1800

2217

A was

LKK:

IDAC:

29349

Surveyor:

ump

DOI:

ASSIGNMENT

16/6/18

Date / Time:

5/2/18

Registered in Merimer:

Pre-assign / CCU / FTE

SLE 68246



Insured Vehicle No.:

Name of Insured:

Ong Chin Hin

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

31118

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Un pinh

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8m088R

Policy No.:

VPA/P1946789

Make / Model:

BMW 730

Place of Accident:

Gaylang Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLE 83115



INSRS:

WSP:

Tel:

Liability:

RMKS:

Borneo Motors



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/2 12:45
6/2

SLE 83115 X:

SLE 68246 X

Pending verification for O/S. Please check O/S DL

7/2/18

Called O/S, No response

4:45pm

Spoke to O/S (Mr. Lim) - confirmed accident details and O/S car - ended TP. O/S will send original photo via email. Informed abt TP email, aware of WCD rules and agreed to settle. Send letter to O/S.

RECEIVED 26 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List/ Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Angela.

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4449.07

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

300.00 (\$ 60 x 5 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 4751.07

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4751.07

Name 1:

Borneo Motors (Singapore) Pte Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



Vivian

Borneo Motors (Singapore) Pte Ltd

Page 2 of 2

Reg No : 196700086Z
T Reg No : MR-8500000-9Online Service Booking :
www.toyotasingapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631-1188

TAX INVOICE


Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept	S1000001/ICASA1	Mr Lee Kian Ming 50 Lorong 40 Geylang #03-14 Singapore 398074 Mobile: 97531070
	Document No 39006754	
	Document Date 13/06/2018	

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
GEXGKZ S3	ZRE171R	27/05/2016	SLC8311S	19077	15980	7DS/SLC8311S/31011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
053REH104549023	1ZRY278260	60	Sam San Joi	01/02/2018 15.11	19/04/2018	8.09

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
2	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLE6824G ACC DATE:31/01/2018 DRIVE IN:01/02/2018 DATE-IN:16/04/2018 DATE SURVEY:16/04/2018 NO OF REPAIR DAYS:5 DAYS BY:ADRIAN (LKK)				30.00
2 S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR A45				154.00
3 S	BP-SUBLET CHECK WIRING & CONDUCT WATER LEAK TEST A45				154.00
4 S	BP-SUBLET REMOVE & INSTALL BOORLID CARPET, GARNISH A45 AND TRIMMI TO ASSIST REPAIR				308.00
5 S	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER REINFORC A45 EMENT, ETCSTRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1540.00
6 S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR A45 EAS				1012.00
7 1	S52159-02904 COVER, RR BUMPER	1.00	539.90	15.00	458.91
8 2	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30	15.00	49.55
9 3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	89.84
0 4	S52023-02190 REINFORCEMENT, RR	1.00	386.60	15.00	328.61
1 5	S52161-0K040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	4,158.01
		Labour 960.01	GST 7.00% 291.06
		Materials 30.00	Less 0.00
		Lubrication/Fluid 3,168.00	
		Others 0.00	
		0.00	Amount Due 4,449.07

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

3691600

SECURITY GUARD

3691600

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 13/06/2018
TIME 11:16

VEHICLE NO SLC8311S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M0088R

Our ref: CC4/ASM18002217/Awa3

Date: 17.04.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLC 8311S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.04.2018 at the premises of M/s Borneo Motors (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,646.10
Revised Estimate Amount	: S\$	3,829.40
"Check" Items Amount	: S\$	776.09
Total (Including Check Items)	: S\$	4,605.49
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4~5 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE 6824G (Insd veh)	Model:	TOYOTA
	SLC 8311S (TP veh)		COROLLA ALTIS 1.6 CVT
Date of Accident:	31/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,321.33
Final Repair Cost	:	\$	4,449.07
Loss of Use	:	\$	300.00
			5 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 4,751.07

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	BORNEO MOTORS (SINGAPORE) PTE LTD	:	\$ 4,751.07

NUR SHAQILAH BTE ABDOL
WAHAB

11/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18002217/Awa3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: RICHARD ANG

Date : 11-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 6824G	Veh. Inspected	SLC 8311S
Policy No.	VPA/P1946789	Coverage (\$)	0.00
Claim No.	S8M0088R	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104549023	Colour	WHITE
Odometer	18721	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45R17	MICHELIN	6 mm
L/H Front Tyre	215/45R17	MICHELIN	6 mm
R/H Rear Tyre	215/45R17	MICHELIN	6 mm
L/H Rear Tyre	215/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2018	Inspection Date	16/04/2018
Survey held at	15 UBI RD 4		
Repairer	BORNEO MOTORS (S) PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8311S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER (SN) (CONSISTENT)	DEFORMED	458.91	458.91
1	RETAINER, RR BUMPER L (SN) (CONSISTENT)	NECESSARY	49.55	49.55
1	RETAINER, RR BUMPER L (SN) (CONSISTENT)	NECESSARY	89.84	89.84
1	RETAINER, RR BUMPER R (SN) (CONSISTENT)	NOT NECESSARY	49.55	-
1	RETAINER, RR BUMPER R (SN) (CONSISTENT)	NOT NECESSARY	89.84	-
1	REINFORCEMENT, RR (SN) (CONSISTENT)	BENT	328.61	328.61
1	ARM, RR BUMPER, OUTE (SN) (CONSISTENT)	NOT NECESSARY	56.27	-
1	ARM, RR BUMPER, OUTE (SN) (CONSISTENT)	NOT NECESSARY	56.27	-
10	CLIPS (SN) (CONSISTENT)	NECESSARY	33.10	33.10
1	PANEL, LAMP LOWER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	551.82	-
1	PLATE, RR FLOOR (SN) (CONSISTENT)	NOT NECESSARY	199.15	-
1	PANEL, LUGGAGE DOOR (SN) (CONSISTENT)	NOT NECESSARY	603.58	-
1	WEATHERSTRIP, LUGGAGE (SN) (CONSISTENT)	NOT NECESSARY	144.67	-
1	LOCK ASSY, LUGGAGE C (SN) (CONSISTENT)	NOT NECESSARY	328.61	-
1	STRIKER, LUGGAGE COM (SN) (CONSISTENT)	NOT NECESSARY	12.58	-
1	LUGGAGE COMP EMBLEM (SN) (CONSISTENT)	NOT NECESSARY	50.74	-
1	EMBLEM, SYMBOL (SN) (CONSISTENT)	NOT NECESSARY	33.74	-
1	EMBLEM, SYMBOL (SN) (CONSISTENT)	NOT NECESSARY	37.48	-
1	BACK SENSOR 070, 310A (SN) (CONSISTENT)	NOT NECESSARY	135.79	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SEALANT - REAR END PANEL (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			3,420.10	990.01
LABOUR				
DRILL HOLE & INSTALL REVERSE SENSOR.			154.00	154.00
CHECK WIRING & CONDUCT WATER LEAK TEST.			154.00	154.00
REMOVE & INSTALL BOOTLID CARPET, GARNISH AND TRIMMI TO ASSIST REPAIR.			308.00	308.00
REPLACE REAR BUMPER, REAR BUMPER REINFORCEMENT, STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL, LAMP LOWER.			3,080.00	1,540.00

Report Ref No. CC4/ASM18002217/Awa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS.		2,530.00	1,012.00
			6,226.00	3,168.00
GRAND TOTAL			9,646.10	4,158.01
RECOMMENDED COST OF REPAIRS				4,158.01

Report Ref No. CC4/ASM18002217/Awa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.