



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking : www.toyotasingapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631-1188

Account Detail		Account No	Customer Detail
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept		S1000001 / ICASA1	Mr Lee Kian Ming 50 Lorong 40 Geylang #03-14 Singapore 398074 Mobile: 97531070
		Document No	
		Document Date	
		0	
		02/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	27/05/2016	SLC8311S	14966	15980	7DS/SLC8311S/31011
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104549023	12RY278260	60	Sam San Joi	01/02/2018 15.11	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES ^{acc} TP-DIRECT SETTLEMENT TP-SLE6824G ACC DATE:31/01/2018 DRIVE IN:01/02/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				✓ 154.00
3	S	BP-SUBLET CHECK WIRING & CONDUCT WATER LEAK TEST				✓ 154.00
4	S	BP-SUBLET SEALANT - REAR END PANEL				na x 80.00
5	S	BP-SUBLET REMOVE & INSTALL BOORLID CARPET, GARNISH AND TRIMMI TO ASSIST REPAIR				✓ 308.00
6	S	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER REINFORC EMENT, ETCSTRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1540 3080.00
7	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				1012 2530.00
8	1	S52159-02904 COVER, RR BUMPER ^{Deformed.}	1.00	✓ 539.90	15.00	✓ 458.91
9	2	S52563-02250 RETAINER, RR BUMPER L ^{2 done}	1.00	58.30	15.00	✓ 49.55
10	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	✓ 89.84
11	4	S52562-02250 RETAINER, RR BUMPER R ^{acc}	1.00	58.30	15.00	✓ 49.55

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Amount Due
		Labour Materials Lubrication/Fluid Others	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 02/02/2018
08:20

VEHICLE NO

SLC8311S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Acknowledged by Repairer

Signature:

Date:

3607096

3607096



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept	S1000001 / ICASA1 Document No 0 Document Date 02/02/2018	Mr Lee Kian Ming 50 Lorong 40 Geylang #03-14 Singapore 398074 Mobile: 97531070

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	27/05/2016	SLC8311S	14966	15980 :7DS/SLC8311S/31011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104549023	12RY278260	60	Sam San Joi	01/02/2018 15.11	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	5	S52575-02140 RETAINER, RR BUMPER R <i>Not New</i>	1.00	105.70	15.00	* 89.84
13	6	S52023-02190 REINFORCEMENT, RR <i>Not New</i>	1.00	386.60	15.00	? 328.61
14	7	S52182-02160 ARM, RR BUMPER, OUTE <i>Not New</i>	1.00	66.20	15.00	? 56.27
15	8	S52181-02190 ARM, RR BUMPER, OUTE <i>Not New</i>	1.00	66.20	15.00	? 56.27
16	9	S52161-0K040 CLIPS <i>Not New</i>	10.00	3.90	15.00	✓ 33.10
17	0	S58307-02380 PANEL, LAMP LOWER <i>Not New</i>	1.00	649.20	15.00	* 551.82
18	1	S58387-02240 PLATE, RR FLOOR <i>Not New</i>	1.00	234.30	15.00	? 199.15
19	2	S64401-02B71 PANEL, LUGGAGE DOOR <i>Not New</i>	1.00	710.10	15.00	* 603.58
20	3	S64461-02220 WEATHERSTRIP, LUGGAG <i>Not New</i>	1.00	170.20	15.00	* 144.67
21	4	S64600-02080 LOCK ASSY, LUGGAGE C <i>Not New</i>	1.00	386.60	15.00	* 328.61
22	5	S64621-06080 STRIKER, LUGGAGE COM <i>Not New</i>	1.00	14.80	15.00	* 12.58
23	6	S75431-02090 LUGGAGE COMP EMBLEM, <i>Not New</i>	1.00	59.70	15.00	* 50.74
24	7	S75442-02330 EMBLEM, SYMBOL <i>Not New</i>	1.00	39.70	15.00	* 33.74
25	8	S75442-02340 EMBLEM, SYMBOL <i>Not New</i>	1.00	44.10	15.00	* 37.48
26	9	SPZ061-12021 16 BACK SENSOR 070, 310A <i>Not New</i>	1.00	? 159.75	15.00	? 135.79

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,310.10	9,646.10
		Labour 30.00	GST 7.00%
		Materials 6,306.00	675.23
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 10,321.33

PLEASE TEAR ALONG PERFORATED LINE

3607097

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLC8311S

CUSTOMER

DATE 02/02/2018
TIME 08:20

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Adrian Lim
16/04/18 04-05 yrs.

3607097



Borneo Motors