



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept	S1000001 / ICASA1	Mr Lee Kian Ming 50 Lorong 40 Geylang #03-14 Singapore 398074 Mobile: 97531070
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
------	------	-------	----------	------------	------------	--------	------------------

16	GEXGKZ S3	ZRE171R	27/05/2016	SLC8311S	14966	15980	7DS/SLC8311S/310111
----	-----------	---------	------------	----------	-------	-------	---------------------

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
------------	-----------	--------	-------	------------------	------------	--------------

MR053REH104549023	1ZRY278260	60	Sam San Joi	01/02/2018 15.11	--/--/----	0.00
-------------------	------------	----	-------------	------------------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES ^{new} TP-DIRECT SETTLEMENT TP-SLE6824G ACC DATE:31/01/2018 DRIVE IN:01/02/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				✓ 154.00
3	S	BP-SUBLET CHECK WIRING & CONDUCT WATER LEAK TEST				✓ 154.00
4	S	BP-SUBLET SEALANT - REAR END PANEL				✓ 80.00
5	S	BP-SUBLET REMOVE & INSTALL BOORLID CARPET, GARNISH AND TRIMMI TO ASSIST REPAIR				✓ 308.00
6	S	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER REINFORC EMENT, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1540 3080.00
7	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				1012 2530.00
8	1	S52159-0Z904 COVER, RR BUMPER ^{Deformed.}	1.00	✓ 539.90	15.00	✓ 458.91
9	2	S52563-02250 RETAINER, RR BUMPER L ^{2 doors}	1.00	58.30	15.00	✓ 49.55
10	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	✓ 89.84
11	4	S52562-02250 RETAINER, RR BUMPER R ^{new new}	1.00	58.30	15.00	✓ 49.55

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607096

TO SECURITY GUARD

3607096

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 02/02/2018
TIME 08:20

VEHICLE NO

SLC8311S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept	S1000001 / ICASA1	Mr Lee Kian Ming 50 Lorong 40 Geylang #03-14 Singapore 398074 Mobile: 97531070
	Document No	
	Document Date	
	0	
	02/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	27/05/2016	SLC8311S	14966	15980 :7DS/SLC8311S/31011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104549023	12RY278260	60	Sam San Joi	01/02/2018	15.11	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	5	S52575-02140 RETAINER, RR BUMPER R <i>Not New</i>	1.00	105.70	15.00	* 89.84
13	6	S52023-02190 REINFORCEMENT, RR ?	1.00	386.60	15.00	? 328.61
14	7	S52182-02160 ARM, RR BUMPER, OUTE ?	1.00	66.20	15.00	? 56.27
15	8	S52181-02190 ARM, RR BUMPER, OUTE ?	1.00	66.20	15.00	? 56.27
16	9	S52161-0K040 CLIPS <i>Not New</i>	10.00	3.90	15.00	✓ 33.10
17	0	S58307-02380 PANEL, LAMP LOWER <i>Not New</i>	1.00	649.20	15.00	* 551.82
18	1	S58387-02240 PLATE, RR FLOOR ?	1.00	234.30	15.00	? 199.15
19	2	S64401-02B71 PANEL, LUGGAGE DOOR <i>Not New</i>	1.00	710.10	15.00	* 603.58
20	3	S64461-02220 WEATHERSTRIP, LUGGAGE <i>Not New</i>	1.00	170.20	15.00	* 144.67
21	4	S64600-02080 LOCK ASSY, LUGGAGE C <i>Not New</i>	1.00	386.60	15.00	* 328.61
22	5	S64621-06080 STRIKER, LUGGAGE COM <i>Not New</i>	1.00	14.80	15.00	* 12.58
23	6	S75431-02090 LUGGAGE COMP EMBLEM, ? <i>Not New</i>	1.00	59.70	15.00	* 50.74
24	7	S75442-02330 EMBLEM, SYMBOL	1.00	39.70	15.00	* 33.74
25	8	S75442-02340 EMBLEM, SYMBOL	1.00	44.10	15.00	* 37.48
26	9	SPZ061-12021 16 BACK SENSOR 070, 310A ?	1.00	159.75	15.00	? 135.79

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	9,646.10
		Labour	3,310.10
		Materials	30.00
		Lubrication/Fluid	6,306.00
		Others	0.00
			0.00
			GST 7.00%
			Less
			Amount Due
			10,321.33

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 02/02/2018
TIME 08:20*Adrian Lim*
16/04/18 04-05 yrs.

VEHICLE NO SLC8311S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**