



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : **ODWR**Vehicle No. : **SFS3999C**Make & Model : **B.M.W. Z4 SDRIVE 23I**Year of Manufacture : **2009**Chassis No. : **WBALM32020E155228**Ins Company : **AXA**

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : **31/01/2018**Time of Accident : **17:00**

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : **Andrew**

Signature : _____

Parts (a) Cost / List Price Items \$ **225.00**Plus/Less 0% \$ **-**Total of Cost / List \$ **225.00**(b) Nett Price Items \$ **-**

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ **-**Total Parts Cost (Appendix A) \$ **225.00**Labour (Appendix B) \$ **2,150.00**Total Repair Cost \$ **2,375.00**

Contact No

Frt Counter Operation

63837466 - Patrick Tia

63837730 - Brenda Ng

63837890 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : **Kennerh**Company : **CKK**Survey conducted on : **5/2/18** at **1.30pm**Remarks By Surveyor(a) The repair of this vehicle is authorized / ☒ is not authorized until further notice.(b) Recommended Days of Repair : **05** day(s)(c) Resurvey : Required / ☒ Not Required(d) Excess : \$ **NIL**(e) Signature of surveyor : **Le** Date: **5/2/18**

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SFS3999C Case Owner : Andrew

Make & Model : B.M.W. Z4 SDRIVE 23I Year Manufacture : 2009

Chassis No : WBALM32020E155228 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : ODWR

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper side retainer RH <i>DIT</i>	1	\$ 35.00				<i>✓</i>
2	RH front fender emblem logo <i>M</i>	1	\$ 50.00				<i>✓</i>
3	RH front fender emblem S DRIVE 23i <i>M</i>	1	\$ 100.00				<i>✓</i>
4	RH front fender signal lamp <i>Sm</i>	1	\$ 40.00				<i>X</i>
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Year of Manufacture : 2009

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.