

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2251T

DATE 5/2/2018 11:22

MAKE :

MODEL : HYUNDAI i40

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 562.30
	Front Bumper Bracket Top (RH) /			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (RH) /			\$ 1,388.00
	Front Fender (RH) /			\$ 619.00
	Front Fender Shield (RH) X			\$ 169.80
	Front Fender Retainer X			\$ 9.20
	Front Wheel Hub Cap /			\$ 150.70
	SUB TOTAL			\$ 2,930.60
	LESS 20%			\$ 586.12
	DISCOUNTED TOTAL			\$ 2,344.48
	Front Fender Advertisement Logo (RH) /			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 ⁴⁰⁰
	Spray Painting Charge			\$ 400.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 50.00 ²⁰
	FRT Wheel Alignment			\$ 80.00 ^X
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 3,584.48

Kalok (CCK)
5/2/18 15:15 hrs
2 Days
PIP
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.