

LKK 9161 5379  
@ 11:00 a.m.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: [www.esteemperf.com.sg](http://www.esteemperf.com.sg)

### Repair Estimates

PC 3788 K

|                  |                             |    |          |
|------------------|-----------------------------|----|----------|
| Parts            | (a) Cost / List Price Items | \$ | 1,237.50 |
|                  | Plus/Less 25%               | \$ | 309.38   |
|                  | Total of Cost / List        | \$ | 928.13   |
|                  | (b) Nett Price Items        |    |          |
|                  | Less                        |    |          |
|                  | Total of Nett Item          |    |          |
|                  | (c) Special Nett Items      |    |          |
| Total Parts Cost |                             |    |          |
| Labour           |                             | \$ | 650.00   |
| Total            |                             | \$ | 1,578.13 |

Not Authorized  
Resurvey After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenner  
Company : LKK  
Survey conducted on : 20/2/18 at 11:00

#### Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **PC 3788 K**  
Make & Model : **TOYOTA HIACE**  
Chassis No : **JTFHT02P600157737**

Submit By : **Carmen Lim**  
Year Manufacture : **2014**  
Engine No. :  
**Cost / List**

| S/No. | Part Description              | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|-------------------------------|-----|------------|-------|-------------------------|
| 1     | Front bumper                  | 1   | \$468.20   |       | ✓                       |
| 2     | Front bumper clip             | 10  | \$48.00    |       | ✓                       |
| 3     | Front bumper side retainer RH | 1   | \$160.60   |       | X                       |
| 4     | Headlamp RH                   | 1   | \$560.70   |       | ✓                       |
| 5     |                               |     |            |       |                         |
| 6     |                               |     |            |       |                         |
| 7     |                               |     |            |       |                         |
| 8     |                               |     |            |       |                         |
| 9     |                               |     |            |       |                         |
| 10    |                               |     |            |       |                         |
| 11    |                               |     |            |       |                         |
| 12    |                               |     |            |       |                         |
| 13    |                               |     |            |       |                         |
| 14    |                               |     |            |       |                         |
| 15    |                               |     |            |       |                         |
| 16    |                               |     |            |       |                         |
| 17    |                               |     |            |       |                         |
| 18    |                               |     |            |       |                         |
| 19    |                               |     |            |       |                         |
| 20    |                               |     |            |       |                         |
| 21    |                               |     |            |       |                         |
| 22    |                               |     |            |       |                         |
| 23    |                               |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

