

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3374X

DATE 3/2/2018 10:10

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>x rep</i>			\$ 1,681.40
	Boot Lid Rubber <i>x</i>			\$ 115.80
	Boot Lid Lock Upper <i>x</i>			\$ 137.90
	Boot Lid Lock Lower <i>x</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>—</i>			\$ 27.20
	Boot Lid CRDI Plate <i>—</i>			\$ 41.00
	Boot Lid Lamp (LH) <i>x</i>			\$ 556.80
	Bootlid Moulding <i>—</i>			\$ 85.00
	Bootlid i40 Emblem <i>—</i>			\$ 41.00
	Bootlid Lower Garnish <i>—</i>			\$ 398.00
	Rear Bumper <i>—</i>			\$ 603.60
	Rear Bumper Reinforcement <i>—</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>LH RH?</i>	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket <i>?</i>			\$ 49.00
	Rear Bumper Clips <i>—</i>			\$ 22.00
	Rear Bumper Sponge <i>?</i>			\$ 143.40
	Rear Bumper Under Cover <i>—</i>			\$ 225.00
	Rear Bumper Reflector Lamp (LH) <i>—</i>			\$ 32.00
	Tail Lamp (LH) <i>?</i>			\$ 565.60
	Tail Lamp Quarter Panel (LH) <i>x rep</i>			\$ 97.90
	Rear Panel <i>x rep</i>			\$ 592.30
	Rear Panel Garnish <i>x</i>			\$ 57.70
	Rear Panel Lower Panel <i>x</i>			\$ 495.50
	Exhaust Pipe Insulator, LH <i>x</i>			\$ 58.55
	Exhaust Silencer, LH <i>—</i>			\$ 954.00
	Exhaust Pipe Hanger <i>x</i>			\$ 58.55
	Rear Fender (LH) <i>x rep</i>			\$ 2,020.10
	Rear Fender Inner Lining (LH) <i>x</i>			\$ 164.40
	Rear Fender Air-Duct <i>x</i>	\$	51.60	\$ 103.20
	Rear Windscreen Moulding <i>x</i>			\$ 60.00
SUB TOTAL				\$ 10,282.95
LESS 20%				\$ 2,056.59
DISCOUNTED TOTAL				\$ 8,226.36
	Boot Lid Comfort Logo & Tel No. Sticker <i>—</i>			\$ 30.00
	Boot Lid Advertisement Logo <i>—</i>			\$ 100.00
	Rear Bumper Reverse Sensor <i>—</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>—</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>—</i>	\$	100.00	\$ 200.00
	Rear Windscreen Sealant <i>x</i>			\$ 46.00
				\$ 561.70

Nett
Nett
Nett
Nett
Nett
Nett

SHB 3374X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 ⁶⁰⁰
	Spray Painting Charge			\$ 1,000.00 ⁷²⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 100.00 ²⁰
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ⁵⁰
	Remove/Refix Rear Windscreen Glass			\$ 120.00 ^X
	Remove/Refix Reverse Sensor			\$ 120.00 ²⁰
	Remove/Refix Exhaust Pipe			\$ 150.00 ⁵⁰
	TOTAL LABOUR			\$ 3,190.00
	ESTIMATE TOTAL			\$ 11,978.06
Kalac CKK 5/2/18 1845h 3 0-71 4/5 After Repair photo.				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				