

Rashid

CC 4/AIG1800

2232, A Ph

LKK
IDAC

Surveyor:

Adnan

DOI:

ASSIGNMENT

5/2/18

Date / Time:

5/2/18

Registered in Merimen:

5/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 30026

Name of Insured:

NEWSTEAD TECHNOLOGY PTE LTD

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

20/01/18

Claim No.:

535354939754

Policy No.:

200354270-03

Make / Model:

Toyota

Place of Accident:

N/A Lempang

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PUTRA AL-MATIN BIN SHAHEIN

Driver Tel No.:

(V/L YES / NO) N/A

OI GIA REPORT:

YES

NO:

TP GIA REPORT:

YES

NO

Insured Liability:

%

Final ? Yes / No

5/2/18



INSRS:

WSP:

Tel:

Liability:

RMKS:

4/18
Heng
Kinsmen

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check/Iss: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 2A

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
11/2/18

UP

TP.

#250.00 + #20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|----------------------------|------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CC4/AIG18002232/Apb3 | | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 05-02-2018 | |  |
| | | Code : AIG | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBD 3002E | Veh. Inspected | SJG 4709H | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 05/02/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 30/01/2018 | Inspection Date | 05/02/2018 | |
| Survey held at | KINSMEN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-19 AUTOBAY BUILDING SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |



ESTIMATE BILL

DATE : 05-02-18

JHMRH684085204266

OUR REF NO : SJG 4709H
MODEL : HONDA STRAM

NAME : JY ELETRICAL PTE LTD
ADDRESS : 7, YISHUN, INDUSTRIAL ST 1,
#05-46, NORTH SPRINT BIZHUB
SINGAPORE 768162

ESTIMATE ITEM

| | | |
|--|---------------------|---------------------------------|
| 1) REAR WINDSCREEN MOULDING <i>nee</i> | 2 PCS @ \$ 84.10 | 168.20 ✓ |
| 2) BOOT LID <i>Deeded</i> | | 1520.00 <i>903</i> |
| 3) BOOT LID WEATHERSTRIPE <i>let</i> | | 230.00 <i>122.10</i> |
| 4) BOOT LID STOPPER <i>nee nee</i> | 2 PCS @ \$ 10.20 | 20.40 X. |
| 5) TAIL LAMP (RH) <i>replaced</i> | | 427.00 <i>338.80</i> |
| 6) REAR BUMPER <i>Deeded</i> | | 1431.10 <i>688</i> |
| 7) REAR BUMPER CLIP <i>nee</i> | 6 PCS @ \$ 4.00 | 24.00 ✓ |
| 8) REAR BUMPER SIDE ATTACHMENT <i>nee</i> | 2 PCS @ \$ 49.00 | 98.00 <i>48</i> |
| 9) REAR BUMPER TOW COVER <i>Deeded</i> | | 74.00 <i>36</i> |
| 10) REAR EXHAUST SILENCER <i>nee nee</i> | | 567.00 X |
| 11) REAR EXHAUST MOUNTING <i>nee</i> | 2 PCS @ \$ 26.00 | 52.00 X |
| 12) REAR END PANEL <i>Deeded</i> | | 480.80 <i>2808.90</i> |
| 13) REAR PANEL INNER GARNISH <i>nee</i> | | 185.10 <i>2247.12</i> |
| 14) SPARE TYRE BRACKET <i>nee</i> | | 340.00 X |
| 15) SPARE TYRE ADJUSTING HOOK AND NUT <i>nee</i> | | 45.00 X |
| | | <hr/> 5662.60 |
| | LESS DISCOUNT - 20% | 1132.52 |
| | | 4530.08 |

SPECIAL NETT ITEM

| | | |
|--|--|-------------------|
| 1) REAR WINDSCREEN INNERSEAL <i>nee</i> | | 60.00 <i>40</i> |
| 2) REAR WINDSCREEN GUM <i>nee</i> | | 60.00 <i>40</i> |
| 3) REVERSE SENSOR WITH CONTROL UNIT <i>Damaged</i> | | 380.00 <i>200</i> |
| 4) REAR EXHAUST CHROME <i>nee nee</i> | | 120.00 X. |
| | | 620.00 |

LABOUR CHARGE

| | |
|--|------------------|
| 1) TO CHECK WIRING SYSTEM | 50.00 <i>30</i> |
| 2) TO APPLY UNDER SEALING ON AFFECTED AREAS | 120.00 <i>50</i> |
| 3) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT | 240.00 <i>80</i> |
| 4) TO REMOVE AND REFIX SPARE TYRE BRACKET | 120.00 X |
| 5) TO REMOVE AND REFIX REAR EXHAUST SILENCER | 150.00 X. |

- 6) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT
- 7) TO REMOVE AND REFIX TRIM, GARNISH, UPHOLSTERY AND ETC
- 8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC
- 9) TO RESPRAY ON THE AFFECTED AREAS

120.00 50
 150.00 60
 1000.00 800
 880.00 700
 2830.00
 7980.08

1770

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

L/S Admining
 05/02/18
 06 Days

Total 425712
 L/S 3 HK ✓

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 9825C

Vehicle Details

Vehicle No.: SJG4709H

Vehicle to be Exported: Yes

Intended De-registration Date: 03 Feb 2018

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8L A

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R18A12804248

Chassis No.: JHMRN68408S204266

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$20,330.00

Original Registration Date: 01 Jul 2008

First Registration Date: 01 Jul 2008

Transfer Count: 1

Actual ARF Paid: \$20,330.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Jun 2018

PARF Rebate Amount: \$10,165.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2018

COE Category: E - Open Category

Honda Stream 1.8A

| | |
|------------------------|---|
| Price | \$17,800 |
| Reg date | 09-Jun-2008 |
| Manufactured | 2007 |
| Mileage | 112,025 km |
| Transmission | Auto |
| Engine Capacity | 1,799 cc |
| Road Tax | \$978 per year |
| Power | 103.0 kW (138 bhp) |
| Curb Weight | 1,370 kg |
| Features | 1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Auto Climatic Aircon Control, Reverse Sensors, Knockdown Rear Seats, 4 x Disc Brake. |
| Accessories | Sports Rims, Pioneer Car Stereo System, Solar Film, Electrical Retractable Side Mirrors, Upholstery Leather Seats. |
| Description | Low Interest At 1.99%. Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Spectacular Good Condition, Test It And It Will Show You! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come To Our Aircon Showroom To Admire It In Pristine Condition Now, Before It's Gone! |
| COE | \$17,113 |
| OMV | \$21,472 |
| ARF | \$21,472 |
| Depreciation | - |
| No. of owners | 3 |
| Type of Vehicle | MPV |
| Availability | Available |

Seller Information

| | | |
|--------------------------|--|----------|
| Company | Dickson Automobile = dealer's pricelist = 76 vehs sold 253 vehs available | |
| Address | 55 Ubi Avenue 3 #01-01 | |
| Website | dicksonauto.com.sg | |
| Office No | 68447667 | |
| Contact Person(s) | Jonathan Quah | 91901666 |
| | Ricky Eng | 91853390 |
| | Eric Lee | 91827304 |

Posted on : 28-Jan-2018

Last Updated : 28-Jan-2018



New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



Maximise your earnings

Deliver with Uber Eats today. No experience needed.

Honda Stream

Price Range

Depreciation

2008

Vehicle Type

Used Car Comparison

— Comparing 3 Vehicles —

Honda Stream 1.8A Sunroof

Honda Stream 1.8A RSZ

Honda Stream 1.8A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to add to compare.

CAR DETAILS

| | | | | |
|-------------------|---|---|---|---|
| Price | \$18,888 | \$17,000 | \$17,800 | - |
| Instalment | \$3,338 | \$3,005 | \$3,146 | - |
| Registration Date | 18-Jun-2008 | 03-Jul-2008 | 09-Jun-2008 | - |
| Manufactured | 2007 | 2008 | 2007 | - |
| Mileage | 197,000 km | 118,000 km | 112,025 km | - |
| Transmission | Auto | Auto | Auto | - |
| Engine Cap | 1,799 cc | 1,799 cc | 1,799 cc | - |
| Road Tax | \$978 /yr | \$978 /yr | \$978 /yr | - |
| Power | 103.0 kW (138 bhp) | 103.0 kW (138 bhp) | 103.0 kW (138 bhp) | - |
| Curb Weight | 1,385 kg | 1,370 kg | 1,370 kg | - |
| Features | 1.8L I-VTEC Engine! 5 Speed Auto! ABS! 4 x Disc Brakes! Dual SRS Airbags! Auto Climatic Aircon Control! Electric Retractable Mirrors! Pedal Shift! | Powerful And Fuel Efficient 16 Valves SOHC I-VTEC Engine, 138Bhp, 5 Speed AT, Paddle Shifters, Dual Airbags, ABS, Digital Climatic Aircon. | 1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Auto Climatic Aircon Control, Reverse Sensors, Knockdown Rear Seats, 4 x Disc Brake. | - |
| Accessories | Sun Roof! Sports Rims! Leather Seats! Solar Film! Knockdown Rear Seats! HID Head Lights! Etc! | Full Leather Seats, Sports Rims, Reverse Sensors, Solar Film, Pioneer Player With Reverse Camera, Door Visor, Fog Lamps | Sports Rims, Pioneer Car Stereo System, Solar Film, Electrical Retractable Side Mirrors, Upholstery Leather Seats. | - |
| Description | Meticulous Owner Who Maintains His Car Very Well, All Wear And Tear Including Tyres Fully Replaced, Elegant Black With Lush Beautiful Black Interior, Up to 80% Financing Possible And We Do Welcome Trade Ins, Call/SMS Now To Arrange A Viewing And Viewings Strictly By Appointment Only | Genuine Low Mileage Only 118 K K/m. Road Tax Up To COE Ends. New Paint, Ready For COE Extension. Superb Condition. Servicing Just Done. Message / Whatsapp For Viewing Appointment. | Low Interest At 1.99%. Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Spectacular Good Condition, Test It And It Will Show You! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come To Our Aircon Showroom To Admire It In Pristine Condition Now, Before It's Gone! | - |
| COE | \$14,640 | \$16,500 | \$17,113 | - |
| OMV | \$20,882 | \$17,537 | \$21,472 | - |
| ARF | \$20,882 | \$17,537 | \$21,472 | - |
| Depreciation | - | - | - | - |
| No. of Owners | 2 | 4 | 3 | - |
| Type of Vehicle | MPV | MPV | MPV | - |
| Category | PARF Car, Premium Ad Car | PARF Car, Premium Ad Car | PARF Car | - |
| Availability | Available | Available | Available | - |

SELLER INFORMATION

Nivitha (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Monday, 5 February 2018 11:35 AM
To: 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: aigencrypt - Pre repair inspection request - SJG4709H VS GBD3002E (OI) DOA: 30.01.18
Attachments: RE: Notice of accident/notice to conduct pre-repair survey:Accidenton30.0... (257 KB); PRS.YHM.1st notice.AIG.SJG4709H.GBD3002E.amended.pdf

Hi,

Please refer to the enclosed request from **KSCGP Juris LLP**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

12:03pm @ 5/2/2018
vehicle in
person @ Wqh ting
amend on 6/2/18

@ 5/2/18 3:57pm
- Catherine confirm
ntsp do do.
* even attach lawyer notice.

Your Insured's vehicle : GBD 3002E
Our client's vehicle ; ref: SJG 4709H ; YHM/sy
Date : 5 February 2018

AIG Asia Pacific Insurance Pte. Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 30 JANUARY 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to the above matter and your email of even date.

We are instructed that our client would like to nominate your surveyor, Adrian Ling from LKK Auto Consultants Pte Ltd as the Single Joint Expert. Please be informed that our client's vehicle is available for pre-repair survey within next 2 working days at: -

Address : Yi Heng Motor Workshop
Block 1 Kaki Bukit Avenue 6
#02-19 Autobay Building
Singapore 417883
Contact Person/Tel : Mr. Yong Patric / 6509 0052

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your Insured's vehicle : GBD 3002E
Our client's vehicle : ref: SJG 4709H ; YHM/sy
Date : 5 February 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (party by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC4/AIG18002232/Apb3

09 MARCH 2018

NEWSTEAD TECHNOLOGIES PTE LTD
1 ROCHOR CANAL ROAD
#03-82 SIM LIM SQUARE
SINGAPORE 188504
ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GBD 3002E & SJG 4709H ON 30/01/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJG 4709H against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|---|---------------|--|--|--|-------------|---|
| Main | 05 Feb 2018 Edit Reg | | 05 Feb 2018 00:00 Edit Adj Rpt | S\$3,400.00 Edit Estimates | S\$3,400.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|-------------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | Newstead Technologies Pte Ltd , Co. Reg. No.: 200100468D | | | | | | | | |
| Main Claimant: | JY ELECTRICAL ENGINEERING PTE LTD , Co. Reg. No.: 201409825C | | | | | | | | |
| Vehicle Reg. No.: | SJG4709H | Date of Loss: | 30/01/2018 12:00 - :59 | | | | | | |
| Claim Type: | TP / 5353549397SG | Policy/Cover Note No.: | 2100384270-03 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | GBD3002E | Policy No. (Claimant): | DMCTHQ17-000007 | | | | | | |
| | Excess: | | | | | | | | |
| Repairer: | Kinsmen Auto Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6, #02-19 AUTOBAY BUILDING, 417883 Kaki Bukit - Tel: 81886626 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com | | | | | | | | |
| Claimant's Insurer: | EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/02/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (06/02/2018): No OI GIA Report AIG_SG (06/02/2018): Request To Upload TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

***SJG4709H (5353549397SG)**
[GBD3002E]

JY ELECTRICAL ENGINEERING PTE LTD
Jan 30 2018 12:00PM
[Newstead Technologies Pte Ltd]
Kinsmen Auto Pte Ltd

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_doc... 20/3/2018

| | | | | | |
|----|----------------|--------------------|---|----------|-------------------------------------|
| 32 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 52 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 53 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 54 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 55 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 56 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 57 | 16/03/18 14:42 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 58 | 16/03/18 14:43 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 59 | 16/03/18 14:43 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 60 | 16/03/18 14:43 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 61 | 16/03/18 14:43 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/02/18 16:02 | EMAIL FROM AIG DD 05022018 | 1 | Load PDF |
| 2 | 05/02/18 16:02 | NOTICE | 1 | Load PDF |
| 3 | 14/02/18 14:08 | TP GIA REPORT | 1 | Load PDF |
| 4 | 17/03/18 14:44 | TP ESTIMATE | 1 | Load PDF |
| 5 | 20/03/18 08:02 | LETTER TO OI | 1 | Load PDF |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 12/02/18 10:57 | E-filed GIA report - GBD3002E | 1 | Load PDF |
| 2 | 12/02/18 10:57 | Third Party E-filed GIA report SJG4709H | 1 | Load PDF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18002232/APB3Q2

Date: 20/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100384270-03
 Claimant Vehicle No: SJG4709H Insured Vehicle No: GBD3002E
 Date of Loss: 30/01/2018 Nature of Claim: TP Claim No: 5353549397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG4709H**
 Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A12804248
 Reg. Date: 01/07/2008 (Man. Year: 2008) Chassis No: JHMRN68408S204266
 Colour: Bronze Odometer: 260357 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 5,150.08 | 2,527.12 | 2,622.96 | 50.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,830.00 | 1,770.00 | 1,060.00 | 37.46 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,980.08 | 4,297.12 | 3,682.96 | 46.15 |
| Approved Total (Overridden) (S\$) | | 3,400.00 | | |
| (S\$) | 7,980.08 | 3,400.00 | 4,580.08 | 57.39 |
| + GST 7.00/7.00% (S\$) | 558.61 | 238.00 | 320.61 | 57.39 |
| Nett Amount (S\$) | 8,538.69 | 3,638.00 | 4,900.69 | 57.39 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 05/02/2018
 Date Inspected: 05/02/2018 Inspected At: Kinsmen Auto Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6, #02-19
 AUTOBAY BUILDING
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|------------|
| 1 | 2 | | *REAR WINDSCREEN MOULDING | Bent | 168.20 FL | *168.20 FL |
| 2 | 1 | | *BOOT LID | Dented | 1,520.00 FL | *903.00 FL |
| 3 | 1 | | *BOOT LID WEATHERSTRIP | Cut | 230.00 FL | *122.10 FL |
| 4 | 2 | | *BOOT LID STOPPER | Not Necessary | 20.40 FL | *- FL |
| 5 | 1 | | *TAIL LAMP (RH) | Cracked | 427.00 FL | *338.80 FL |
| 6 | 1 | | *REAR BUMPER | Deformed | 1,431.10 FL | *688.00 FL |
| 7 | 6 | | *REAR BUMPER CLIP | Necessary | 24.00 FL | *24.00 FL |
| 8 | 2 | | *REAR BUMPER SIDE ATTACHMENT | Necessary | 98.00 FL | *48.00 FL |
| 9 | 1 | | *REAR BUMPER TOW COVER | Deformed | 74.00 FL | *36.00 FL |
| 10 | 1 | | *REAR EXHAUST SILENCER | Not Necessary | 567.00 FL | *- FL |
| 11 | 2 | | *REAR EXHAUST MOUNTING | Not Necessary | 52.00 FL | *- FL |
| 12 | 1 | | *REAR END PANEL | Dented | 480.80 FL | *480.80 FL |
| 13 | 1 | | *REAR PANEL INNER GARNISH | Not Necessary | 185.10 FL | *- FL |
| 14 | 1 | | *SPARE TYRE BRACKET | Not Necessary | 340.00 FL | *- FL |
| 15 | 1 | | *SPARE TYRE ADJUSTING HOOK AND NUT | Not Necessary | 45.00 FL | *- FL |
| 16 | 1 | | *REAR WINDSCREEN INNERSEAL | Necessary | 60.00 FS | *40.00 FS |
| 17 | 1 | | *REAR WINDSCREEN GUM | Necessary | 60.00 FS | *40.00 FS |
| 18 | 1 | | *REVERSE SENSOR WITH CONTROL UNIT | Damaged | 380.00 FS | *200.00 FS |
| 19 | 1 | | *REAR EXHAUST CHROME | Not Necessary | 120.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 6,282.60 | 3,088.90 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 1,132.52 | 561.78 |
| Total Parts (S\$) | 5,150.08 | 2,527.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING SYSTEM | New | 50.00 | 30.00 |
| 2 | TO APPLY UNDER SEALING ON AFFECTED AREAS | New | 120.00 | 50.00 |
| 3 | TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT | New | 240.00 | 80.00 |
| 4 | TO REMOVE AND REFIX SPARE TYRE BRACKET | New | 120.00 | 0.00 |
| 5 | TO REMOVE AND REFIX REAR EXHAUST SILENCER | New | 150.00 | 0.00 |
| 6 | TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT | New | 120.00 | 50.00 |
| 7 | TO REMOVE AND REFIX TRIM ,GARNISH ,UPHOLSTERY AND ETC | New | 150.00 | 60.00 |
| 8 | TO REPLACE NEW PARTS ,CUT ,WELD ,KNOCK ETC | New | 1,000.00 | 800.00 |
| 9 | TO RESPRAY ON THE AFFECTED AREAS | New | 880.00 | 700.00 |
| Gross Labour Cost (\$\$) | | | 2,830.00 | 1,770.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >