

REC BY:

REF: CS3/LCR18002236/M1d302

Initial Instruction:

2405

MA

ASSIGNMENT (Office)

(Person):

chin lee ying

of

LCR

Date/Time:

5/2/2018

ated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFG 4151M

Insured:

SLL1494X

Tel:

6153 5779

at Workshop m/s

Lian Heng

of

160 Sin Ming Drive # 06-10

Policy No:

0999994978

Claim No:

2109976265SG

Excess:

Sum Insured:

D.O.A. 31/01/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up?}

H.O.D. Endorsement:

Date/Time:

10:03am @ 5/2/18

Person Contacted:

Tony

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SFG 4151M-X
	SLL1494X-X

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFG 4151 M Yr Regn: 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Poyota Altis C.C. 1598Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A Rim orTyre Size: F: 205/55 R16

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mm

D.O.A. _____

D.O.I. 5/3/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Submit DAR. report.

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

180

Transportation: _____

2)

) S + RS) \$

) Photos

) Other

20Report Format: DAR

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

TOTAL

200

Your password will expire in 7 days. [Click here to change it.](#)

FW: - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL1494X AND SFG4151M ON 31/01/2018

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc:
Sent: 5/2/2018 9:30:47 AM

Hi LKK,

We received reminder from law firm, kindly contact workshop to arrange for survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin, Lee-Ying
Sent: Friday, February 02, 2018 5:20 PM
To: 'assignments'; 'Admin A'
Cc: Fong, Andy-SY
Subject: RE: AIGENCRYPT - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL1494X AND SFG4151M ON 31/01/2018

Hi LKK,

Have you arrange survey for this PRI?

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin, Lee-Ying
Sent: Friday, February 02, 2018 1:45 PM

To: 'assignments'; 'Admin A'

Cc: Fong, Andy-SY

Subject: AIGENCRYPT - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL1494X AND SFG4151M ON 31/01/2018

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & CO

UEN NO. 53181067D

Advocates & Solicitors
Commissioner for Oaths

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

→ Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : lgene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/L1/1812210/st
Your Reference : SLL 1494X

Date : 1st February 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120

BY FAX 6835-7416 ONLY

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 31/01/2018 INVOLVING VEHICLE NOS. SFG 4151M AND SLL 1494X ALONG KAKI BUKIT ROAD 3 TRAFFIC LIGHT JUNCTION TOWARDS JLN TENAGA.

We are instructed by TAN SOH BOEY (owner of motor vehicle no. SFG 4151M) and/or LIAN HENG PAINTER COMPANY (the motor workshop for SFG 4151M) to notify you of a road traffic accident on 31/01/2018 at about 1135 hours along KAKI BUKIT ROAD 3 TRAFFIC LIGHT JUNCTION TOWARDS JLN TENAGA involving our client's vehicle registration number [SFG 4151M] and [SLL 1494X] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO - (Branch Office)
Encl

c.c. 1) LORF PTE LTD

2) NAME OF WORKSHOP :
LIAN HENG PAINTER COMPANY
160 Sin Ming Drive
#06-10 Sin Ming AutoCity
Singapore 575722
Telephone : 6453-5779/ 9863-2371 Fax : 6453-3173

(Vehicle : SLL 1494X)

(Vehicle : SFG 4151M)

(Attention : Normy/ Henry)

SFG 4181M

Rear Bumper	Dented
Rear Bumper Clip Set	Nec
Rear Bumper Sponge.	Tom
Rear Damper x 2	Dented
Rear End Panel	Dented
Rear End Panel Garnish	Deform
Taillamp x 2	?
Boottlid Lamp x 2	?
Rear Boottlid	Dented
Rear Boottlid Lock	Bent
Rear Boottlid Rubber	Deform
Rear Boottlid Emblem x 5	Nec
Rear Reverse Sensor	Damage

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Main Claimant: TAN SOH BOEY									
Vehicle Reg. No.: SFG4151M		Date of Loss: 31/01/2018 00:00 - :59 [108 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2109976265SG		Policy/Cover Note No.: 0999994978 (Comprehensive)							
Vehicle Reg. No. (Insured): SLL1494X		Policy No. (Claimant):							
		Excess:							
Repairer: Lian Heng Painter Company (HQ) BLK 11 Sin Ming Industrial Estate Sector B, #01-87, 575655 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 13/04/2018]									
Claimant's Solicitor: M NEDUMARAN & CO - Tel: 66351124									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (05/04/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFG4151M (2109976265SG)**
[SLL1494X]
TP
TAN SOH BOEY
Jan 31 2018 12:00AM
[LCRF PTE LTD]
Lian Heng Painter Company

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Assessment Reports						1 per page
No	Finalized On			Thumbnail	Print	
1	05/04/18 16:37	Accident Statement From: SC - Reg. No: SLL1494X, Claimant: LCRF PTE LTD		 Load HTM		
Photos/Images						3 per page
No	Relabel/Reorder			Thumbnail	Print	
1	10/05/18 17:17	General View		 Load JPG		☒
2	10/05/18 17:17	General View		 Load JPG		☒
3	10/05/18 17:17	General View		 Load JPG		☒
4	10/05/18 17:17	General View		 Load JPG		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18002236/M1D3E2

Date: 10/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994978
Claimant Vehicle No : SFG4151M **Insured Vehicle No :** SLL1494X
 Date of Loss: 31/01/2018 Nature of Claim: TP Claim No: 2109976265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG4151M**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: HIDDEN
 Reg. Date: 01/01/2009 (Man. Year: 2009) Chassis No: HIDDEN
 Colour: Silver Odometer: 0 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/02/2018
 Date Inspected: 05/02/2018 Inspected At: 160SIN MING DRIVE #06-10
 Repairer : Lian Heng Painter Company (HQ)
 Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*SET REAR BUMPER CLIP	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SPONGE	Torn	0.00 F	*- F
4	2		*REAR DAMPER	Dented	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL GARNISH	Deformed	0.00 F	*- F
7	2		*TAILLAMP	* Check	0.00 F	*- F
8	2		*BOOTLID LAMP	* Check	0.00 F	*- F
9	1		*REAR BOOTLID	Dented	0.00 F	*- F
10	1		*REAR BOOTLID LOCK	Bent	0.00 F	*- F
11	1		*REAR BOOTLID RUBBER	Deformed	0.00 F	*- F
12	5		*REAR BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*REAR REVERSE SENSOR	Damaged	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >