

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6787 M

1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✕	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 ✕	\$	92.00
1 pc	Bootlid emblem ✕	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Bootlid rubber weatherstrip ✕	\$	96.00
		\$	2,103.00

Less 10%

\$ 210.30
\$ 1,892.70

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	280.00 200
1 set	Bootlid stickers ✓	\$	100.00
Sundry		\$	50.00 20
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 ✕
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bootlid, bootlid lower garnish, end panel		\$	850.00 500
To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, end panel		\$	850.00 500
To apply rustproofing on the repaired and replaced panels.		\$	150.00 ✕
		\$	4,520.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kaharitery
2/2/18 1000 hrs.
3 Days
LHS
After Repair