

Aida

CC4 / III1800

2241

HAWAII

KK:

IDAC:

Surveyor:

MA CR

DOI:

ASSIGNMENT

5/1/18

Date / Time:

Registered in Merimen:

5/1/18

1/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH9491P

Name of Insured:

CTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

1/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lee PHAM GUAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MCOM001

H-Sonata

YISHUN ST 22 Opp Air C/P.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chuan



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Date/Time		STAGE	DATE / PIC
7/1/18	SH6535E - WSP / MCI 6014321 / MIGHT 12; DOA: 1/1/18	Non-Reporting ltr (1st):	
7/1/18	SH9491P - WSP / MCI 12074315 / YV16397; DOA: 2/1/18	Non-Reporting ltr (2nd):	
7/1/18	See k liability via merimen.	Non-Reporting ltr (Final):	
8/1/18	liability clear via merimen	Notification ltr (if non-pickup):	
26/4/18	File pass to typist type report	Call OI:	
28/1/18	Rec'd mandate via merimen.	After call ltr to OI:	
27/1/18	RECEIVED 26 APR 2018	Documentation Check List:	Handler Typist
30/4/18	Mandate approve via merimen	Notification ltr (if non-pickup)	☐ ☐
		After call ltr to OI:	☐ ☐
		Authorisation To Act:	☒ ☐
		Release Voucher:	☒ ☐
		Final Repair Bill:	☒ ☐
		Car Rental Invoice:	☒ ☐
		Towing Invoice	☐ ☐
		LTA / GIA :	☒ ☐
		Medical Bill:	☐ ☐
		PIR:	☐ ☐
		Mandate/Reject Instruction:	☒ ☐
		LOD	☒ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☐ ☐
		Others:	☐ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	SS	() days	Reduction:	%	Email ☐	Call ☐
--------------	----	----------	------------	---	--------------------------------	-------------------------------

FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐	Call ☐
------------------	------------	--------------	--------------------------------	-------------------------------

Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	24.	If NO or B 28, Ass. Lia:
------------------	---	-----------------------------------	-----	--------------------------

Repair Cost:	SS	11710.00	(13 days) X 115.00
--------------	----	----------	----------------------

Loss of Rental (LOR):	SS	1495.00	(13 days) X 115.00
-----------------------	----	---------	----------------------

Loss of Use (LOU):	SS	500.00	(13 days) X 115.00
--------------------	----	--------	----------------------

Loss of Income (LOI):	SS	—	() days
-----------------------	----	---	----------

LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]
-----------------------------------	-----------------------------------	------------------------------------	------------------------------------	-----------------

GIA/LTA Search	SS	—
----------------	----	---

Medical:	SS	—
----------	----	---

Disbursement:	SS	—	(e.g. Tow/ Independent)
---------------	----	---	-------------------------

Legal Cost	SS	—
------------	----	---

Total:	SS	13785.00	Global Sum SS: 13000.00
--------	----	----------	-------------------------

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐	Call ☐
---------------	------------	---------------	--------------------------------	-------------------------------


Payee 1:	SS	13000.00	Name 1:	Chunni Motor Work Pte Ltd
----------	----	----------	---------	---------------------------

Payee 2: (Strike if N.A.)	SS	—	Name 2:	—
---------------------------	----	---	---------	---

Payee 3: (Strike if N.A.)	SS	—	Name 3:	—
---------------------------	----	---	---------	---

ASSIGNMENT

Room: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at Workshop no: Quinn
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 13 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SA16252E / Page: FEB 2014
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or: _____
 Make: HYUNDAI 140 CC: 1685
 Colour: BLUE A/C: _____ Insured / Std / Nil / NA
 Sp. Reading: 53077 T. Radio: Insured / Std / Nil / NA
 Eng No: _____
 C No: KMHCB41UMDU04356
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 205/60 HR16
 R: 205/60 HR16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Weslake
 Front: 8 mm Rear: 8 mm
 R. Bal: 8 mm L. Bal: 8 mm
 D.O.A: 1/10/2018 D.O.A: 1/10/2018
 Survey held at: Weslake
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision

26/4/18 confirm US \$11000.00 with 13 working days

(2018) \$7666 x 41%.

Date/Time File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Breakdown: _____

Costs: _____

Notes: _____

Report Format: _____

Lump Sum / L.B.I.: \$ _____

Add Fee: ☐ Site Insp: \$ _____

☐ Inter. Exp: \$ _____

☐ Tech. Rep: \$ _____

☐ Night and: \$ _____

600
10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18002241/M1wa3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 05-02-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9491P	Veh. Inspected	SH 6253E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/02/2018	Inspection Date	05/02/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

To survey by Ldc (Ma)

VEHICLE NO : SH 6253E

DATE : 2.02.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

India

NT

Qty	Parts Description/ Labour	Type	Unit Price	Amount
✓	Rear Bumper		claf ✓ S	603.60
✓	Rear Bumper Clip 10 pcs		hse ✓ S	22.00
✓	Rear Fender With Housing (LH)		27. ✓ S	4,736.80
	Rear Fender Inner Lining (LH)		se ✓ S x	164.40
✓	Rear Windscreen Moulding		✓ S	60.00
✓	Rear Door (LH)		at ✓ S	1,351.10
✓	Rear Door Gear/Regulator (LH)		✓ S	785.50
✓	Rear Door Hinge Lower (LH)		✓ S	53.40
	Rear Door Check (LH)		✓ S	66.50
✓	Front Door (LH)		at ✓ S	1,403.05
✓	Front Door Gear / Regulator (LH)		✓ S	785.50
✓	Front Door Power Motor		✓ S	950.90
✓	Door Centre Pillar Outer (LH)		✓ S	1,786.20
	Rocker Panel Outer Garnish (LH)		2 x S	483.60
✓	Rear Tyre Rim (LH)		2 S	351.90
✓	Rear Wheel Hup-Cap (LH)		cur ✓ S	150.70
✓	Rear Wheelbearing ING & Hub		2 S	401.40
✓	Rear Trailing Arm (LH)		2 S	120.00
✓	Rear Assist (LH)		2 S	120.00
✓	Rear Shock Absorber (LH)		se x S	342.20
	Rear Shock Absorber Mounting (LH)		se x S	57.70
✓	Rear Crossmember		2 S	1,190.00
✓	Stabilizer Bar		cur x S	204.60
✓	Stabilizer Link		cur x S	68.15
✓	Rear Upper Arm (LH)		2 S	335.75
✓	Rear Lower Arm (LH)		2 S	204.35
✓	Rear Knuckle Arm (LH)		2 S	574.80
SUB TOTAL				S 17,374.10
LESS 20%				S 3,474.82
DISCOUNTED TOTAL				S 13,899.28
	Rear Bumper Rubber Mat		hse ✓ S	50.00
	Rear Windscreen Sealant		hse ✓ S	46.00
	Rear Door Comfortdelgro & Apps Sticker (LH)		hse ✓ S	80.00
	Front Door Coloured Comfort Logo (LH)		hse ✓ S	75.00
	Rear Tyre (LH)		over ✓ S	216.00
				S 467.00

Nett
Nett
Nett
Nett
Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6253E

DATE : 2.02.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

India

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper		del ✓	\$ 603.60
	Rear Bumper Clip 10 pcs		use ✓	\$ 22.00
	Rear Fender With Housing (LH)		2? ✓	\$ 4,736.80
	Rear Fender Inner Lining (LH)		one ✓	\$ x 164.40
	Rear Windscreen Moulding		✓	\$ 60.00
	Rear Door (LH)		at ✓	\$ 1,351.10
	Rear Door Gear/Regulator (LH)		?	\$ 785.50
	Rear Door Hinge Lower (LH)		use ✓	\$ 53.40
	Rear Door Check (LH)		over ✓	\$ 66.50
	Front Door (LH)		at ✓	\$ 1,403.05
	Front Door Gear / Regulator (LH)		?	\$ 785.50
	Front Door Power Motor		?	\$ 950.90
	Door Centre Pillar Outer (LH)		use ✓	\$ 1,786.20
	Rocker Panel Outer Garnish (LH)		2x	\$ 483.60
	Rear Tyre Rim (LH)		?	\$ 351.90
	Rear Wheel Hup-Cap (LH)		over ✓	\$ 150.70
	Rear Wheelbearing ING & Hub		?	\$ 401.40
	Rear Trailing Arm (LH)		?	\$ 120.00
	Rear Assist (LH)		?	\$ 120.00
	Rear Shock Absorber (LH)		x	\$ 342.20
	Rear Shock Absorber Mounting (LH)		x	\$ 57.70
	Rear Crossmember		?	\$ 1,190.00
	Stabilizer Bar		over x	\$ 204.60
	Stabilizer Link		over x	\$ 68.15
	Rear Upper Arm (LH)		?	\$ 335.75
	Rear Lower Arm (LH)		?	\$ 204.35
	Rear Knuckle Arm (LH)		?	\$ 574.80
	SUB TOTAL			\$ 17,374.10
	LESS 20%			\$ 3,474.82
	DISCOUNTED TOTAL			\$ 13,899.28
	Rear Bumper Rubber Mat		use ✓	\$ 50.00
	Rear Windscreen Sealant		use ✓	\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (LH)		use ✓	\$ 80.00
	Front Door Coloured Comfort Logo (LH)		use ✓	\$ 75.00
	Rear Tyre (LH)		over ✓	\$ 216.00
				\$ 467.00

SH 6253E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 1100
	Spray Painting Charge			\$ 1,200.00 1080
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 100.00 60
	Towing Charge			\$ 50.00 1
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100?
	Remove/Refix Reverse Sensor			\$ 120.00 60
	Remove/Refix Undercarriage (RR)			\$ 400.00 180?
	Remove/Refix Fuel Tank			\$ 150.00 X
	Transfer of Door		\$ 120.00	\$ 240.00 120
	Rear Wheel Alignment			\$ 120.00 80
	TOTAL LABOUR			\$ 4,300.00
	ESTIMATE TOTAL			\$ 18,666.28
Not Authorised L/S Rep Alt in paint powder LK Auto mb 8-9w days 5/2/2018				
LK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 5 February 2018 9:03 AM
To: Chunni Motor; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Zuhaidah Samsuri
Subject: RE: Accident involving veh no: SH 6253E & SH 9491P on 01.02.18
Attachments: 02022018160607.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SH6253E and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

9:37 am @ 5/2/2018
vehicle In
person @ Lynn
sur @ MA

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: 03 February, 2018 10:07 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident involving veh no: SH 6253E & SH 9491P on 01.02.18

Dear Sir,

We agree to appoint LKK Auto Consultants Pte Ltd.

Thank you

Regards,

Chunni Motor Work P/L

On Fri, Feb 2, 2018 at 4:40 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: 02 February, 2018 4:11 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Accident involving veh no: SH 6253E & SH 9491P on 01.02.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06, Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162.

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing,

handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SH6253E (MCT18020052)**
[SH9491P]

TP
COMFORT TRANSPORTATION PTE LTD
Feb 1 2018 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
Chunni Motor Work Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/02/2018 15:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SH6253E - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00:OID coming out from parking lot.

DOCUMENTS SUMMARY

There are no documents.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 6253 E

Technician:

Mileage: 530727

Time Printed 5.2.18 4:05 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°44'		-3°00' 3°00'
3°53'		-0°19' 5°41'
0°36'		-1°30' 1°30'
22°00'		
21°17'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°18'		-3°00' 3°00'
4°35'		-0°19' 5°41'
-0°28'		-1°30' 1°30'
12°51'		
13°09'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-1°01'		-3°00' 3°00'
-0°43'		-3°00' 3°00'
9°09'		-3°00' 3°00'
0°08'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°36'		-3°30' 2°30'
8°14'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°59'		-3°30' 2°30'
-0°08'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-1°23'		-3°00' 3°00'
8°06'		-3°00' 3°00'
4°11'		-3°00' 3°00'

View Received Message

This mail is associated with :

***SH6253E (MCT18020052)**
[SH9491P]

TP

COMFORT TRANSPORTATION PTE LTD

Feb 1 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/11/2018 14:03 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$13785.00) - SH6253E - Claim Handler: Zuhaidah Bte Samsuri

Approved:13785.00:Anymore damages photos? Looks like insufficient photos.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH6253E	Date of Loss:	01/02/2018 23:00 - :59 [47 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18020052	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SH9491P	Policy No. (Claimant):	MCOM0015
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 14/02/2018]		
Driver/Custodian (Insured):	LEE THIAM GUAN (), NRIC: S0911169G		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (30/11/2018): **Alert - Adj Mandate Approved (S\$13785.00) - SH6253E - Claim Handler: Zuhaidah Bt...**
- III_SG (28/08/2018): **Alert - Adj Mandate Maintained - SH6253E - Claim Handler: Zuhaidah Bte Samsuri**
- III_SG (08/02/2018): **Alert - Adj Mandate Approved (S\$0.00) - SH6253E - Claim Handler: Zuhaidah Bte Sa...**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SH6253E (MCT18020052)**

[SH9491P]

TP

COMFORT TRANSPORTATION PTE LTD

Feb 1 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 08:49	General View	 Load JPG	☒
2	30/04/18 08:49	General View	 Load JPG	☒
3	30/04/18 08:49	General View	 Load JPG	☒
4	30/04/18 08:49	General View	 Load JPG	☒
5	30/04/18 08:49	General View	 Load JPG	☒
6	30/04/18 08:49	General View	 Load JPG	☒
7	30/04/18 08:49	General View	 Load JPG	☒
8	30/04/18 08:49	General View	 Load JPG	☒
9	30/04/18 08:49	General View	 Load JPG	☒
10	30/04/18 08:49	General View	 Load JPG	☒
11	30/04/18 08:49	General View	 Load JPG	☒
12	30/04/18 08:49	General View	 Load JPG	☒
13	30/04/18 08:49	General View	 Load JPG	☒
14	30/04/18 08:49	General View	 Load JPG	☒
15	30/04/18 08:49	General View	 Load JPG	☒
16	30/04/18 08:49	General View	 Load JPG	☒
17	30/04/18 08:49	General View	 Load JPG	☒
18	30/04/18 08:49	General View	 Load JPG	☒
19	30/04/18 08:49	General View	 Load JPG	☒
20	30/04/18 08:49	General View	 Load JPG	☒
21	30/04/18 08:49	General View	 Load JPG	☒
22	30/04/18 08:49	General View	 Load JPG	☒
23	30/04/18 08:49	General View	 Load JPG	☒
24	30/04/18 08:49	General View	 Load JPG	☒
25	30/04/18 08:49	General View	 Load JPG	☒
26	30/04/18 08:49	General View	 Load JPG	☒
27	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
28	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
29	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
30	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
31	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
32	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
33	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
34	27/11/18 11:51	Reinspection Photo	 Load JPG	☒
35	27/11/18 11:51	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
37	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
38	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
39	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
40	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
41	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
42	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
43	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
44	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
45	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
46	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
47	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
48	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
49	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
50	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
51	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
52	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
53	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
54	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
55	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
56	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
57	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
58	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
59	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
60	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
61	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
62	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
63	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
64	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
65	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
66	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
67	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
68	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
69	27/11/18 11:51	Reinspection Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 16:22	TP ESTIMATE + TP GIA REPORT	1 Load PDF	
2	05/02/18 16:22	ACKNOWLEDGEMENT EMAIL TO III DD 05.02.2018	1 Load PDF	
3	07/02/18 13:42	TP ESTIMATE - MARKED	1 Load PDF	
4	27/04/18 17:35	AUTHORISATION TO ACT	1 Load PDF	
5	27/04/18 17:35	LOD	1 Load PDF	
6	27/04/18 17:35	RENTAL RECEIPT	1 Load PDF	
7	27/04/18 17:35	WORKSHOP INVOICE	1 Load PDF	
8	13/12/18 11:49	DISCHARGE VOUCHER	1 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 08:51	Singapore Accident Statement	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002241/DWA3S2

Date: 13/12/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SH6253E	Insured Vehicle No :	SH9491P
Date of Loss:	01/02/2018	Nature of Claim:	TP
		Claim No:	MCT18020052

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6253E		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDDU377524
Reg. Date:	11/02/2014 (Man. Year: 2013)	Chassis No:	KMHLB41UMDU043568
Colour:	Blue	Odometer:	530727 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,366.28	13,040.56	1,325.72	9.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,940.00	1,360.00	31.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,666.28	15,980.56	2,685.72	14.39
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	18,666.28	11,000.00	7,666.28	41.07
+ GST 7.00/7.00% (S\$)	1,306.64	770.00	536.64	41.07
Nett Amount (S\$)	19,972.92	11,770.00	8,202.92	41.07
+ Loss of Use (13.0 x S\$40.00/day) (S\$)		520.00		
+ Car Rental (13.0 x S\$115.00/day) (S\$)		1,495.00		
Nett Liability (S\$)		13,785.00		
Global Sum Settlement (S\$)		13,000.00		

INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 05/02/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK
 Autopoint
 Singapore 568047

Estimated Period of Repair: 13.0 days

Adjuster: BRYAN TANI**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2018)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6253E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*REAR FENDER WITH HOUSING (LH)	Bent	4,736.80 FL	*4,736.80 FL
4	1		*REAR FENDER INNER LINING (LH)	Serviceable	164.40 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Bent	60.00 FL	*60.00 FL
6	1		*REAR DOOR (LH)	Dented	1,351.10 FL	*1,351.10 FL
7	1		*REAR DOOR GEAR / REGULATOR (LH)	Bent / Shorted	785.50 FL	*785.50 FL
8	1		*REAR DOOR HINGE LOWER (LH)	Bent	53.40 FL	*53.40 FL
9	1		*REAR DOOR CHECK (LH)	Serviceable	66.50 FL	*- FL
10	1		*FRONT DOOR (LH)	Dented	1,403.05 FL	*1,403.05 FL
11	1		*FRONT DOOR GEAR / REGULATOR (LH)	Bent / Shorted	785.50 FL	*785.50 FL
12	1		*FRONT DOOR POWER MOTOR	Bent	950.90 FL	*950.90 FL
13	1		*DOOR CENTRE PILLAR OUTER (LH)	Bent	1,786.20 FL	*1,786.20 FL
14	1		*ROCKER PANEL OUTER GARNISH (LH)	Repair	483.60 FL	*- FL
15	1		*REAR TYRE RIM (LH)	Bent	351.90 FL	*351.90 FL
16	1		*REAR WHEEL HUP-CAP (LH)	Cut	150.70 FL	*150.70 FL
17	1		*REAR WHEELBEARING ING & HUB	Bent	401.40 FL	*401.40 FL
18	1		*REAR TRAILING ARM (LH)	Bent	120.00 FL	*120.00 FL
19	1		*REAR ASSIST (LH)	Bent	120.00 FL	*120.00 FL
20	1		*REAR SHOCK ABSORBER (LH)	Serviceable	342.20 FL	*- FL
21	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Serviceable	57.70 FL	*- FL
22	1		*REAR CROSSMEMBER	Bent	1,190.00 FL	*1,190.00 FL
23	1		*STABILIZER BAR	Serviceable	204.60 FL	*- FL
24	1		*STABILIZER LINK	Serviceable	68.15 FL	*- FL
25	1		*REAR UPPER ARM (LH)	Bent	335.75 FL	*335.75 FL
26	1		*REAR LOWER ARM (LH)	Bent	204.35 FL	*204.35 FL
27	1		*REAR KNUCKLE ARM (LH)	Bent	574.80 FL	*574.80 FL
28	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
30	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
31	1		*FRONT DOOR COLOURED COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
32	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	17,841.10	16,237.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,474.82	3,197.39
Total Parts (\$\$)	14,366.28	13,040.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,600.00	1,100.00
2	SPRAY PAINTING CHARGE.	New	1,200.00	1,080.00
3	WIRING CHARGE.	New	50.00	30.00
4	TUFF KOTE.	New	100.00	60.00
5	TOWING CHARGE.	New	50.00	50.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	100.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	60.00
9	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	180.00
10	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
11	TRANSFER OF DOOR.	New	240.00	120.00
12	REAR WHEEL ALIGNMENT.	New	120.00	80.00
Gross Labour Cost (S\$)			4,300.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >