

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 6253E

DATE : 2.02.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

IndiG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper		claf ✓	\$ 603.60
	Rear Bumper Clip 10 pcs		haz ✓	\$ 22.00
	Rear Fender With Housing (LH)		2? ✓	\$ 4,736.80
	Rear Fender Inner Lining (LH)		su ✓	\$ x 164.40
	Rear Windscreen Moulding		✓	\$ 60.00
	Rear Door (LH)		at ✓	\$ 1,351.10
	Rear Door Gear/Regulator (LH)		? ✓	\$ 785.50
	Rear Door Hinge Lower (LH)		haz ✓	\$ 53.40
	Rear Door Check (LH)		su ✓	\$ 66.50
	Front Door (LH)		at ✓	\$ 1,403.05
	Front Door Gear / Regulator (LH)		? ✓	\$ 785.50
	Front Door Power Motor		? ✓	\$ 950.90
	Door Centre Pillar Outer (LH)		haz ✓	\$ 1,786.20
	Rocker Panel Outer Garnish (LH)		2x ✓	\$ 483.60
	Rear Tyre Rim (LH)		? ✓	\$ 351.90
	Rear Wheel Hup-Cap (LH)		cur ✓	\$ 150.70
	Rear Wheelbearing ING & Hub		? ✓	\$ 401.40
	Rear Trailing Arm (LH)		? ✓	\$ 120.00
	Rear Assist (LH)		? ✓	\$ 120.00
	Rear Shock Absorber (LH)		x ✓	\$ 342.20
	Rear Shock Absorber Mounting (LH)		x ✓	\$ 57.70
	Rear Crossmember		? ✓	\$ 1,190.00
	Stabilizer Bar		only x ✓	\$ 204.60
	Stabilizer Link		only x ✓	\$ 68.15
	Rear Upper Arm (LH)		? ✓	\$ 335.75
	Rear Lower Arm (LH)		? ✓	\$ 204.35
	Rear Knuckle Arm (LH)		? ✓	\$ 574.80
	SUB TOTAL			\$ 17,374.10
	LESS 20%			\$ 3,474.82
	DISCOUNTED TOTAL			\$ 13,899.28
	Rear Bumper Rubber Mat		haz ✓	\$ 50.00
	Rear Windscreen Sealant		haz ✓	\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (LH)		haz ✓	\$ 80.00
	Front Door Coloured Comfort Logo (LH)		haz ✓	\$ 75.00
	Rear Tyre (LH)		over ✓	\$ 216.00
				\$ 467.00

Nett

Nett

Nett

Nett

Nett

Nett

SH 6253E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 1100
	Spray Painting Charge			\$ 1,200.00 1080
	Wiring Charge			\$ 50.00 30
	Tuff Kote			\$ 100.00 60
	Towing Charge			\$ 50.00 1
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100?
	Remove/Refix Reverse Sensor			\$ 120.00 60
	Remove/Refix Undercarriage (RR)			\$ 400.00 180?
	Remove/Refix Fuel Tank			\$ 150.00 X
	Transfer of Door		\$ 120.00	\$ 240.00 120
	Rear Wheel Alignment			\$ 120.00 80
	TOTAL LABOUR			\$ 4,300.00
	ESTIMATE TOTAL			\$ 18,666.28
Not Authorised HS Reg Alt - paint powder Lick auto mb 8-9w days <u>5/2/2018</u>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				