

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

Date / Time:

21/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJG 2044E

Name of Insured:

OP3 Creative Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A

28/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SJG 2044E

Policy No.:

SJG 2044E

Make / Model:

SJG

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJG 2044E



INSRS:

WSP:

Tel:

Liability:

RMKS:

NHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SJG 2044E / 17/1/2018 28/3/18 / Aua 3 n2: 28/01/18

SJG 2044E - X

20/2/18 BNP. Fault out first letter.

OL rear ended to TP.

RECEIVED 10 SEP 2018

RECEIVED 04 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN 3/5/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

5/9/18

Confirm with Sukyi

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

3500.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

360.00 (\$60 x 6 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

3867.45

Global Sum S\$: 3800.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3800.00

Name 1:

NEW HOCK TECK MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJJ842R Yr Regn: 2008 Sept
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Peugeot 308 C.C. 1598Colour: Red. A/C: Insured / Std / NI / NASp. Reading: 167701 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF34C5FTFSS200256.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45 R17.R: 225/45 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Liny Long.

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 02/02/18Survey held at MHT.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China.LIS - \$3500 + CRcd: \$ 11753.00 / 77%.MV: 16.5KPV: 12.8KNett: 3.7K.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ + RS. \$ _____

) Photos _____

) Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18002245/Aua3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 05-02-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 2044E	Veh. Inspected	SJJ 842R	
Policy No.	SNM18D00760C02	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/01/2018	Inspection Date	02/02/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Tuesday, 20 February, 2018 1:24 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJG2044E (OI : CTI - SNM18D00760C02) and SJJ842R (TP : LKK REF - CC6/CTI18002245/Aua3) on 28/01/2018

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: HMK

Dear Mei Kwan,

Our insured has not reported yet.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 20 February, 2018 12:17 PM
To: Lucas Lee; Chong Boon Sen
Cc: Thin Thin (LKKAUTO); Jas Khine (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SJG2044E (OI : CTI - SNM18D00760C02) and SJJ842R (TP : LKK REF - CC6/CTI18002245/Aua3) on 28/01/2018

Dear Lucas / Boon Sen,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #18-00 Springleaf Tower Singapore 079909
Tel: 6369 8111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D00760/C02/2**

Date: **09 FEBRUARY 2018**

via Ordinary & Registered Mail

**OP3 CREATIVE PTE LTD
15 KIM CHUAN TERRACE**

SINGAPORE 537037

Dear Sir / Madam

**ACCIDENT INVOLVING SJG2044E AND SJJ842R ON 28 JANUARY 2018
ALONG CTE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SJJ842R**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us **IMMEDIATELY** through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advise that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your **NO CLAIM DISCOUNT** will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN
Ref : CC6/CT118002245/AUA3
Contact No : 68412360
via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0421A) - VITESSE SOLUTIONS

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/CTI18002245/Aua3

20th February 2018

OP3 CREATIVE PTE LTD
15 KIM CHUAN TERRACE
SINGAPORE 537037

Dear Sir / Madam,

ACCIDENT INVOLVING SJG 2044E AND SJJ 842R ON 28.01.2018 ALONG/ AT CTE

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from CHINA TAIPING INSURANCE SINGAPORE PTE LTD dated 09th February 2018.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by 27th February 2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Thin Thin
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6801J

Vehicle Details

Vehicle No.: SJJ842R

Vehicle to be Exported: Yes

Intended De-registration Date: 02 Feb 2018

Vehicle Make: PEUGEOT

Vehicle Model: 308 1.6 A TURBO

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: 10FJAV0274242

Chassis No.: VF34C5FTF55200256

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$23,967.00

Original Registration Date: 01 Sep 2008

First Registration Date: 01 Sep 2008

Transfer Count: 5

Actual ARF Paid: \$23,967.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Aug 2018

PARF Rebate Amount: \$11,983.00

Intended COE Rebate Details

COE Expiry Date:	31 Aug 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$13,289.00
COE Rebate Amount:	\$768.00
Total Rebate Amount:	\$12,751.00

The information contained herein is correct as at 02 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6801J

Vehicle Details

Vehicle No.: SJJ842R

Vehicle to be Exported: Yes

Intended De-registration Date: 02 Feb 2018

Vehicle Make: PEUGEOT

Vehicle Model: 308 1.6 A TURBO

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: 10FJAV0274242

Chassis No.: VF34C5FTF55200256

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$23,967.00

Original Registration Date: 01 Sep 2008

First Registration Date: 01 Sep 2008

Transfer Count: 5

Actual ARF Paid: \$23,967.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Aug 2018

PARF Rebate Amount: \$11,983.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$13,289.00

COE Rebate Amount: \$768.00

Total Rebate Amount: \$12,751.00

The information contained herein is correct as at 02 Feb 2018

A-Assurance
Assurance in Insurance

Car Insurance Expiring?
We get you the cheapest insurance renewal

[Click to get quote](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)

[Advertiser Login](#)

[Ways of Selling](#)

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.65% APOR Car Financing
GV Credit Pte Ltd [Enquire](#)



Browse by Category ▾

Sort by Date Posted ▾

20 results/page ▾

1 vehicles

308

[Advanced Search](#) 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	308	Any	Any	2008	Any	Any	Any	Available



Peugeot 308 1.6A Premium

\$16,500

\$7,520 /yr

03-Nov-2008

1,598 cc

106,688 km

Hatchback

Available

Premium Continental Hatchback At Very Low Depreciation. 1 Of The Best Condition Used Units Around. Come View To Believe. Refined, Roomy Cabin And Stylish Look. Please Call To Arrange An Appointment Fo...

Posted: 22-Dec-2017 Tags: 2008 Peugeot 308, Peugeot 308, Peugeot, 308, Used Peugeot

[Save this search criteria, to get email alerts whenever a match is found.](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 ▾ results/page

sgCarMart is the number one car classifieds for parallel import cars; Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used 308, 308 Singapore, used 308 Singapore, used 308, used vehicles Singapore or even buy used 308 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current; sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- [Home](#)
- [New Car](#)
- [Used Car](#)
- [Sell Car](#)
- [Motoring Directory](#)
- [Products Guide](#)
- [Article](#)
- [Forum](#)
- [Tool & Tip](#)

- [About Us](#)
- [Careers](#)
- [Contact Us](#)
- [Sitemap](#)

© 2004-2018 sgCarMart. All rights reserved.

- [Terms of Service](#)
- [Privacy Policy](#)
- [Personal Data Protection Statement](#)

[Compare](#)



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LU JUN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/02/2018

Accident date: 28/01/2018

Estimated repair cost for vehicle no: SJJ842R PEUGEOT 308 1.6 A '08

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid <i>Rejis</i>		\$1,480.00 x
2	1	Rear Boot Lid Emblem Logo <i>new</i>		\$68.00 ✓
3	1	Rear Boot Lid Inner Lock		\$105.00 x
4	1	Rear Boot Lid Inner Rubber		\$142.00 ✓
5	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$678.00 x
6	1	Rear Boot Lid Windscreen Seal		\$105.00 x
7	2	Rear Tail Lamp <i>cracked</i>	\$296.00	\$592.00 ✓
8	1	Rear Bumper <i>deformed</i>		\$845.00 ✓
9	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
10	2	Rear Bumper Side Retainer <i>new</i>	\$34.00	\$68.00 ✓
11	2	Rear Bumper Side Cover <i>new</i>	\$128.00	\$256.00 x
12	1	Rear Bumper Towing Cover <i>not new</i>		\$58.00 x
13	1	Rear Bumper Number Plate <i>set</i>		\$50.00 ✓
14	2	Rear Bumper Number Plate Lamp <i>new new</i>	\$68.00	\$136.00 x
15	1	Rear Bumper Inner <i>Plastic dehd</i>		\$182.00 ✓
16	1	Rear Bumper Reinforcement <i>Bent</i>		\$465.00 ✓
17	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 2nd (sn)
18	1	Rear End Panel <i>dehd</i>		\$1,452.00 785
19	1	Rear End Panel Top Garnish <i>dehd</i>		\$148.00 ✓
20	2	Rear Fender Inner Trim Board <i>not new</i>	\$658.00	\$1,316.00 x
21	1	Rear Exhaust <i>2 new</i>		\$958.00 x
22	1	Rear Centre Exhaust		\$765.00 x
23	1	Rear Spare Tyre Panel Top Cover <i>2 new</i>		\$612.00 x
24	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 x

Subtotal:- \$11,363.00

Labour charges

To remove & refit cushion		\$280.00 50
To remove & refit reverse sensor		\$100.00 50
To remove & refit rear & centre exhaust		\$380.00 X
To remove & refit rear windscreen		\$120.00 X
Gum	1360	\$50.00 X
To check wiring		\$60.00 30
Tuff kote		\$100.00 30
Panel beating		\$1,400.00 600
Spray painting		\$1,400.00 600

Subtotal:- \$3,890.00

Total:- \$15,253.00

total: 446940

h/s: 3.5/10

05/07/10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18002245/Aua3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 2044E	Veh. Inspected	SJJ 842R
Policy No.	DMPCSN3040231700	Coverage (\$)	0.00
Claim No.	SNM18D00760C02/2	Excess (\$)	0.00
Assign From		Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 308	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	VF34C5FTF55200256	Colour	RED
Odometer	167701	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	LING LONG	6 mm
L/H Front Tyre	225/45 R17	LING LONG	6 mm
R/H Rear Tyre	225/45 R17	LING LONG	6 mm
L/H Rear Tyre	225/45 R17	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/01/2018	Inspection Date	02/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 842R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,480.00	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	68.00	68.00
1	REAR BOOT LID INNER LOCK	NOT NECESSARY	105.00	-
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	142.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	678.00	-
1	REAR BOOT LID WINDSCREEN SEAL	NOT NECESSARY	105.00	-
2	REAR TAIL LAMP @\$296.00	CRACKED	592.00	592.00
1	REAR BUMPER	DEFORMED	845.00	845.00
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$34.00	NECESSARY	68.00	68.00
2	REAR BUMPER SIDE COVER @\$128.00	NOT NECESSARY	256.00	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	58.00	-
1	REAR BUMPER NUMBER PLATE	BENT	50.00	50.00
2	REAR BUMPER NUMBER PLATE LAMP @\$68.00	NOT NECESSARY	136.00	-
1	REAR BUMPER INNER PLASTIC	DEFORMED	182.00	182.00
1	REAR BUMPER REINFORCEMENT	BENT	465.00	465.00
1	REAR END PANEL	DENTED	1,452.00	785.00
1	REAR END PANEL TOP GARNISH	DEFORMED	148.00	148.00
2	REAR FENDER INNER TRIM BOARD @\$658.00	NOT NECESSARY	1,316.00	-
1	REAR EXHAUST	NOT NECESSARY	958.00	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	765.00	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	612.00	-
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
	LESS 10% DISCOUNT		-	-323.30
			10,983.00	2,909.70
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	GUM (SN)	NOT NECESSARY	50.00	-
			430.00	200.00

Report Ref No. CC6/CT118002245/Aua3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REFIT CUSHION .		280.00	50.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REAR WINDSCREEN .	NOT NECESSARY	120.00	-
	TO CHECK WIRING .		60.00	30.00
	TUFF KOTE.		100.00	30.00
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BOOT LID .		1,400.00	600.00
	SPRAY PAINTING .		1,400.00	600.00
			3,840.00	1,360.00
	GRAND TOTAL		15,253.00	4,469.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CC6/CTI18002245/Aua3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.