

INS. CASE OWNER:

Kah Leong

CC 3/CTI1800

V52, 6/2/18

LKK:

IDAC:

Surveyor:

XGL

DOI:

ASSIGNMENT

2/2/18

Date / Time:

2/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKZ 6252H

Name of Insured:

YUEN HUNY KIM

Insured Tel No.:

HP:

83329334

Excess Sec II :SS

D.O.A:

31/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

DMP CSN 3014491802

Make / Model:

BMW

Place of Accident:

RMK RVE 3 TWOS RMK RW 6 &

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHC 4018M



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMART



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

6/2/18

Sent By:

TOM

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

2/12/19

Confirm with: Tan Lee Hui

Email ☐ Call ☐

Final Liability:

S\$

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia.:

Repair Cost:

S\$

4424.68

Loss of Rental (LOR):

S\$

738.30

(

6

days)

x \$123.05

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

300.00

(\$

50

x

6

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

5469.98

Global Sum S\$: 5450.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

5450.00

Name 1:

SMART Taxis Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$400

COPY SENT

Shel.

China

SHC4618m

12 Dec 2017

Toyota Prius Hybrid
Brown 1798
17822

JTDKB3FU703576147

195/65 R15
11

SS DUN BANOV Q1 PS L24 MID CH78U PR SW

TOYO

Front	Pass	8	8
8	8	8	8

02-02-18
w/s 4pm

See if Demos

The U.C. Cross frame Body Structure attached to the

PIP - \$4424.68 (Red \$ 5160.61 / 541)

☐ Prel Report
☐ Final Report

Days Of Rep
Resume No of The

Add Fee

See Fee



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18002252/Gyb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 05-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 6252H	Veh. Inspected	SHC 4018M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	02/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 CUBA LANE, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18002252/Gyb3

Date: 05.02.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC4018M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.02.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,346.12
Revised Estimate Amount	: S\$	3,708.58
"Check" Items Amount	: S\$	2,605.31
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

China.

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4018M
 Ref. No : TAX/01/18/2190
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TEO LEE HUAT
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 31/01/2018 08:40:00 PM
 Accident Reported Date / Time : 01/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094414
 Special Instruction to ARC, if any :
 TOWED \$40 / SKZ6252H
 Prepared Date : 01/02/2018 11:01:45 AM



LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4 Days.

~~Unsurvied Repair~~

After repair photos.

Gino Q:ay - 82880282

02/2/18.

part by part.

before paint photos.

Chassis No : JTDKB3FU703576147

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,836.00	0.00
Total Material Charges :	5,556.12	5,556.12
Other Charges :	940.00	0.00
TOTAL :	9,346.12	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	02/02/2018 10:11:29 AM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/02/2018 10:11:29 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/2/2018 10:11:47 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 800
Total Labour	1,014.00	0.00 400 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	378.00	0.00 200 ✓
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 X
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X
TO RESPRAY BUMPER BEAM	180.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 200 150 ✓
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200 ✓
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 150 ✓
Total Spray Painting & Panel Beating	1,836.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	80.00	0.00 40 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	20.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	940.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
21594793			COVER, RR BUMPER ASSY <i>Re</i>	1	423.90	25.00	317.92 ✓	Replace	Replace	No
24624700			PAD, RR BUMPER, RH & LH, 1 <i>2 / NCL</i>	2	3.80	25.00	5.70 ✓	Replace	Replace	No
24624700			PAD, RR BUMPER, RH & LH, 2 <i>2 / NCL</i>	2	3.80	25.00	5.70 ✓	Replace	Replace	No
24624700			PAD, RR BUMPER, RH & LH, 3 <i>2 / NCL</i>	2	3.80	25.00	5.70 ✓	Replace	Replace	No
21914700			SEAL, RR BUMPER ARM, RH & LH <i>2 / NCL</i>	2	11.00	25.00	16.50 ✓	Replace	Replace	No
			PIXEL STICKER <i>2 / NCL</i>	2	60.00	0.00	120.00 ✓	Replace	Replace	No
			SENSOR REVERSE <i>DM</i>	1	180.00	0.00	180.00 ✓	Replace	Replace	No
24534700			GUARD, RR BUMPER, LOWER <i>Re</i>	1	558.30	25.00	418.72 ✓	Replace	Replace	No
21694700			COVER, GUARD RR BUMPER LOWER <i>cut</i>	1	14.80	25.00	11.10 ✓	Replace	Replace	No
24614700			PAD, RR BUMPER, CTR <i>? X NN</i>	3	2.20	25.00	4.95 <i>1</i>	Replace	Replace	No
25664790			FILLER, RR BUMPER, LH <i>? X NN</i>	1	119.90	25.00	89.92 <i>1</i>	Replace	Replace	No
25654790			FILLER, RR BUMPER, RH <i>? X NN</i>	1	119.90	25.00	89.92 <i>1</i>	Replace	Replace	No
21611600			CLIPS PIECE, FRT & RR BUMPER <i>NCL</i>	10	1.50	25.00	11.25 ✓	Replace	Replace	No
25764700			RETAINER, RR BUMPER, LH <i>NCL</i>	1	111.50	25.00	83.62 ✓	Replace	Replace	No
25754700			RETAINER, RR BUMPER, RH <i>NCL</i>	1	112.70	25.00	84.52 ✓	Replace	Replace	No
20234700			REAR BUMPER REINFORCEMENT <i>2 NN</i>	1	318.80	25.00	239.10 <i>1</i>	Replace	Replace	No
99973010			ANTENNA, ELECTRICAL KEY <i>2 NN</i>	1	60.30	10.00	54.27 <i>1</i>	Replace	Replace	No
21834700			WIRE, LUGGAGE ROOM <i>? X NN</i>	1	143.50	10.00	129.15 <i>1</i>	Replace	Replace	No
33074700			END PANEL SUB-ASSY, BODY LOWER BACK <i>? X NN</i>	1	629.80	25.00	472.35 <i>1</i>	Replace	Replace	No
33504700			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH <i>2 NN</i>	2	56.70	25.00	85.05 <i>1</i>	Replace	Replace	No
33114710			SPARE TYRE PANEL PAN, REAR FLOOR <i>2 NN</i>	1	564.80	25.00	423.60 <i>1</i>	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX <i>? NCL</i>	1	37.00	0.00	37.00 <i>1</i> ✓	Replace	Replace	No
11054720			TAIL GATE GLASS SUB-ASSY, BACK DOOR <i>X NN</i>	1	1,569.70	25.00	1,177.27 <i>1</i>	Replace	Replace	No
13504700			TAIL GATE LOCK ASSY, BACK DOOR <i>BT</i>	1	452.10	10.00	406.89 ✓	Replace	Replace	No
11175010			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE <i>X NN</i>	2	27.90	25.00	41.85 <i>1</i>	Replace	Replace	No
5714700			TAIL GATE MOULDING GLASS, BACK DOOR <i>X NN</i>	1	29.70	25.00	22.27	Replace	Replace	No

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
'5574470 10		TAIL GATE MOULDING LOWER GLASS, BACK DOOR , LH X NH	1	29.90	25.00	22.42	Replace	Replace	No
'5573471 10		TAIL GATE MOULDING LOWER GLASS, BACK DOOR , RH X NH	1	29.90	25.00	22.42	Replace	Replace	No
	COMMON	SEALANT W/SCREEN X NH	3	37.00	0.00	111.00	Replace	Replace	No
'6801471 0A1		TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY B - CBA	1	891.20	25.00	668.40	Replace	Replace	No
'5441470 10		NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR - NL	1	52.30	25.00	39.22	Replace	Replace	No
'5442471 0		NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR - NL	1	52.30	25.00	39.22	Replace	Replace	No
'5403480 0		EMBLEM SUB-ASSY REAR - NL	1	46.30	25.00	34.72	Replace	Replace	No
		STICKER SMRT LOGO - NL	1	7.80	0.00	7.80	Replace	Replace	No
		STICKER DECAL 6555 8888 - NL	1	21.60	0.00	21.60	Replace	Replace	No
	REAR	NUMBER PLATE X NH	1	30.00	0.00	30.00	Replace	Replace	No
		NUMBER PLATE FRAME X NH	1	25.00	0.00	25.00	Replace	Replace	No
TOTAL MATERIALS							5,556.19	5,556.12	
TOTAL MATERIALS(Discounted)							5,556.12	5,556.12	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									
		REAR BUMPER REINFORCEMENT		239.10		239.10			
				118.80					

Shu Pei (LKKAUTO)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Tuesday, 6 February 2018 9:02 AM
To: Shu Pei (LKKAUTO); Claims Dept of CTI
Cc: Sharon Han; Jas Khine (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SKZ6252H (OI : CAI - TBA) and SHC4018M (TP : LKK REF -CC3/CTI18002252/Gyb3) on 31.01.2018
Attachments: DCIVisionDocumentSummary.pdf

WITHOUT PREJUDICE

Dear all

Attach herewith insured GIA's report.

Thank you.

Regards,

Adeline Chng

Executive
Claims Department (Motor Division)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896155
Fax: 62247478/62247175
Email: adeline.chng@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

 Please consider the environment before printing this email

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 6 February, 2018 8:53 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Sharon Han <sharon.han@sg.cntaiping.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKZ6252H (OI : CAI - TBA) and SHC4018M (TP : LKK REF - CC3/CTI18002252/Gyb3) on 31.01.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 4018M at M/s SMRT Automotive Services Pte Ltd – Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18002252/Gdb3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-12-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 6252H	Veh. Inspected	SHC 4018M
Policy No.	DMPCSN3013491802	Coverage (\$)	0.00
Claim No.	SNM18D00612C02	Excess (\$)	0.00
Assign From		Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703576147	Colour	BROWN
Odometer	17822	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4018M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER ,RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.92
2	PAD ,RR BUMPER ,RH & LH,1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER ,RH & LH,2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER ,RH & LH,3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	SEAL ,RR BUMPER ARM ,RH & LH @\$11.00 (DISC 25%)	NECESSARY	22.00	16.50
1	GUARD ,RR BUMPER ,LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER ,GUARD RR BUMPER LOWER (DISC 25%)	CUT	14.80	11.10
10	CLIPS PIECE ,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	RETAINER ,RR BUMPER ,LH (DISC 25%)	NECESSARY	111.50	83.62
1	RETAINER ,RR BUMPER ,RH (DISC 25%)	NECESSARY	112.70	84.52
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	CRACKED	891.20	668.40
1	NAME PLATE (HYBRID) ,LUGGAGE COMPARTMENT DOOR (DISC 25%)	DEFORMED	52.30	39.22
1	NAME PLATE (PRIUS) ,LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	TAIL GATE LOCK ASSY ,BACK DOOR (DISC 10%)	BENT	452.10	406.89
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
3	PAD ,RR BUMPER ,CTR @\$2.20	NOT NECESSARY	6.60	-
1	FILLER ,RR BUMPER ,LH	NOT NECESSARY	119.90	-
1	FILLER ,RR BUMPER ,RH	NOT NECESSARY	119.90	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	ANTENNA ,ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	WIRE ,LUGGAGE ROOM	NOT NECESSARY	143.50	-
1	END PANEL SUB-ASSY ,BODY LOWER BACK	NOT NECESSARY	629.80	-
2	REINFORCEMENT ASSY ,REAR FLOOR END PANEL ,RH & LH @\$56.70	NOT NECESSARY	113.40	-

Report Ref No. CC3/CTI18002252/Gdb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL ,PAN ,REAR FLOOR	NOT NECESSARY	564.80	-
1	TAIL GATE GLASS SUB-ASSY ,BACK DOOR	NOT NECESSARY	1,569.70	-
2	TAIL GATE DAM ,BACK DOOR GLASS UPPER ADHESIVE @\$27.90	NOT NECESSARY	55.80	-
1	TAIL GATE MOULDING GLASS ,BACK DOOR	NOT NECESSARY	29.70	-
1	TAIL GATE MOULDING LOWER GLASS ,BACL DOOR ,LH	NOT NECESSARY	29.90	-
1	TAIL GATE MOULDING LOWER GLASS ,BACL DOOR ,RH	NOT NECESSARY	29.90	-
3	SEALANT W/SCREEN @\$37.00	NOT NECESSARY	111.00	-
1	NUMBER PLATE	NOT NECESSARY	30.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	25.00	-
	TO TRANSFER REAR TAILGATE MECHANISM .	NOT NECESSARY	120.00	-
1	REAR BUMPER REINFORCEMENT (DISC 25%)	NECESSARY	318.80	239.10
			7,538.40	2,754.68
	LABOUR			
	PANEL BEATING & BODY WORK .		1,014.00	800.00
	SPRAY PAINT.		1,836.00	700.00
	TOWING CHARGE.		80.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO INSPECT RR LIGHTING ,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	20.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,670.00	1,670.00
	GRAND TOTAL		11,208.40	4,424.68
	RECOMMENDED COST OF REPAIRS			4,424.68

Report Ref No. CC3/CTI18002252/Gdb3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.