


China.

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4018M
 Ref. No : TAX/01/18/2190
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TEO LEE HUAT
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 31/01/2018 08:40:00 PM
 Accident Reported Date / Time : 01/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094414
 Special Instruction to ARC, if any :
 TOWED \$40 / SKZ6252H
 Prepared Date : 01/02/2018 11:01:45 AM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4 Days.

~~Insurance Repair~~

After repair photos.

Quo Qiang - 82880282

02/2/18.

part by part.

before paint photos.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703576147

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,836.00	0.00
Total Material Charges :	5,556.12	5,556.12
Other Charges :	940.00	0.00
TOTAL :	9,346.12	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	02/02/2018 10:11:29 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/02/2018 10:11:29 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 2/2/2018 10:11:47 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 <i>400 - 600</i>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	378.00	0.00 <i>200</i>
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 <i>?</i>
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 <i>?</i>
TO RESPRAY BUMPER BEAM	180.00	0.00 <i>?</i>
TO RESPRAY REAR PANEL	180.00	0.00 <i>200 150</i>
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 <i>?</i>
TO RESPRAY TAIL GATE	378.00	0.00 <i>200</i>
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 <i>150</i>
Total Spray Painting & Panel Beating	1,836.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 <i>?</i>
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>30</i>
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 <i>x</i>
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 <i>x</i>
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 <i>40</i>
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 <i>60</i>
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	20.00	0.00 <i>?</i>
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>?</i>
TO WASH AND VACUUM	60.00	0.00 <i>?</i>
Total Other Costs	940.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY <i>le</i>	1	423.90	25.00	317.92	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 <i>2/</i>	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 <i>2/</i>	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 <i>2/</i>	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH <i>3/</i>	2	11.00	25.00	16.50	Replace	Replace	No
			PIXEL STICKER <i>—</i>	2	60.00	0.00	120.00	Replace	Replace	No
			SENSOR REVERSE <i>DM</i>	1	180.00	0.00	180.00	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER <i>le</i>	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER <i>cut</i>	1	14.80	25.00	11.10	Replace	Replace	No
5246147010			PAD, RR BUMPER, CTR <i>?</i>	3	2.20	25.00	4.95 <i>2</i>	Replace	Replace	No
5256647930			FILLER, RR BUMPER, LH <i>?</i>	1	119.90	25.00	89.92 <i>2</i>	Replace	Replace	No
5256547930			FILLER, RR BUMPER, RH <i>?</i>	1	119.90	25.00	89.92 <i>2</i>	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER <i>— MCL</i>	10	1.50	25.00	11.25	Replace	Replace	No
5257647010			RETAINER, RR BUMPER, LH <i>— MCL</i>	1	111.50	25.00	83.62	Replace	Replace	No
5257547010			RETAINER, RR BUMPER, RH <i>— MCL</i>	1	112.70	25.00	84.52	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT <i>?</i>	1	318.80	25.00	239.10 <i>2</i>	Replace	Replace	No
5999730110			ANTENNA, ELECTRICAL KEY <i>?</i>	1	60.30	10.00	54.27 <i>2</i>	Replace	Replace	No
5218347010			WIRE, LUGGAGE ROOM <i>?</i>	1	143.50	10.00	129.15 <i>2</i>	Replace	Replace	No
5830747010			END PANEL SUB-ASSY, BODY LOWER BACK <i>?</i>	1	629.80	25.00	472.35 <i>2</i>	Replace	Replace	No
583504700			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH <i>?</i>	2	56.70	25.00	85.05 <i>2</i>	Replace	Replace	No
583114710			SPARE TYRE PANEL, PAN, REAR FLOOR <i>?</i>	1	564.80	25.00	423.60 <i>2</i>	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX <i>?</i>	1	37.00	0.00	37.00 <i>2</i>	Replace	Replace	No
81054721			TAIL GATE GLASS SUB-ASSY, BACK DOOR <i>X</i>	1	1,569.70	25.00	1,177.27 <i>2</i>	Replace	Replace	No
93504700			TAIL GATE LOCK ASSY, BACK DOOR <i>BT</i>	1	452.10	10.00	406.89	Replace	Replace	No
61175010			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE <i>X</i>	2	27.90	25.00	41.85 <i>2</i>	Replace	Replace	No
55714700			TAIL GATE MOULDING GLASS, BACK DOOR <i>X</i>	1	29.70	25.00	22.27	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
75574470 40			TAIL GATE MOULDING LOWER GLASS, BACK DOOR , LH <i>X</i>	1	29.90	25.00	22.42 <i>l</i>	Replace	Replace	No
75573471 10			TAIL GATE MOULDING LOWER GLASS, BACK DOOR , RH <i>X</i>	1	29.90	25.00	22.42 <i>l</i>	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN <i>X</i>	3	37.00	0.00	111.00 <i>l</i>	Replace	Replace	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY <i>R - CBA</i>	1	891.20	25.00	668.40	Replace	Replace	No
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR <i>del</i>	1	52.30	25.00	39.22	Replace	Replace	No
75442471 30			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR <i>del</i>	1	52.30	25.00	39.22	Replace	Replace	No
75403480 10			EMBLEM SUB-ASSY REAR <i>del</i>	1	46.30	25.00	34.72	Replace	Replace	No
			STICKER SMRT LOGO <i>del</i>	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 <i>del</i>	1	21.60	0.00	21.60	Replace	Replace	No
	REAR		NUMBER PLATE <i>X</i>	1	30.00	0.00	30.00 <i>l</i>	Replace	Replace	No
			NUMBER PLATE FRAME <i>X</i>	1	25.00	0.00	25.00 <i>l</i>	Replace	Replace	No
TOTAL MATERIALS								5,556.19	5,556.12	
TOTAL MATERIALS(Discounted)								5,556.12	5,556.12	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									