

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8277R

MAKE :

MODEL : HYUNDAI i40

CHINA

DATE 2/2/2018 10:47

DVA: 01.02.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover ✓			\$ 1,052.20	
	Front Bumper Sponge ?			\$ 142.20	
	Front Bumper Reinforcement ?			\$ 526.10	
	Front Bumper Bracket (LH) ?			\$ 24.60	
	Headlamp (LH) ✓			\$ 1,388.00	
	Front Fender (LH) ✓			\$ 619.00	
	Front Fender Shield (LH) ?			\$ 169.80	
	Front Wheel Hub Cap (LH) ✓			\$ 150.70	
	SUB TOTAL			\$ 4,072.60	
	LESS 20%			\$ 814.52	
	DISCOUNTED TOTAL			\$ 3,258.08	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Front Door Comfort Logo (LH) ✕			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) ✕			\$ 100.00	Nett
	Front Tyre (LH) ✕			\$ 216.00	Nett
				\$ 491.00	
	Labour Charge				
	Panel Beating			\$ 560.00 300	
	Spray Painting Charge			\$ 600.00 760	
	Wiring Charge			\$ 50.00 20	
	Tuff Kote			\$ 50.00 20	
	FRT Wheel Alignment			\$ 80.00 ✕	
	TOTAL LABOUR			\$ 1,340.00	
	ESTIMATE TOTAL			\$ 5,089.08	
Larry Ng 1 Call 1664 2/2/18 1245 hr 3041 PIP Before Part photo.					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: