

20/03/2002

ASS. REC. BY:

REF:

CS/MSG18002258/Aqd30

Special Instruction:

Survivor:

Mennen

Adrian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSIG

Date/Time:

5/2/18 @ 11.11am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SF24556D

Insured:

SLK 7271M

at Workshop m/s

Torque 5

Tel:

64524457

of

No. 8, Kaki Bkt Ave 4 # 01-50

Policy No:

29069766 MKF

Claim No:

548531

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/02/18

CA / REV / REP. / REV 24 HRS

'w/p'

H.O.D. Endorsement:

Date/Time:

12:24pm @ 5/2/18

Person Contacted:

Jenny

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SF24556D-x

SLK 7271M-x

06/07/18 @

7.40pm informed Christina Wong, we are pending estimate from repasser.

13/3/18 @

2.12pm revised to Christina Wong via Mennen.

V5 \$4000, 6 days CRed @ 10314-83, 75%.

REF:

Signature

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

SF24556D

Yr Regn: 2005 / Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Altis.

C.C.

1598.

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

257576.

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MR053ZEC107101593.

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

185/20R14.

R: _____

185/20R14.

BS DDN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 05/02/18.

Survey held at

Torque 5.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS/G.

* Note: MV: 201K.

PV: 15.4K

Next: 4.6K.

RECEIVED

13/3/2018

Date/Time. File Pass to?

☐

Preli. Report

1) 13/3/18

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

) S + RS) SI

) Photos

) Others

)

TOTAL

Report Format: _____

Lump Sum / I.B.A. (\$) _____

MER-IP
4000Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002258/Aqd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-02-2018



Code : MSG

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SLK 7271M	Veh. Inspected	SFZ 4556D
Policy No.	29069766MKF	Coverage (\$)	0.00
Claim No.	548531	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/02/2018	Inspection Date	05/02/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Reference No.: Cs/MSG/1800758/Aq/3
Policy Type: OD / TP / TP RES / TL / EVA

\$fz 4556D

Typist

(1) Office Assign Form

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

[illegible]

(1) Assignment Form

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity. (C.C)
N	Colour
C	Odometer. (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

[illegible]

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

13	3	18
----	---	----

Date _____

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submission	Adj Assigned	Adj By	Adj Submitted	Prv. Approved	Status
Main	02 Feb 2018		05 Feb 2018 11:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All				
CLAIM SUBFOLDER DETAILS			[Created by insurer]					
Insured:		GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G						
Main Claimant:		QUAH KEE PING, ID: S0107585C						
Vehicle Reg. No.:		SFZ4556D	Date of Loss:	02/02/2018 00:00 - :59				
Claim Type:		TP / 548531	Policy/Cover Note No.:	29069766MKF (Comprehensive) Cover : 01/02/2018 - 31/01/2019				
Vehicle Reg. No. (Insured):		SLK7271M	Policy No. (Claimant):					
			Excess:	S\$2,000.00				
Repairer:		Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457						
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]						
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/02/2018]						
Adj Asg. Remarks:		Kindly appoint MR MARCUS CHUA to conduct the survey . Please contact Mr Teo @ 6452 4457 to arrange for survey						
ASSOCIATED MAIL RECEIVED								
There are no mail for this case.								
View All Compose Case Mail								
ALL ASSOCIATED TASKS								
View All Search Tasks Create New Task Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Created On	Done?
No results.								

Iryani Amin

From: Woon Choo Kwok
Sent: Friday, 2 February, 2018 3:43 PM
To: Lionel Tan; Iryani Amin
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: Accident involving SFZ4556D & SLK7271M on 02/02/2018 (PRE-REPAIR SURVEY REQUEST)
Attachments: image001.emz; image012.wmz; SFZ4556D-GIA REPORT.pdf
Categories: Red Category

Dear LT & IBA

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MSIG** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Friday, February 02, 2018 3:08 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: Accident involving SFZ4556D & SLK7271M on 02/02/2018 (PRE-REPAIR SURVEY REQUEST)

From: Torque 5 Assessment [<mailto:assessment@torque5.com>]
Sent: Friday, February 02, 2018 2:35 PM
To: Claims <claims@sg.msig-asia.com>
Cc: assessment@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; claims@torque5.com
Subject: Accident involving SFZ4556D & SLK7271M on 02/02/2018 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Quah Kee Ping, to notify you of the aforesaid accident involving our client's vehicle SFZ 4556 D and your insured's vehicle SLK 7271 M on 02/02/2018.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SLK 7271 M for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Stephanie Teo (9147 8841)

Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 02/02/2018 01.00PM

PRS ARRANGEMENT (Date & Time) : 02/02/2018 02.35PM

PRS ACKNOWLEDGEMENT

Appointed Surveyor :
(Name & Signature)

Date & Time of Inspection :

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

Heng Lee Yi

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 13 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLK7271M	Accident Date	: 02/02/2018
TP Vehicle No	: SFZ4556D	Assignment Date	: 05/02/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 6.00
Date of Inspection	: 05/02/2018		
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,314.83
Revised Amount	:S\$	5,020.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,020.65

Lump Sum Repair	:S\$	4,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	15,359.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,641.00

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 6 February 2018 2:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SFZ 4556D (YOUR REF: 548531)

This mail is associated with :

***SFZ4556D (548531)**

[SLK7271M]

TP

QUAH KEE PING

Feb 2 2018 12:00AM

[GRAB RENTALS PTE.LTD.]

Torque 5 Pte Ltd

Dear Christina,

Please be informed that we have inspected the vehicle SFZ 4556D on 05/02/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Cbe Renewal Toyota Estima 2.4A



2018 Toyota Estima 2.4A
 5 Year Cbe Renewal
 GV Credit Pte Ltd

PRIME MOTOR & LEASING

With over 200 units of vehicles to choose from, ranging from all European to Japanese Make.

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

36 vehicles

Altis

Show 1 - 10 of 36 results

	Model	Price	Depreciation	Year Old	Eng Cap	Mileage	Veh Type	
Search Selection	Altis	Any	Any	> 10 year(s) old	Any	Any	Any	Available



Toyota Corolla Altis 1.6A (COE till 04/2020)

\$18,800**\$8,420 /yr****14-May-2005****1,598 cc****143,000 km****Sedan****Available**

Well Maintain, Immaculate Condition, Fuel Efficient And Reliable, In House Loan And Bank Loan Available, Trade In Are Welcome, Call Or Visit Our Showroom For Viewing.

Motor Universe Credit Pte Ltd

Posted: 26-Jan-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 09/2020)

\$19,800**\$7,560 /yr****19-Sep-2005****1,598 cc****-****Sedan****Available**

Well Maintained, Low Depreciation And Value For Your Money, Excellent Condition! Extended Warranty Available! Let This Reliable Yet Value For Money Sedan Give You A Comfortable And Enjoyable Ride. Buy...

Dickson Automobile

Posted: 20-Jan-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 10/2025)

\$48,000**\$6,260 /yr****04-Oct-2005****1,598 cc****176,884 km****Sedan****Available**

Neat And Well Maintained Altis Is Up For Sale. Call Me Now For More Information. Indeed This Is A Fuel Saver. Don't Miss It.

DIRECT OWNER

Posted: 02-Feb-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 09/2020)

\$21,500**\$8,110 /yr****11-Oct-2005****1,598 cc****-****Sedan****Available**

Cheapest In The Market! Why Rent When It's Only \$600 Depreciation Monthly? Low \$ Drive Away. Good For The Next 3 Years. Call Us Now!

Posted: 05-Feb-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

► Buy Tyres Online!
 ► Latest Special Offers from Tyrepack!



Toyota Corolla Altis 1.6A (COE till 10/2020)

\$19,800**\$7,310 /yr****21-Oct-2005****1,598 cc****-****Sedan****Available**

Not To Be Missed! Regularly Serviced. Smooth Engine And Gearbox. No Excessive Vibrations. No Funny Sounds From Suspensions.

Posted: 10-Jan-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 12/2020)

\$23,588**\$8,200 /yr****22-Dec-2005****1,598 cc****-****Sedan****Available**

\$0 Drive Away! 100% Accident Free, Very Well Maintained By Owner. Most Parts Has Been Replaced. In House Finance. In House Workshop. All In 1 Stop. Door Step Viewing Available. Kindly Arrange For View...

Posted: 02-Feb-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2021)

\$23,800**\$7,860 /yr****15-Feb-2006****1,598 cc****147,000 km****Sedan****Available**

"One Year In-House Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Monthly Installment, 10% Down Pa...

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7585C

Vehicle Details

Vehicle No.:	SFZ4556D
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Red
Manufacturing Year:	2005
Engine No.:	3ZZ4516678
Chassis No.:	MR053ZEC107101593
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,493.00
Original Registration Date:	20 Oct 2005
First Registration Date:	20 Oct 2005
Transfer Count:	1
Actual ARF Paid:	\$18,143.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,399.00
COE Rebate Amount:	\$15,359.00
Total Rebate Amount:	\$15,359.00

Message

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 02 / 02 / 2018 (dd/mm/yy) Time of Accident: 07 : 45 (24-HR-FORMAT)

Vehicle No. : SFZ4556D Vehicle Make & Model: Toyota Altis

Exact location of Accident: Loyang Ave.

Policyholder's Name / IC No. : Quah Kee ping / 50107585C

Driver's Name / IC No. : _____ (As Above) ☒

Driver's Contact No. : 9159 0767 Company Contact No: _____

Driver's Address: 6 Jalan Teliti

Insurance Company: NTUC Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

☒ Owner / ☐ Spouse / ☐ Children / ☐ Friend / ☐ Parents / ☐ Sibling / ☐ Relative / ☐ Employee / ☐ Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Occupation (nature of job) ☒ Indoor/ ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SLK7271M (B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: SLC6429A (C)

Driver's Contact No: _____ Insurance Company (If any): _____

Vehicle No: YM 9268X (D)

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, i vehicle 'A' was traveling on my designated lane. The car in front stopped and i follow suit. Suddenly, i heard a loud bang from behind and saw that vehicle 'D' has collided vehicle 'C' and 'B'. soon after i felt a large impact on my rear. I came down and realised that i was involved in a four car chain collision. I would also like to state that i felt one impact during this accident. I also had a passenger with me, Quah suat hong (S7701275C).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

TPMS19.

Xiao Chen.

Vehicle No : SFZ4556D
Make & Model : TOYOTA, COROLLA 1.6, MR053ZEC107101593
Year of : 2005
Manufacture

ESTIMATION REPORT

Estimation No. : E18020005
DOA : 02/02/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bootlid <i>broken</i>	1.00	0.00	0.00 ^{850.10}
2	Rear bootlid lock <i>2nd</i>	1.00	0.00	0.00 ^{890.00}
3	Rear bootlid weather strip <i>cut</i>	1.00	0.00	0.00 ^{152.90} 6320
4	Rear bootlid logo	1.00	0.00	0.00 ^{167.20}
5	Rear bootlid emblem - 1.6	1.00	0.00	0.00 ^{89.90} 3520
6	Rear bootlid emblem - E	1.00	0.00	0.00 ^{89.90} 38.40
7	Rear bootlid emblem - VVT-I	1.00	0.00	0.00 ^{167.90} 32.40
8	Rear bootlid emblem - Corolla	1.00	0.00	0.00 ^{169.90} 36.80
9	Rear bootlid emblem - Altis	1.00	0.00	0.00 ^{169.90} 38.80
10	Rear bootlid lamp (LH) <i>3 men</i>	1.00	0.00	0.00 ^{169.90} 25.20
11	Rear bootlid lamp (RH)	1.00	0.00	0.00 ^{981.20}
12	Rear bumper <i>broken</i>	1.00	0.00	0.00 ^{981.20}
13	Rear bumper clip <i>m</i>	1.00	0.00	0.00 ^{389.90}
14	Rear bumper retainer (LH) <i>3 m</i>	1.00	0.00	0.00 ^{50.00} 30
15	Rear bumper retainer (RH)	1.00	0.00	0.00 ^{98.90} 34.20
16	Rear bumper bracket (LH) <i>m</i>	1.00	0.00	0.00 ^{98.90} 34.20
17	Rear bumper bracket (RH) <i>broken</i>	1.00	0.00	0.00 ^{151.60}
18	Tail lamp (LH) <i>cracked</i>	1.00	0.00	0.00 ^{151.60} 4320
19	Tail lamp (RH) <i>cut</i>	1.00	0.00	0.00 ^{390.00} 289.60
20	Tail lamp clip (LH) <i>3 m</i>	1.00	0.00	0.00 ^{390.00} 289.60
21	Tail lamp clip (RH)	1.00	0.00	0.00 ^{15.00}
22	Tail lamp bracket (LH) <i>3 m</i>	1.00	0.00	0.00 ^{15.00}
23	Tail lamp bracket (RH)	1.00	0.00	0.00 ^{38.90}
24	Rear fender (LH) <i>3 m</i>	1.00	0.00	0.00 ^{38.90}
25	Rear fender (RH)	1.00	0.00	0.00 ^{1261.20}

Continue on next page...

6963



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFZ4556D
Make & Model : TOYOTA, COROLLA 1.6, MR053ZEC107101593
Year of : 2005
Manufacture

Estimation No. : E18020005
DOA : 02/02/2018

366770

No	Description	Qty	U/P	Amt
26	Rear fender cowl (LH)	1.00	0.00	0.00 + 188.70
27	Rear fender cowl (RH)	1.00	0.00	0.00 + 188.70
28	Rear fender cowl clip (LH)	1.00	0.00	0.00 + 50.00
29	Rear fender cowl clip (RH)	1.00	0.00	0.00 + 50.00
30	Rear fender inner trim (LH)	1.00	0.00	0.00 + 348.90
31	Rear fender inner trim (RH)	1.00	0.00	0.00 + 348.90
32	Rear fender inner trim clip (LH)	1.00	0.00	0.00 + 50.00
33	Rear fender inner trim clip (RH)	1.00	0.00	0.00 + 50.00
34	Rear fender air duct (LH)	1.00	0.00	0.00 +
35	Rear fender air duct (RH)	1.00	0.00	0.00 + 700.80
36	Rear end panel	1.00	0.00	0.00 + 395.00
37	Rear end panel top garnish	1.00	0.00	0.00 + 47.70
38	Rear end panel top garnish clip	1.00	0.00	0.00 + 50.00
39	Spare wheel panel	1.00	0.00	0.00 + 789.90
40	Spare wheel panel top board	1.00	0.00	0.00 + 428.90
41	Spare wheel panel sponge	1.00	0.00	0.00 +
42	Exhaust pipe	1.00	0.00	0.00 + 920.00
43	Exhaust pipe mounting	1.00	0.00	0.00 + 112.00
44	Exhaust pipe gasket	1.00	0.00	0.00 + 65.00
45	Taillamp Panel @ 381.20 RH Buckled	1.00	0.00	0.00 + 12393.10
Subtotal				\$5 0.00
Discount (0.00%)				\$5 0.00
Subtotal				\$5 0.00

Section: Special Nett Items

45	Rear bumper reverse sensor	1.00	400.00	400.00 - 200
46	Rear fender sealant	1.00	80.00	80.00 +
47	Rear end panel sealant	1.00	80.00	80.00 - 60

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFZ4556D
Make & Model : TOYOTA, COROLLA 1.6, MR053ZEC107101593
Year of Manufacture : 2005

Estimation No. : E18020005
DOA : 02/02/2018

No	Description	Qty	U/P	Amt
48	Spare wheel	1.00	500.00	500.00
49	Spare wheel panel sealant	1.00	80.00	80.00
50	Spare wheel panel insulator	1.00	100.00	100.00
				Amt S\$ 1,240.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,240.00

Section: Labour Items

51	To R&R accident affected areas	1.00	1,500.00	1,500.00
52	To putty & respray accident affected areas	1.00	1,300.00	1,300.00
53	To rust proof accident affected areas	1.00	60.00	60.00
54	To R&R rear boot mechanism	1.00	80.00	80.00
55	To R&R rear luggage compartment	1.00	200.00	200.00
56	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
57	To check wiring layout of tail lamp	1.00	80.00	80.00
58	To R&R exhaust pipe assy	1.00	200.00	200.00
59	To R&R rear windscreen	1.00	180.00	180.00
60	To check for water seepage	1.00	100.00	100.00
				Amt S\$ 3,780.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,780.00

total 5020.65

A/K

Adrian Ling
65/02/18 4/8
UG Samp.

P: 4754.40
= 3565.80
SN: 260.00
L: 1810.00

5635.80

#LIS \$4500 @ 6 repair days

KKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	1,240.00
Labour Items Subtotal	S\$
	3,780.00
Total	S\$ 5,020.00

PAGE 3 OF 3

14314.83

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 11:11 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G		
Main Claimant:	QUAH KEE PING, ID: S0107585C		
Vehicle Reg. No.:	SFZ4556D	Date of Loss:	02/02/2018 00:00 - :59
Claim Type:	TP / 548531	Policy/Cover Note No.:	29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019
Vehicle Reg. No. (Insured):	SLK7271M	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2018]		
Adj Asg. Remarks:	Kindly appoint MR MARCUS CHUA to conduct the survey . Please contact Stephanie Teo @ 6452 4457 to arrange for survey		

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

Claim Documents

***SFZ4556D (548531)**
[SLK7271M]
TP
QUAH KEE PING
Feb 2 2018 12:00AM
[GRAB RENTALS PTE.LTD.]
Torque 5 Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser ▼](#)

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/02/18 08:59	Non Reporting Letter to OI	Load HTM	
Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 14:12	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 15:42	General View	Load JPG	☒
2	13/03/18 15:42	General View	Load JPG	☒
3	13/03/18 15:42	General View	Load JPG	☒
4	13/03/18 15:42	General View	Load JPG	☒
5	13/03/18 15:42	General View	Load JPG	☒
6	13/03/18 15:42	General View	Load JPG	☒
7	13/03/18 15:42	General View	Load JPG	☒
8	13/03/18 15:42	General View	Load JPG	☒
9	13/03/18 15:42	General View	Load JPG	☒
10	13/03/18 15:42	General View	Load JPG	☒
11	13/03/18 15:42	General View	Load JPG	☒
12	13/03/18 15:42	General View	Load JPG	☒
13	13/03/18 15:42	General View	Load JPG	☒
14	13/03/18 15:42	General View	Load JPG	☒
15	13/03/18 15:42	General View	Load JPG	☒
16	13/03/18 15:42	General View	Load JPG	☒
17	13/03/18 15:42	General View	Load JPG	☒
18	13/03/18 15:42	General View	Load JPG	☒
19	13/03/18 15:42	General View	Load JPG	☒
20	13/03/18 15:42	General View	Load JPG	☒
21	13/03/18 15:42	General View	Load JPG	☒
22	13/03/18 15:42	General View	Load JPG	☒
23	13/03/18 15:42	General View	Load JPG	☒
24	13/03/18 15:42	General View	Load JPG	☒
25	13/03/18 15:42	General View	Load JPG	☒
26	13/03/18 15:42	General View	Load JPG	☒
27	13/03/18 15:42	General View	Load JPG	☒

28	13/03/18 15:42	General View	1	Load JPG	☒
29	13/03/18 15:42	General View	1	Load JPG	☒
30	13/03/18 15:42	General View	1	Load JPG	☒
31	13/03/18 15:42	General View	1	Load JPG	☒
32	13/03/18 15:42	General View	1	Load JPG	☒
33	13/03/18 15:42	General View	1	Load JPG	☒
34	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
35	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
36	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
37	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
38	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
39	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
40	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
41	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
42	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
43	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
44	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
45	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
46	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
47	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
48	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
49	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
50	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
51	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
52	13/03/18 15:42	Reinspection Photo	1	Load JPG	☒
Documentation					
				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/02/18 16:57	TPD SFZ4556D - PRI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002258/AQD3E2
Date: 14/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29069766MKF
Claimant Vehicle No :	SFZ4556D	Insured Vehicle No :	SLK7271M
Date of Loss:	02/02/2018	Nature of Claim:	TP
		Claim No:	548531

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFZ4556D	Engine No:	3ZZ4516678
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEC107101593
Reg. Date:	20/10/2005 (Man. Year: 2005)	Odometer:	257576 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,534.82	3,090.65	7,444.17	70.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,930.00	1,850.00	48.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,314.82	5,020.65	9,294.17	64.93
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	14,314.82	4,000.00	10,314.82	72.06
+ GST 7.00/7.00% (\$\$)	1,002.04	280.00	722.04	72.06
Nett Amount (\$\$)	15,316.86	4,280.00	11,036.86	72.06

INSPECTION

Date of Assignment:	05/02/2018		
Date Inspected:	05/02/2018	Inspected At:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4., #01-50 Singapore 415875
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/14/2018

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2018)
Parts: 143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFZ4556D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	890.00 FL	*850.10 FL
2	1		*REAR BOOTLID LOCK	Damaged	152.90 FL	*63.20 FL
3	1		*REAR BOOTLID WEATHER STRIP	Cut	167.20 FL	*167.20 FL
4	1		*REAR BOOTLID LOGO	Necessary	89.90 FL	*35.20 FL
5	1		*REAR BOOTLID EMBLEM - 1.6	Necessary	69.90 FL	*38.40 FL
6	1		*REAR BOOTLID EMBLEM - E	Necessary	69.90 FL	*32.40 FL
7	1		*REAR BOOTLID EMBLEM - VVT-I	Necessary	69.90 FL	*36.80 FL
8	1		*REAR BOOTLID EMBLEM - COROLLA	Necessary	69.90 FL	*38.80 FL
9	1		*REAR BOOTLID EMBLEM - ALTIS	Necessary	69.90 FL	*39.20 FL
10	1		*REAR BOOTLID LAMP (LH)	Not Necessary	481.20 FL	*- FL
11	1		*REAR BOOTLID LAMP (RH)	Not Necessary	481.20 FL	*- FL
12	1		*REAR BUMPER	Deformed	389.90 FL	*389.90 FL
13	1		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
14	1		*REAR BUMPER RETAINER (LH)	Necessary	98.90 FL	*34.20 FL
15	1		*REAR BUMPER RETAINER (RH)	Necessary	98.90 FL	*34.20 FL
16	1		*REAR BUMPER BRACKET (LH)	Not Necessary	151.60 FL	*- FL
17	1		*REAR BUMPER BRACKET (RH)	Dented	151.60 FL	*43.20 FL
18	1		*TAIL LAMP (LH)	Cracked	390.00 FL	*289.60 FL
19	1		*TAIL LAMP (RH)	Cut	390.00 FL	*289.60 FL
20	1		*TAIL LAMP CLIP (LH)	Necessary	15.00 FL	*15.00 FL
21	1		*TAIL LAMP CLIP (RH)	Necessary	15.00 FL	*15.00 FL
22	1		*TAIL LAMP BRACKET (LH)	Not Necessary	38.90 FL	*- FL
23	1		*TAIL LAMP BRACKET (RH)	Not Necessary	38.90 FL	*- FL
24	1		*REAR FENDER (LH)	Repair	1,261.20 FL	*- FL
25	1		*REAR FENDER (RH)	Repair	1,261.20 FL	*- FL
26	1		*REAR FENDER COWLING (LH)	Not Necessary	188.70 FL	*- FL
27	1		*REAR FENDER COWLING (RH)	Not Necessary	188.70 FL	*- FL
28	1		*REAR FENDER COWLING CLIP (LH)	Not Necessary	50.00 FL	*- FL
29	1		*REAR FENDER COWLING CLIP (RH)	Not Necessary	50.00 FL	*- FL
30	1		*REAR FENDER INNER TRIM (LH)	Not Necessary	348.90 FL	*- FL
31	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	348.90 FL	*- FL
32	1		*REAR FENDER INNER TRIM CLIP (LH)	Not Necessary	50.00 FL	*- FL
33	1		*REAR FENDER INNER TRIM CLIP (RH)	Not Necessary	50.00 FL	*- FL
34	1		*REAR FENDER AIR DUCT (LH) (NPA)	Not Necessary	0.00 FL	*- FL
35	1		*REAR FENDER AIR DUCT (RH) (NPA)	Not Necessary	0.00 FL	*- FL
36	1		*REAR END PANEL	Dented	795.00 FL	*700.80 FL
37	1		*REAR END PANEL TOP GARNISH	Deformed	231.70 FL	*47.70 FL
38	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FL	*10.00 FL
39	1		*SPARE WHEEL PANEL	Repair	789.90 FL	*- FL
40	1		*SPARE WHEEL PANEL TOP BOARD	Torn	428.90 FL	*192.50 FL
41	1		*SPARE WHEEL PANEL SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
42	1		*EXHAUST PIPE	Not Necessary	920.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHAUST PIPE MOUNTING	Not Necessary	112.00 FL	*- FL
44	1		*EXHAUST PIPE GASKET	Not Necessary	65.00 FL	*- FL
45	1		*TAILLAMP PANEL	O/S Buckled	762.40 FL	*381.20 FL
46	1		*REAR BUMPER REVERSE SENSOR	Damaged	400.00 FS	*200.00 FS
47	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
49	1		*SPARE WHEEL	Not Necessary	500.00 FS	*- FS
50	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*SPARE WHEEL PANEL INSULATOR	Not Necessary	100.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	13,633.10	4,034.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,098.28	943.55
Total Parts (\$\$)	10,534.82	3,090.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,500.00	850.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,300.00	850.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	40.00
4	TO R & R REAR BOOT MECHANISM	New	80.00	50.00
5	TO R&R REAR LUGGAGE COMPARTMENT	New	200.00	60.00
6	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	50.00
7	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	30.00
8	TO R&R EXHAUST PIPE ASSY	New	200.00	0.00
9	TO R&R REAR WINDSCREEN	New	180.00	0.00
10	TO CHECK FOR WATER SEEPAGE	New	100.00	0.00
Gross Labour Cost (S\$)			3,780.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >