

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0154/2018/GW
Date : 3-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chua Choon Guan
Address : Blk 322 Tampines Street 33
#10-146
Singapore 520322
Telephone : HP +65 97604621
Type of Claim : Own Damage Claims
Policy No. : 1800003093
Vehicle No : **SJW 2218 L**
Model Code : Audi A3 SB 1.0 TFSI
Model / Year : Jan-18
Engine No : CHZ612567
Chassis No : WAUZZZ8V0JA060807
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Jan-18
Place of Accident : Tan Tock Seng Hospital Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJW 2218 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	750.
3	To respray front bumper and rhs front fender.	\$ 1,500.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SJW 2218 L.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehd</i>	\$ 1,613.00	✓
2	FRONT BUMPER GUIDE SECTION-RH ?	\$ 33.00	?
3	FRONT BUMPER CLOSING ELEMENT-RH <i>men</i>	\$ 254.00	+
4	FRONT FENDER-RH <i>Regis</i>	\$ 746.00	+
5	FRONT FENDER BRACKET -RH <i>men</i>	2 \$ 65.00	+
6	FRONT FENDER CLOSING ELEMENT-RH <i>men</i>	\$ 53.00	+
7	FRONT WHEEL HOUSING LINER-RH <i>men</i>	\$ 151.00	+
8	LED HEADLOIGHT -RH <i>cruld</i>	\$ 4,888.00	✓
9	HEADLIGHT WASHER LIFT CYLINDER <i>men</i>	\$ 123.00	+
10	SUNDIRES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		\$ 8,326.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 12,478.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 05/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant