

REF: CS3 /MS617022159 /Grb-1e2

Special Instruction:

Malimán

ASSIGNMENT (Office)

From (Person): Jasmine Lok of MSU Date/Time: 24/01/2018

Estimated Cost: _____ Bill to: _____

US: \$ 7400.00

Third Parties:

Claimant:

Surveyor:

Workshop:

OD(TP Re-inspection) / Evaluation

To Inspect Vehicle No: GBD 7127C

Insured: GBD 4674J

at Workshop m/s ACE Autolution

Tel: 6844 1184

of 13 Kaki Bukit Rd 4 #03-29

Policy No: _____ Claim No: M537032

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16-11-2017
(Client's Record)

(Client's Record)

06-02-2018 (Tuesday) @ 10:30am

Do not Finalize

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 7 days)

Date/Time: 2/24/18 Submit Final Fig 370.0, 5 days (Red S 3760 / 50 %; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

RECEIVED 28 FEB 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 28/2/18 File Pass to typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop in/s _____

of _____

Insured _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBD7127C Reg: 30 Mar 2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Toyota Hiace No: 2982Colour: white A.O. Insured / Std / NI / NASer. Reading: 127469 T Radio: Insured / Std / NI / NA

Eng No: _____

O No: ITFH T02-P 300-155 427

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15R: 17BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R.Bal. 6 mm R.Bal. 6 mmL.Bal. 6 mm L.Bal. 6 mmD.O.A. _____ D.O.I. 06-02-18Survey held at: w/s 10:30 AmDes. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

Date/Time File Pass to:

☐ : Preli. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Date/Time File Return to:

Survey Fee

Transportation

___ \$ + P.S. ___ \$

Photos

Time

Report Format:

Lump Sum M.B. in \$

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Technician \$☐ Cleaning \$

TOTAL

Signature
28/2/2018

ASSIGNMENT

Ref: _____ Date: _____

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No. **G3D 7127C**At Workshop No. **Tampine H.T. Svc**No. **932 Tampine St. 93 #31-36**

Insured

Policy No.

Claims No.


Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Est. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA PR Seen

Consistent? : Yes or No

Est. Repairs.

4

days

Res: Yes or No

Lump Sum

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No. **G3D 7127C** Reg. **30/3/2015**Type: M. Car / M. Cycle / Bus **(Van)** / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make **Toyota Hiace** : 2982Colour **White** A.C. Insured / Std / NI / NASt. Reading **(1877)** T. Basic Insured / Std / NI / NA

Eng No.

Ch No. **JTFHT02P3001SS427**Gen. Cond. **Good / Fair** / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi Nil / S/Rim / **STD A/Rim** or

Tyre Size F:

195 R15 C

R:

195 R15 CBS: **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R. Bal

4

mm

R. Bal

4

mm

L. Bal

4

mm

L. Bal

4

mm

D.O.A.

16/11/2017 DOI **21/11/2017**

Survey held at:

At Above @ 1.26pmDes. of Damages: Frt / **Rear** / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

 Range **\$2900 - \$3900**
4 days

RECEIVED 1 FEB 2016

RUT

31/1/2018

File Time File Passed

31-01-2018

File Time File Returned



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transit Fee

Towing Fee

Parking Fee

Other Fee

Total Fee

Add Fee:



Site Insp. \$



Interview \$




Tech. Insp. \$



Other Fee \$

Report Format: **PRS.**

Lump Sum / I.B.I.:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17022159/rb-1

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBD 4674J	Veh. Inspected	GBD 7127C
Policy No.		Coverage (\$)	0.00
Claim No.	M537032	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	06/02/2018
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-22 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Sent: Wednesday, 24 January, 2018 5:13 PM
To: Don Tan
Cc: assignments; SUR
Subject: RE: Our ref: M537032 Your ref: AS.172673.dt

Dear Don,

We refer to the email below.

Our appointed surveyor, LKK Auto Consultants (6256 3561) will be reverting to you shortly.

Dear Wilson Teo,

Please reply Mr Don from Chia S Arul LLC (6733 4647) regarding the re-inspection date.

Thank you.

Have a nice day ahead

Jasmine Lok

Executive, Claims Services (Motor)

Direct line +65 6594 2550 | Direct fax +65 6225 7402 | jasmine_lok@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us

on    

From: Don Tan [mailto:don@chiaarul.com]
Sent: Wednesday, 24 January, 2018 5:09 PM
To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Subject: RE: Our ref: M537032 Your ref: AS.172673.dt

WITHOUT PREJUDICE

Dear Jasmine,

We refer to the above matter and to your email below.

Kindly be inform that our client's vehicle is ready for re-inspection on the following details:-

Date:	6 February 2018 (Tuesday)
Time	10.30 a.m.

Venue:	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03 – 29 BARTLEY BIZ CENTRE SINGAPORE 417807
Contact:	Ms Jenny 6844 1184

Kindly let us have your confirmation soon.

Thank you.

Regards,

Mr Don Tan

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Begin forwarded message:

From: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>

Subject: Our ref: M537032 Your ref: AS.172673.dt

Date: 17 January 2018 at 2:30:08 PM SGT

To: "info@chiaarul.com" <info@chiaarul.com>

Dear Alywin,

We acknowledge receipt of your client's claim on 10.01.2018

We would like to re-inspect your client's vehicle. Please arrange for an appointment, giving at least 10 days prior notice.

Thank you.

Have a nice day ahead.





Jasmine Lok

Executive, Claims Services (Motor)

Direct line +65 6594 2550 | Direct fax +65 6225 7402 | jasmine_lok@sg.msig-asia.com



MSIG insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore
048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No.

200412212G | <http://www.msg.com.sg/> | Follow us on    

A member of  **INSURANCE GROUP**

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017		20 Nov 2017 15:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SYSTEM TECHNIC ENGINEERING PTE LTD, Co. Reg. No.: -		
Main Claimant:	VOIS PTE LTD, Co. Reg. No.: 200505930G		
Vehicle Reg. No.:	GBD7127C	Date of Loss:	16/11/2017 07:00 - :59
Claim Type:	TP / 537032	Policy/Cover Note No.:	B2862557MKC (Comprehensive) Coverage: 04/11/2017 - 03/11/2018
Vehicle Reg. No. (Insured):	GBD4674J	Policy No. (Claimant):	
	Excess:		
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 07/02/2018]		
Driver/Custodian (Insured):	TEO WEE CHONG (), NRIC: S7507422J		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (05/02/2018): Report Send Back Alerts - GBD7127C (TP)


ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S



Our ref: AS.172673.dt

Your ref: To be advised

537032
JLote

10th January 2018

SYSTEM TECHNIC ENGINEERING PTE. LTD.
37 JALAN PEMIMPIN
#04-15 MAPEX
SINGAPORE 577177

BY CERTIFICATE OF POSTING

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY
#23-01 SGX CENTRE 2
SINGAPORE 068807

BY PDX

Dear Sirs,

**ACCIDENT INVOLVING GBD 7127C & GBD 4674J & ANOTHER ALONG SLIP ROAD
OF PUNGGOL ROAD TOWARDS TPE(SLE) ON 16 NOVEMBER 2017**

We refer to the above matter.

We act for **VOIS PTE LTD**, the owner of motor vehicle GBD 7127C involved in the captioned accident.

We were instructed by our client to claim damages against you in connection with a road traffic accident on 16 November 2017 along slip road of Punggol Road involving our client's motor vehicle GBD 7127C and your motor vehicle GBD 4674J driven by you or your authorized driver and/or your insured at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a)	Cost of Repair		S\$ 7,400.00
b)	Rental (13 days x \$120)		S\$ 1,560.00
c)	LTA		S\$ 7.49
d)	Cost of survey		S\$ 400.00
e)	Costs		S\$ 1,500.00
	Total		S\$ 10,867.49

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

ML, ML2 solve
ML
Scan England do
17/1/18 M. M. M. M.

A copy of each of the following supporting documents is enclosed.

- a) Our client's police report;
- b) A copy of the LTA search;
- c) A copy of the survey report; and
- d) A copy of the rental invoice.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

MR ARULCHELVAN S

Enclosure(s)

Enquire Vehicle & Owner Information (Vehicle No. GBD4674J As At 16 Nov 2017 / 07:25:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: GBD7127C

Current Owner Details

Owner ID Type: Company
Owner ID: 200500254M
Owner Name: SYSTEM TECHNIC ENGINEERING PTE. LTD.
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 37
Registered Street Name: JALAN PEMIMPIN
Registered Unit No.: # 04 - 15
Registered Building Name: MAPEX
Registered Postal Code: 577177

Current Vehicle Details

Vehicle No.: GBD4674J
Make Description/Model: TOYOTA / TOYOTA HIACE VAN TURBO 5 DR MANUAL
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Thank you



Chia See Kim Angela Sharon has successfully logged out.

Your last login date and time was 10 Jan 2018, 09:37:06.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please [CLEAR YOUR CACHE](#) after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	GBD4674J	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	10 Jan 2018 / 09:37:50

172433.d4

JOB SUMMARY REPORT

ACE AUTOLUTION PTE LTD
13 ,KAKI BUKIT ROAD 4
BARTLEY BIZ CENTRE #03-29,
SINGAPORE 417807.

BILLING

BILL to -

Vehicle NO : GBD 7127 C
Repair Type : LUMPSUM
Repair As Per Surveyor Report: \$ 7,400.00
Material Cost :
Less Repair Items/Adjustment
Special Nett Items :
Total Repair Cost : \$ 7,400.00

Final Repair Cost : \$ 7,400.00

Others

Search Fees (LTA) -
Surveyor Fees \$ 400.00
Loss of Rental \$ 1,560.00 13 DAYS

Loss Of Use -

Total Amount Bill : \$ 9,360.00

Approved By : QUEK YONG PHENG
Date : 4/1/18

Signature:





福泉興汽車出租及貿易私人有限公司

HOCK CHUAN HENG CAR RENTAL & TRADING PTE LTD

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246, 6294 9170 Fax: 6298 386

HIRER'S PARTICULARS
If Different From
Section ①I/We Vois Pte Ltd
of 121 B Edgedale Plains
S 821121 Tel: 9106 9828

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from HOCK CHUAN HENG CAR RENTAL & TRADING PTE LTD hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:

a) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$1500 to cover for any third party damage or injury claims and also bear the full cost of any damage cause to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.

b) COMPREHENSIVE MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2000 for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle.

whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the Terms and Conditions. Hire, hereinafter mentioned and printed at the back hereof:

Vehicle Regn No. 車輛註冊號碼 <u>6F 24 S</u>		Rental Agreement 合同號碼 No. H 14651	
Section ① Hirer's And/Or Driver's Particulars 租車者/駕駛員個人記錄		租出日期及時間 Date & Time OUT <u>16/11/2017 @ 6:00p</u>	
姓名 Name: <u>Koo Hong Thian</u>		交車日期及時間 Date & Time IN <u>29/11/2017 @ 6:30p</u>	
地址 Address: <u>121 B Edgedale Plains, S 821121</u>		Chargeable	Rates Amount
S		<u>13</u>	天 Days @ \$ <u>81560</u>
居民證/護照號碼 I/C No./Passport No: <u>62488622 R</u>	駕駛執照號碼 Driving Licence No:	星期 Weeks @ \$	
居民證/護照種類 Type of I/C./Passport:	Pass 日期 Pass Date: <u>27/04/2015</u>	月 Months @ \$	
出生日期 Date of Birth: <u>7/3/1980</u>	發出地 Place of Issue:		
三號保險底金 \$1500/- a) Third Party Only Policy Excess \$1500/-	一號保險底金 \$2000/- b) Comprehensive Policy Excess \$2000/-	保險 Insurance	
車輛必須歸還車主於 Vehicle Must Be Returned To Owner's Office By:		總計 Total Charge	
備註與付款記錄 Remarks & Payment Records		按金 Security Deposit	
		總金額 Total Payable	<u>81560</u>
		來銀 Amount Paid	
		送車/費 Delivery Fees	
IMPORTANT! For Singapore Use only.		收車費用 Collection Fees/Misc.	
		超過/小時 Extra Hours @ \$	
出車油箱 Fuel Tank OUT <u>E 1/8 1/4 1/2 3/4 7/8 F</u>	出車油箱 Fuel Tank IN <u>E 1/8 1/4 1/2 3/4 7/8 F</u>	租費不包括汽油 Rates Do Not Include Fuel	添油 Refuelling
車牌號碼 Vehicle No: 1)	起 From:	至 To:	
車牌號碼 Vehicle No: 2)	起 From:	至 To:	
工具 Tools	輪胎 Spare Tyre	裝飾品 Accessories	加額費用 Total Additional Charges
車輛發出人 Vehicle Issued By:	車輛接收人 Vehicle Collected By:		
NOTE: 註 租車者或司機必須付所有停車, 違反交通及曠過量黑煙法例負起一切的責任。 HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING, TRAFFIC AND SMOKY EXHAUST VIOLATION.			
		總計 Grand Total	

租車者不准載沙或石灰
HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE
PLS CHECK ENGINE OIL AND RADIATOR WATER EVERY MORNING.我/我們同意以上及後頁租車公司所列的條規與條件。
I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.日期
Date: 29/11/17租車者簽名
Signature of Hirer: [Signature]

ACE AUTOLUTION PTE LTD

13,KAKI BUKIT ROAD 4 ,BARTLEY BIZ CENTRE #03-29,SINGAPORE 417807.

COMPANY REG. NO : 201403869W

EMAIL: admin@aceauto.com.sg

TEL: 6844 1184

FAX: 6702 4202

NAME : VOIS PTE LTD

DATE : 4/1/18

PROFORMA INVOICE : ACE-165-2017

JOB NO. -

ADDRESS : BLK 121B EDGEDALE PLAINS
821121

VEHICLE NO. GBD 7127 C

MAKE & MODEL : TOYOTA HIACE

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	COST OF REPAIR			\$ 7,400.00
			TOTAL	\$7,400.00

IMPORTANT

Please remit payment within 7 days from the due date

An interest of 1.5% per month will be levied on all overdue amounts

*All cheques must be made payable to **ACE AUTOLUTION PTE LTD***

(WE ARE NOT GST REGISTERED)

This a computer generated document.No signature is required.

S K AUTO CONSULTANTS

Invoice

Bill To: Vois Pte Ltd
C/o ACE Autolution Pte Ltd
13 Kaki Bukit Road 4 #03-29
Bartley Biz Centre
Singapore 417807

Invoice No:	2017461
Date:	28/12/2017
Our Ref	TP/017/0461SK

Description	Amount (S\$)
PARTICULARS	
Vehicle Registration No. : GBD 7127C	400.00
Date of Accident : 16/11/2017	
Date of Inspection : 17/11/2017	
SERVICES:	
Assessment with report (inclusive of transport charges and photographs etc)	
Total	400.00
Balance Due	400.00

We would appreciate your cheque crossed and made payable to:
S K AUTO CONSULTANTS


Authorized Signature

S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/017/0461SK
Your Reference: TBA

Date: 28/12/2017

TO: Vois Pte Ltd
C/o ACE Autolution Pte Ltd
13 Kaki Bukit Road 4 #03-29
Bartley Biz Centre
Singapore 417807

Assessment of Vehicle No : GBD 7127C
Date of Accident : 16/11/2017
Date of Inspection : 17/11/2017

We have carried out a physical assessment of GBD 7127C at ACE Autolution Pte Ltd according to your instructions on 17/11/2017 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	GBD 7127C
Make & Model	:	Toyota Hiace Van Turbo
Year of Registration	:	2015
Engine Capacity (cc)	:	2982 cc
Chassis No.	:	JTFHT02P300155427
Engine No.	:	1KD2467388
Colour	:	White
Mileage (km)	:	118770

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	Yokohama 195R15C - 80%
LH Make/Size	:	Yokohama 195R15C - 80%

Rear

RH Make/Size	:	Yokohama 195R15C - 80%
LH Make/Size	:	Yokohama 195R15C - 80%

Note: % denotes the remaining percentage of the tyre

S K AUTO CONSULTANTS


Page No. 2

Our Reference TP/017/0461SK
Vehicle No. GBD 7127C

4.DESCRPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Rear portion

Please see attached schedule for details.



Estimated Amount : S\$10,055.15
Adjusted Amount : S\$7,400/-
Estimated Repair Days : 7 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 Days** from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **S K AUTO CONSULTANTS** for any reliance on this report by any third party.

Page No. 3

Vehicle No. GBD 7127C

57.5

S K AUTO CONSULTANTS

Page No. 4



Our Reference TP/017/0461SK
Vehicle No. GBD 7127C

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)	
	LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	1200.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	800.00	400
3	To remove, refix wiring system at accident damaged areas and check for proper function	150.00	120.00	30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00	120.00	60
5	To remove and refix rear windscreen	140.00	120.00	100
6	To remove and replace reverse sensors and test for proper function	100.00	80.00	40
7	To perform anti-rust treatment on affected areas	150.00	120.00	60
	Labour Total :	3090.00	2560.00	1090
	TOTAL (PARTS & LABOUR):	10055.15	9265.15	

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lump Sum contract amount is S\$7,400/-



 S. Kumanan
 Motor Surveyor

4125.75
20%: 3300

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2017		20 Nov 2017 15:05 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SYSTEM TECHNIC ENGINEERING PTE LTD, Co. Reg. No.: -		
Main Claimant:	VOIS PTE LTD, Co. Reg. No.: 200505930G		
Vehicle Reg. No.:	GBD7127C	Date of Loss:	16/11/2017 07:00 - :59
Claim Type:	TP / 537032	Policy/Cover Note No.:	B28625557MKC (Comprehensive) Coverage: 04/11/2017 - 03/11/2018
Vehicle Reg. No. (Insured):	GBD4674J	Policy No. (Claimant):	
		Excess:	
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 07/02/2018]		
Driver/Custodian (Insured):	TEO WEE CHONG (), NRIC: S7507422J		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- MSIG_SG (05/02/2018): Report Send Back Alerts - GBD7127C (TP)

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD7127C (537032)**
[GBD4674J]
TP
VOIS PTE LTD
Nov 16 2017 7:00AM
[SYSTEM TECHNIC ENGINEERING PTE LTD]
Ace Autolution

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

[View](#) [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/11/17 14:27	Accident Statement From: SC - Reg. No: GBD4674J, Claimant: SYSTEM TECHNIC ENGINEERING PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 18:04	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/01/18 18:04	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
5	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/01/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
23	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
24	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
25	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
26	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
27	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
28	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
29	31/01/18 18:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▾		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/11/17 14:24	TP PRI		Load PDF	
2	20/11/17 14:27	E-FILE REPORT (SKM5818B) From:SC - Reg. No: GBD4674J, Claimant: SYSTEM TECHNIC ENGINEERING PTE LTD		Load PDF	
3	20/11/17 14:37	E-FILE REPORT (GBD7127C) From:SC - Reg. No: GBD4674J, Claimant: SYSTEM TECHNIC ENGINEERING PTE LTD		Load PDF	
4	20/11/17 14:54	OUR REJECTION REPLY & NOMINATED LKK TO BE OUR SJE		Load PDF	
5	25/01/18 10:24	re-inspection date confirmed		Load PDF	
6	29/01/18 13:50	TP LOD & DOCS		Load PDF	
7	29/01/18 13:50	FINAL BILL		Load PDF	
8	29/01/18 13:50	TP SURVEY REPORT		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 08:18	Invoice		Load PDF	
2	01/03/18 08:38	PHOTO		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17022159/GRBE2-1
Date: 01/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** B28625557MKC
Claimant Vehicle No : GBD7127C **Insured Vehicle No :** GBD4674J
Date of Loss: 16/11/2017 **Nature of Claim:** TP **Claim No:** 537032

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD7127C
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) **Engine No:** 1KD2467388
Reg. Date: 30/03/2015 (Man. Year: 2014) **Chassis No:** JTFHT02P300155427
Colour: White **Odometer:** 127469 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195 R15 **Rear Tyre Size:** 195 R15
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,965.15	3,553.25	3,411.90	48.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,090.00	2,000.00	64.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,055.15	4,643.25	5,411.90	53.82
Approved Total (Overridden) (\$\$)		3,700.00		
Nett Amount (\$\$)	10,055.15	3,700.00	6,355.15	63.20

INSPECTION

Date of Assignment: 20/11/2017
Date Inspected: 06/02/2018 **Inspected At:** Ace Autolution (HQ)
13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre
Singapore 417807
Estimated Period of Repair: 5.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2018)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7127C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Replaced	2,250.00 FL	*1,969.30 FL
2	1		*TAILGATE CENTRE GARNISH	Replaced	278.00 FL	*278.00 FL
3	1		*TAILGATE TOYOTA LOGO (BADGE)	Replaced	82.40 FL	*45.90 FL
4	1		*TAILGATE LOCK	Replaced	387.40 FL	*387.40 FL
5	2		*TAILGATE DAMPERS	Not Necessary	645.40 FL	*- FL
6	1		*TAIL LAMP LHS	Replaced	978.00 FL	*303.10 FL
7	1		*TAIL LAMP LOWER PANEL LHS	Not Necessary	232.00 FL	*- FL
8	1		*REAR BUMPER	Replaced	1,150.00 FL	*599.30 FL
9	1		*TAILGATE GLASS MOULDING	Replaced	192.00 FL	*110.00 FL
10	1		*RHS LOWER CORNER PANEL	Repaired	325.00 FL	*- FL
11	1		*REAR END PANEL	Repaired	982.00 FL	*- FL
12	1		*BOOT WEATHERSTRIP	Replaced	278.00 FL	*278.00 FL
13	1		*TOYOTA STICKER	Replaced	40.00 FS	*30.00 FS
14	1		*HIACE STICKER	Replaced	40.00 FS	*30.00 FS
15	1		*70KM/HR STICKER	Replaced	30.00 FS	*10.00 FS
16	1		*COMPANY ADVERT STICKER (COMPLETE)	Replaced	450.00 FS	*200.00 FS
17	1		*SET REAR BUMPER CLIPS	Replaced	40.00 FS	*40.00 FS
18	1		*REVERSE PARKING SENSORS	Replaced	280.00 FS	*200.00 FS
19	1		*REAR WINDSCREEN SEALANT	Replaced	100.00 FS	*50.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
21	1		*REAR LICENCE PLATE	Replaced	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,910.20	4,546.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,945.05	992.75
Total Parts (\$\$)	6,965.15	3,553.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	400.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	400.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO REMOVE / REFIX INNER TRIMS, FITTINGS, GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	150.00	60.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	100.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION	New	100.00	40.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (S\$)			3,090.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >