

ASS. REC. BY

REF

CS/CTI18002298/Grd3e2

Surveyor:

Merimen

ASSIGNMENT (Office)

Frgt. (Person):

Chong Soon Sen

of

CTI

Date/Time:

5/2/2018 @ 3:08pm

Estimate Cost:

Bill to:

(O.D.)

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 9284L

Insured:

at Workshop t/s:

Chip Soon Auto

Tel:

96346654

of

Blk 9002 #01-74 Tampines Street 93

Policy No:

DMPCSN3011271804

Claim No:

SNM18D00412C01

Sum Insured:

Excess:

\$750.00

Make of Veh:

(Client's Record)

D.O.A.

21/01/2018

CA / REV

REP. / REV 24 HRS

6/2/18

Date/Time:

5:27pm @ 6/2/18

Person Contacted:

Daniel

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 9284L - CS/CTI18001519/Rlvbe2

D.O.A. 21/01/18

7/2/18

Sent preli thru merimen ; seek mandate

8/2/18

Authorise repair ; Inform Daniel to proceed repair and excess

Confirm

\$18,459.21 @ 8 days (Pd. \$5641.79, 23%).

Subject

Xcel.

REF. CTI

5819C

## ASSIGNMENT

File No.

Date 6/2/18

Estimate Cost

① TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No

SKD9284L

at Workshop no

Chip soon Auto

of 81k9002# 01-74 Tampines st. 93

Insured

Policy No.

Claims No.

Sum Insured

Excess

\$750.00


(Client's Record)

Daniel @ 963 + 6654

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

\$85K. 88K

ICAD Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repair

days

Res.

Yes or No

Lump Sum

%

3 Val.

Yes or No

CA / (REV) / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time Action / Instruction

Ver No

SKD9284L

Page 19 Jan 2012

Type M/Cycle Bus/ Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make

Merce E250 1796

Colour

Blue

AC Insured Std / NI / NA

So Reasoning

B2564

T Radio Insured Std / NI / NA

Eng No

C No

WDD 2120 472 A 53 9922

Gen. Cond Good / Fair / Poor / Burnt

Steering Inboard / Jammed / Leaked / Burnt or

Brake Inboard / Jammed / Leaked / Burnt or

Mod. Nil / S/Rim / STD A/Rim or

Tyre Size

F: 245/40ZR18

R: 11

BS / DUN / EXNOVA / GY / PS / LIZA / MIN / QHTEU / PIR / SUM

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D/OA

D/OA

06-02-18

Survey held at

w/s

4pm

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rocked or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to

typist



Prel. Report



Final Report

Date/Time File Return to

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee

220

Date/Time File Return to

Add Fee:



Site Insp

\$



Interview

\$



Tech. Insp

\$



Witnessing

\$

Report Format

00

Lump Sum / I.B. / S

18459.21

220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CT18002298/Grd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 06-02-2018		
		Code : CTI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	SKD 9284L	
Policy No.	DMPCSN3011271804	Coverage (\$)	0.00	
Claim No.	SNM18D00412C01	Excess (\$)	750.00	
Assign From	MERIMEN (CHING BOON SEN)	Assign Date	06/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	21/01/2018	Inspection Date	06/02/2018	
Survey held at	CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 15:08 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POON WAI MUN, ID: S1705819C		
Vehicle Reg. No.:	SKD9284L	Date of Loss:	21/01/2018 09:00 - :59
Claim Type:	OD / SNM18D00412C01	Policy/Cover Note No.:	DMPCSN3011271804 (Comprehensive)
		Excess:	S\$750.00
Repairer:	Chip Soon Auto Supply Co Pte Ltd (HQ) BLOCK 9002 #01-74 TAMPINES STREET 93, TAMPINES INDUSTRIAL PARK A, 528836 Tampines - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/02/2018]		
Driver/Custodian:	SUTINI (49 / Female), NRIC: S6876302I, Tel: +6590301340		
Adj Asg. Remarks:	SURVEY REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Chong Boon Sen

---

**From:** danielseow@chipsoonauto.com.sg  
**Sent:** Monday, 5 February, 2018 9:52 AM  
**To:** Chong Boon Sen  
**Subject:** Fwd: Motor Accident Claim - SKD9284L  
**Attachments:** Accident Report - SKD9284L Mercedes Benz E250.pdf; Quotation - SKD9284L.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

----- Original Message -----

Subject: Motor Accident Claim - SKD9284L  
Date: 2018-02-02 12:12  
From: danielseow@chipsoonauto.com.sg  
To: e-claims@sg.cntaiping.com

Dear Sir,

We are instructed by policy holder (Policy number DMPCSN3011271804), Mr Poon Wai Mun to carry out Own Damage Claim for his vehicle SKD9284L, Mercedes Benz E250.

Please contact Daniel to arrange for the vehicle inspection at 96346654 (Mobile) or 67862811 (Company Tel)

Please kindly find the accident report and quotation attached.

Regards

Daniel Seow  
Technical Adviser

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 07 Feb 2018

**Preliminary Advice**

Vehicle No	: SKD9284L	Accident Date	: 21/01/2018
Make	: MERCEDES-BENZ E250	Policy No.	: DMPCSN3011271804
Assignment Date	: 05/02/2018	Excess	: S\$750.00
Date of Inspection	: 06/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: CHIP SOON AUTO SUPPLY CO PTE LTD (HQ) BLOCK 9002 #01-74 TAMPINES STREET 93, TAMPINES INDUSTRIAL PARK A SINGAPORE 528836		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,451.00
Revised Amount	:S\$	13,902.00
Check Items (Estimated)	:S\$	6,099.00
Total	:S\$	20,001.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	61,107.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,893.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Print Received Message

This mail is associated with :

**\*SKD9284L (SNM18D00412C01)**

OD

Jan 21 2018 9:00AM

[POON WAI MUN]

Chip Soon Auto Supply Co Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 08/02/2018 11:38 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$20001.00) - SKD9284L - Claim Handler: Chong Boon Sen

Approved:20001.00:Please proceed to authorize repairs UP TO \$20,001.00 BEFORE Excess of \$750.00.  
RE-INSPECTION of vehicle required.

## Janice Lee (LKKAUTO)

**From:** Janice Lee (LKKAUTO)  
**Sent:** Thursday, February 08, 2018 12:37 PM  
**To:** 'danielseow22@gmail.com'  
**Subject:** RE: SKD 9284L OD CTI DOA: 21.01.2018

Hi Daniel,

Resent.

\*kindly acknowledge if you have receive this email.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Thursday, February 08, 2018 12:34 PM  
**To:** 'danielseow2022@gmail.com' <danielseow2022@gmail.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** SKD 9284L OD CTI DOA: 21.01.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKD 9284L (excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/01/2018 19:47
Date Of Accident	21/01/2018 09:10
Exact Location Of Accident	TRAFFIC JUNCTION PUNGGOL WAY / SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD9284L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	POON WAI MUN
NRIC No	S1705819C
Email Address	JPAN28X3@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97265048
Alternative Phone No	OTHERS-97265048

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3011271804
Cover Note Number	

### Driver

Name of Driver	SUTINI
NRIC No	S6876302I
Date Of Birth	07/11/1968
Occupation	INDOOR
Date Of Driving Pass	19/11/2007
Driving Experience	10 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90301340
Fax Number	
Contact Number	
EMail Address	KTMEOW@HOTMAIL.COM

Address	112 PUNGGOL WALK #17-26
Postcode	828766
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG9775X
Vehicle Make/Model/Colour	BMW WHITE COLOUR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HO CHEE WEN
NRIC/Passport Number	
Contact Number	81009972
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On this day, 21st Jan 2018 (Sunday). about 09:10 am.

I was travelling from punggol way toward Sengkang E. road

I was near traffic light, the light was still amber. then


I proceed to drive toward Sengkang E. road


Suddenly there was vehicle turning from my right to left and there is an impact at my left side of my car


After impact, we alight and start to take photos and exchange particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  2:30 pm  
Date & Time:

Driver's Signature   
(If driver is not the policyholder)  
Date & Time: 22/1/2018  
2:30 pm

Reporting Centre Personnel's Signature   
Name:  
NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5819C
Vehicle Details	
Vehicle No.:	SKD9284L
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	27186030373584
Chassis No.:	WDD2120472A539922
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,036.00
Original Registration Date:	19 Jan 2012
First Registration Date:	19 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$54,036.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2022
PARF Rebate Amount:	\$35,123.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$65,801.00
COE Rebate Amount:	\$25,984.00
<b>Total Rebate Amount:</b>	<b>\$61,107.00</b>

The information contained herein is correct as at 06 Feb 2018

OK

[Mercedes-Benz e250 Used Vehicle List \(20 vehicles\)](#)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Mercedes-Benz E-Class E250 CGI Coupe</b>	<b>\$99,000</b>	<b>\$18,140 /yr</b>	<b>12-Jan-2012</b>	<b>1,796 cc</b>	<b>119,000 km</b>	<b>Bavarian Marques Pte Ltd</b>	<b>Available</b>
C&C Unit. Upgrades Include Carlsson Exhaust, Remote Start, Upgraded Grille, 19" Wheels, Scuff Plate, Low Mileage Done. 20% Down Payment Drive Away, Trade In Welcome. Evaluation Welcome. Contact Us For...							
Office No. - 68162642 Michael - 97548879   Shawn - 88188544							
<b>Mercedes-Benz E-Class E250</b>	<b>\$83,800</b>	<b>\$14,390 /yr</b>	<b>18-Jan-2012</b>	<b>1,796 cc</b>	<b>-</b>	<b>Igua Motoring</b>	<b>Available</b>
7G-Tronic, Excellent Condition! Original Paintwork With Clean And Neat Interior, 100% Loan Approval With Our Flexible In House Financing Options, All Enquiries Are Welcome Thru Call Or WhatsApp!							
Office No. - 63839000 Wilson - 98520694   Roy - 86499000							
<b>Mercedes-Benz E-Class E250 Avantgarde</b>	<b>\$91,800</b>	<b>\$16,260 /yr</b>	<b>18-Jan-2012</b>	<b>1,796 cc</b>	<b>-</b>	<b>Cars Traditon Pte Ltd</b>	<b>Available</b>
Only 1 Owner! Beautiful Brown With Beige Interior. High OMV \$55,277 Guaranteed Lowest Price And Best Condition In Market. Free 12 Months Warranty Package! Free Car Servicing! Free Car Spa Polish Packa...							
Office No. - 63527288 / 63528525 Aaron - 85114988   Plus - 84995988							
<b>Mercedes-Benz E-Class E250</b>	<b>\$90,800</b>	<b>\$16,160 /yr</b>	<b>19-Jan-2012</b>	<b>1,796 cc</b>	<b>127,000 km</b>	<b>Igua Motoring</b>	<b>Available</b>
Well Maintained By 1 Careful Owner, 7G-Tronic, Excellent Condition! Original Paintwork With Clean And Neat Interior, 100% Loan Approval With Our Flexible In House Financing Options, All Enquiries Are ...							
Office No. - 63839000 Roy - 86499000   Wilson - 98520694							
<b>Mercedes-Benz E-Class E250</b>	<b>\$93,800</b>	<b>\$16,530 /yr</b>	<b>22-Feb-2012</b>	<b>1,796 cc</b>	<b>126,000 km</b>	<b>BW Automobiles</b>	<b>Available</b>
Look No Further! C&C Unit With Very High OMV Of \$54,036, New Road Tax, Zero Mishap, Fully Serviced By C&C, Pristine Interior Condition. Accident Free, View To Believe, Attractive Trade In And Financin...							
Office No. - 62828800 Desmond Lee - 93622220							
<b>Mercedes-Benz E-Class E250</b>	<b>\$97,800</b>	<b>\$17,060 /yr</b>	<b>28-Feb-2012</b>	<b>1,796 cc</b>	<b>113,000 km</b>	<b>Atlantic Automobile Pte Ltd</b>	<b>Available</b>
At Atlantis All Our Cars Have Fully Diagnosed, Repair And Replace Before Put On Sales And Come With 6 Month Warranty Highest Trade In Value For Used Car, Fast And Hassle Free Transaction. Immediate De...							
Office No. - 69098118 William Ng - 83186606   Derrick Ng - 81880050							
<b>Mercedes-Benz E-Class E250 CGI Avantgarde</b>	<b>\$98,500</b>	<b>\$17,050 /yr</b>	<b>05-Apr-2012</b>	<b>1,796 cc</b>	<b>88,000 km</b>	<b>Privilege Motors Pte Ltd</b>	<b>Available</b>
C&C Maintained, CNY Promo, Only 1.98% Interest! No Advance Installment! Down Payment \$10,850, Monthly At \$1,780. Very Well Kept! Accident Free! Cheapest In Town! Peace Of Mind! Highest Trade In And Hig...							
Office No. - 64631155 Ben - 88211155   Desmond Ang - 83821155							
<b>Mercedes-Benz E-Class E250 CGI Avantgarde</b>	<b>\$89,800</b>	<b>\$15,920 /yr</b>	<b>23-Apr-2012</b>	<b>1,796 cc</b>	<b>-</b>	<b>Leco Auto Pte Ltd</b>	<b>Available</b>
Almost Sold! The Cheapest Unit In The Market! 100% Top Notch Condition As It Is A One Owner Unit. 100% Accident Free With Low Mileage Done. If You Are Looking To Buy A E250, This Is The Unit You Must ...							
Office No. - 68410020 / 68460020 Eason - 90096473   Edmund - 81611022   Mike - 93855385							
<b>Mercedes-Benz E-Class E250 Cabriolet</b>	<b>\$109,888</b>	<b>\$19,370 /yr</b>	<b>26-Apr-2012</b>	<b>1,796 cc</b>	<b>69,849 km</b>	<b>ST Auto Pte Ltd</b>	<b>Available</b>
1 Owner! Well Maintain With A Reputable Workshop. Lowest Mileage. 100% Accident Free. Immaculate Condition. Come View To Believe.							
Office No. - 64649098/64647110 Harry Tan - 90674496   Kenny Him - 96411167   Andy Lee - 96867441   Agnes Tan - 97240235							
<b>Mercedes-Benz E-Class E250 Avantgarde</b>	<b>\$102,888</b>	<b>\$17,810 /yr</b>	<b>30-Apr-2012</b>	<b>1,796 cc</b>	<b>105,000 km</b>	<b>Monster Motors Pte Ltd</b>	<b>Available</b>
Excellent Condition, 100% Accident Free And Well Maintained. Black Interior Upholstery, Easy To Maintain, Viewings And Test Drives Are Strictly By Appointment Only. Up To 90% Loan And Trade In Availab...							
Office No. - 69090035 Charles - 83079361   Allister - 97586431							
<b>Mercedes-Benz E-Class E250 CGI</b>	<b>\$101,500</b>	<b>\$17,540 /yr</b>	<b>08-May-2012</b>	<b>1,796 cc</b>	<b>-</b>	<b>Privilege Motors Pte Ltd</b>	<b>Available</b>

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
Contact No. :  
Vehicle No. : SKD9284L  
Vehicle Model : MERCEDES BENZ E250  
Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
Mileage : 132,564  
Page : 1 of 3  
Terms :

Cost plus.

No.	Description of Goods / Services	QTY	Unit Price	Amount
<b>Parts</b>				
1	FRONT GRILLE / CFA	1.00	PCS 930.00	930.00
2	BADGE, FRONT GRILLE / MC	1.00	PCS 43.00	43.00
3	SUPPORT, FRONT GRILLE / A/S	1.00	PCS 19.00	19.00
4	ENGINE HOOD / BUC	1.00	PCS 2,030.00	2,030.00
5	BONNET STAR, ENGINE HOOD / MC	1.00	PCS 79.00	79.00
6	SPRING ELEMENT, ENGINE HOOD / OM	2.00	PCS 34.00	68.00
7	SAFETY HOOK, ENGINE HOOD / BT	1.00	PCS 74.00	74.00
8	ACTUATOR ENGINE HOOD, RH / Act	1.00	PCS 380.00	380.00
9	ACTUATOR ENGINE HOOD, LH / Act	1.00	PCS 380.00	380.00
10	PARKTRONIC SENSORS, FRONT / OM	6.00	PCS 208.00	1,248.00
11	FRONT BUMPER / Act	1.00	PCS 1,250.00	1,250.00
12	CHROME, FRONT BUMPER, RH / Re	1.00	PCS 86.00	86.00
13	CHROME, FRONT BUMPER, LH / Re	1.00	PCS 86.00	86.00
14	BUMPER SUPPORT / X NN	1.00	PCS 77.00	77.00
15	GRILLE, FRONT BUMPER / Re	1.00	PCS 75.00	75.00
16	DAYLIGHT COVER, RH / X NN	1.00	PCS 53.00	53.00
17	DAYLIGHT COVER, LH / Re	1.00	PCS 53.00	53.00
18	DAYLIGHT RUNNING LAMP, RH / X NN	1.00	PCS 131.00	131.00
19	DAYLIGHT RUNNING LAMP, LH / X NN	1.00	PCS 131.00	131.00
20	NUMBER PLATE MOULDING / CFA	1.00	PCS 182.00	182.00
21	NUMBER PLATE WITH FRAME / CFA	1.00	PCS 40.00	40.00
22	IMPACT ABSORBER, CENTRAL / Re	1.00	PCS 110.00	110.00
23	FENDER, FRONT LH / TV	1.00	PCS 1,120.00	1,120.00
24	WHEEL ARC COVER, FRONT LH / Re	1.00	PCS 205.00	205.00
25	PLASTIC CLIPS, WHEEL ARC COVER / MC	8.00	PCS 3.00	24.00
26	HEADLAMP ASSEMBLY, RH / CFA	1.00	PCS 920.00	920.00

The above repairs have been carried out according to the owner request.  
All parts changed are warranty for 6 months.  
The owner acknowledge the amount of repairs which has been agreed upon.  
Any dispute to the invoice must be lodged within 7 days from the date of invoice.  
We will not responsible for any damage not related to the above repair.

**LOK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey shall be without prejudice basis
- No illegal modification is allowed
- Supplementary survey must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***  
**Thank You For Your Patronage**



**Customer Name** : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
**Contact No.** :  
**Vehicle No.** : SKD9284L  
**Vehicle Model** : MERCEDES BENZ E250  
**Chassis No.** : WDD2120472A539922

**Quotation No.** : Q000013  
**Mileage** : 132,564  
**Page** : 2 of 3  
**Terms** :

No.	Description of Goods / Services	QTY	Unit Price	Amount
27	HEADLAMP ASSEMBLY, LH - CAA	1.00 PCS	920.00	874 920.00 ✓
28	CROSS MEMBER, FRONT - BT	1.00 PCS	522.00	495.9 522.00 ✓
29	SUPPORT, CROSS MEMBER, LH - BT	1.00 PCS	285.00	230.75 285.00 ✓
30	SUPPORT PANEL, FRONT CENTRE - BT	1.00 PCS	142.00	134.9 142.00 ✓
31	SUPPORT PANEL, FRONT LH - BT	1.00 PCS	250.00	237.5 250.00 ✓
32	ENGINE HOOD STRIKER - NN	1.00 PCS	44.00	44.00 ?
33	SUPPORT BRACKET, LH - BT	1.00 PCS	53.00	50.45 53.00 ✓
34	AIRCON CONDENSER - BT	1.00 PCS	1,170.00	1111.50 1,170.00 ? ✓
35	AIRCON REFRIGERANT GAS - MC	1.00 PCS	25.00	22.75 25.00 ✓
36	RADIATOR ASSEMBLY - BT	1.00 PCS	875.00	831.25 875.00 ? ✓
37	COOLANT - MERCEDES BENZ - MC	2.00 BOTTLES	24.00	45.60 48.00 ✓
38	RADIATOR FAN ASSEMBLY - CAA	1.00 PCS	905.00	859.75 905.00 ? ✓
39	TURBOCHARGER INTERCOOLER - Cut	1.00 PCS	1,080.00	1026.00 1,080.00 ? ✓
40	ENGINE BOTTOM COVER, FRONT - CAA	1.00 PCS	241.00	228.95 241.00 ✓
41	PLASTIC CLIPS, BOTTOM COVER - MC	12.00 PCS	3.50	39.60 42.00 ✓
42	BRACKET, ENGINE BOTTOM COVER, LH - BT	1.00 PCS	42.00	39.90 42.00 ? ✓
43	FAN SHROUD, RADIATOR - CAA	1.00 PCS	105.00	99.75 105.00 ? ✓
44	IMPACT SENSOR, FRONT BUMPER - MC	1.00 PCS	110.00	110.00 ✓
45	PARKTRONIC WIRE HARNESS - NN	1.00 PCS	228.00	228.00 ?
<b>Labour</b>				
1	LABOUR CHARGES	1.00 SERVICE	2,200.00	2,200.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD SUPPORT PANEL, TO KNOCK, RESHAPE AND ADJUST DAMAGED CHASSIS FRAME AND PANELS			1000 ✓
2	LABOUR CHARGES	1.00 SERVICE	1,800.00	1,800.00
	SPRAY PAINTING CHARGES TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER, WHEEL HOUSE AND AFFECTED AREAS			1200 ✓

The above repairs have been carried out according to the owner request.  
 All parts changed are warranty for 6 months.  
 The owner acknowledge the amount of repairs which has been agreed upon.  
 Any dispute to the invoice must be lodged within 7 days from the date of invoice.  
 We will not responsible for any damage not related to the above repair.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modifications are allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
**Signature:**  
**Date:**

**Opening Hours:** Monday - Saturday : 9.00am - 6.30pm  
 Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
 For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***  
**Thank You For Your Patronage**



Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
Contact No. :  
Vehicle No. : SKD9284L  
Vehicle Model : MERCEDES BENZ E250  
Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
Mileage : 132,564  
Page : 3 of 3  
Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
3	LABOUR CHARGES RENEW RADIATOR, AIRCON CONDENSER, TURBOCHARGER INTERCOOLER, PARKTRONIC SENSORS, HEADLAMP ASSEMBLIES, BONNET ACTUATORS AND RELATED ITEMS	1.00 SERVICE	1,650.00	1,650.00 200
4	LABOUR AND DIAGNOSIS CHARGES CARRY OUT DIAGNOSIS TEST CHECK PARKTRONIC SENSORS ELECTRIC CIRCUIT CARRY OUR PROGRAMMING AND CODING FOR HEADLAMP ASSEMBLIES RESET BONNET ACTUATORS READ AND ERASE FAULT MEMORY	1.00 SERVICE	800.00	800.00 808
5	TOWING SERVICE	1.00 SERVICE	120.00	120.00 8 120.00

8 Days.  
part by part.  
before paint photos.  
After paint photos.  
Guo Qiang - 82880282  
Guo Qiang @ LKK Auto. Com  
06/2/18.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before after estimating
- To display damaged parts clearly
- Parts prices are subject to market
- Third party claims are on "Rejudice" basis
- All claims are subject to LKK Auto. Com
- Suppliers are subject to LKK Auto. Com and is subject to LKK Auto. Com Insurance Company

Acknowledged by repairer

Signature:

Date:

**Twenty Five Thousand Ninety Two and Cents Fifty Seven Only**

The above repairs have been carried out according to the owner request.  
All parts changed are warranty for 6 months.  
The owner acknowledge the amount of repairs which has been agreed upon  
Any dispute to the invoice must be lodged within 7 days from the date of invoice  
We will not responsible for any damage not related to the above repair

Nett	23,451.00
Discount	0.00
7% GST	1,641.57
<b>Total Due</b>	<b>25,092.57</b>

Authorised Signature(s)

Received by

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
Sunday & Public Holidays : Closed  
24 hours breakdown towing service, please call : 9720 3785  
For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***  
**Thank You For Your Patronage**

# Additional items

Impact Absorber, Bumper, LH. 212 885 0537 ✓	\$621	BT	58.90
Bumper inner panel, centre ✓	\$75	RL	71.25
Top Panel ✓	\$130	BT	123.50
Air Duct, intercooler ✓	\$135	CRA	28.25
Bumper Mounting, LH ✓	\$48	CRA	45.60
Outside Temperature sensor - 0075421218 ✓	\$70	PM	
<del>Light</del> Daylight Chime LH ✓	\$130	BR	123.50

\$650

16867

-5%: 16023.65

24ac

18423.65

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Contact No. :  
 Vehicle No. : SKD9284L  
 Vehicle Model : MERCEDES BENZ E250  
 Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
 Mileage : 132,564  
 Page : 1 of 3  
 Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
<b>Parts</b>				
1	FRONT GRILLE / CFA	1.00 PCS	930.00	930.00
2	BADGE, FRONT GRILLE / MC	1.00 PCS	43.00	43.00
3	SUPPORT, FRONT GRILLE / MC	1.00 PCS	19.00	19.00
4	ENGINE HOOD / MC	1.00 PCS	2,030.00	2,030.00
5	BONNET STAR, ENGINE HOOD / MC	1.00 PCS	79.00	79.00
6	SPRING ELEMENT, ENGINE HOOD / MC	2.00 PCS	34.00	68.00
7	SAFETY HOOK, ENGINE HOOD / MC	1.00 PCS	74.00	74.00
8	ACTUATOR ENGINE HOOD, RH / MC	1.00 PCS	380.00	380.00
9	ACTUATOR ENGINE HOOD, LH / MC	1.00 PCS	380.00	380.00
10	PARKTRONIC SENSORS, FRONT / MC	6.00 PCS	208.00	1,248.00
11	FRONT BUMPER / MC	1.00 PCS	1,250.00	1,250.00
12	CHROME, FRONT BUMPER, RH / MC	1.00 PCS	86.00	86.00
13	CHROME, FRONT BUMPER, LH / MC	1.00 PCS	86.00	86.00
14	BUMPER SUPPORT / MC	1.00 PCS	77.00	77.00
15	GRILLE, FRONT BUMPER / MC	1.00 PCS	75.00	75.00
16	DAYLIGHT COVER, RH / MC	1.00 PCS	53.00	53.00
17	DAYLIGHT COVER, LH / MC	1.00 PCS	53.00	53.00
18	DAYLIGHT RUNNING LAMP, RH / MC	1.00 PCS	131.00	131.00
19	DAYLIGHT RUNNING LAMP, LH / MC	1.00 PCS	131.00	131.00
20	NUMBER PLATE MOULDING / MC	1.00 PCS	182.00	182.00
21	NUMBER PLATE WITH FRAME / MC	1.00 PCS	40.00	40.00
22	IMPACT ABSORBER, CENTRAL / MC	1.00 PCS	110.00	110.00
23	FENDER, FRONT LH / MC	1.00 PCS	1,120.00	1,120.00
24	WHEEL ARC COVER, FRONT LH / MC	1.00 PCS	205.00	205.00
25	PLASTIC CLIPS, WHEEL ARC COVER / MC	8.00 PCS	3.00	24.00
26	HEADLAMP ASSEMBLY, RH / MC	1.00 PCS	920.00	920.00

The above repairs have been carried out according to the owner request.  
 All parts changed are warranty for 6 months.  
 The owner acknowledge the amount of repairs which has been agreed upon.  
 Any dispute to the invoice must be lodged within 7 days from the date of invoice.  
 We will not responsible for any damage not related to the above repair.

**Chip Soon Auto Supply Co. Pte Ltd hereby**  
**the Repaired of the following:**  
 • To survey before/after spray painting  
 • To display damaged part during survey  
 • Parts prices are subject to confirmation  
 • Third party survey shall be on "without prejudice" basis  
 • No illegal modification is allowed  
 • Supplementary work must be surveyed and approved by Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
 Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
 For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***

**Thank You For Your Patronage**

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
Contact No. :  
Vehicle No. : SKD9284L  
Vehicle Model : MERCEDES BENZ E250  
Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
Mileage : 132,564  
Page : 2 of 3  
Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
27	HEADLAMP ASSEMBLY, LH - <i>CHAS.</i>	1.00 PCS	920.00	920.00
28	CROSS MEMBER, FRONT - <i>BT.</i>	1.00 PCS	522.00	522.00
29	SUPPORT, CROSS MEMBER, LH - <i>BT.</i>	1.00 PCS	285.00	285.00
30	SUPPORT PANEL, FRONT CENTRE - <i>BT.</i>	1.00 PCS	142.00	142.00
31	SUPPORT PANEL, FRONT LH - <i>BT.</i>	1.00 PCS	250.00	250.00
32	ENGINE HOOD STRIKER - <i>BT.</i>	1.00 PCS	44.00	44.00
33	SUPPORT BRACKET, LH - <i>BT.</i>	1.00 PCS	53.00	53.00
34	AIRCON CONDENSER - <i>BT.</i>	1.00 PCS	1,170.00	1,170.00
35	AIRCON REFRIGERANT GAS - <i>BT.</i>	1.00 PCS	25.00	25.00
36	RADIATOR ASSEMBLY - <i>BT.</i>	1.00 PCS	875.00	875.00
37	COOLANT - MERCEDES BENZ - <i>BT.</i>	2.00 BOTTLES	24.00	48.00
38	RADIATOR FAN ASSEMBLY - <i>BT.</i>	1.00 PCS	905.00	905.00
39	TURBOCHARGER INTERCOOLER - <i>BT.</i>	1.00 PCS	1,080.00	1,080.00
40	ENGINE BOTTOM COVER, FRONT - <i>CPA</i>	1.00 PCS	241.00	241.00
41	PLASTIC CLIPS, BOTTOM COVER - <i>MC.</i>	12.00 PCS	3.50	42.00
42	BRACKET, ENGINE BOTTOM COVER, LH - <i>BT.</i>	1.00 PCS	42.00	42.00
43	FAN SHROUD, RADIATOR - <i>BT.</i>	1.00 PCS	105.00	105.00
44	IMPACT SENSOR, FRONT BUMPER - <i>DM.</i>	1.00 PCS	110.00	110.00
45	PARKTRONIC WIRE HARNESS - <i>X</i>	1.00 PCS	228.00	228.00
<b>Labour</b>				
1	LABOUR CHARGES	1.00 SERVICE	2,200.00	2,200.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD SUPPORT PANEL, TO KNOCK, RESHAPE AND ADJUST DAMAGED CHASSIS FRAME AND PANELS			1000.
2	LABOUR CHARGES	1.00 SERVICE	1,800.00	1,800.00
	SPRAY PAINTING CHARGES TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER, WHEEL HOUSE AND AFFECTED AREAS			1000.
<p>The above repairs have been carried out according to the owner request. All parts changed are warranty for 6 months. The owner acknowledge the amount of repairs which has been agreed upon Any dispute to the invoice must be lodged within 7 days from the date of invoice We will not responsible for any damage not related to the above repair</p>				
<p><b>UAT Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged parts during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on "Without Prejudice" basis</li> <li>No illegal modification is allowed</li> <li>Supplementary items must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>				

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***

**Thank You For Your Patronage**

GST Reg. No.: 201418006M

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
Contact No. :  
Vehicle No. : SKD9284L  
Vehicle Model : MERCEDES BENZ E250  
Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
Mileage : 132,564  
Page : 3 of 3  
Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
3	LABOUR CHARGES RENEW RADIATOR, AIRCON CONDENSER, TURBOCHARGER INTERCOOLER, PARKTRONIC SENSORS, HEADLAMP ASSEMBLIES, BONNET ACTUATORS AND RELATED ITEMS	1.00 SERVICE	1,650.00	1,650.00 200
4	LABOUR AND DIAGNOSIS CHARGES CARRY OUT DIAGNOSIS TEST CHECK PARKTRONIC SENSORS ELECTRIC CIRCUIT CARRY OUR PROGRAMMING AND CODING FOR HEADLAMP ASSEMBLIES RESET BONNET ACTUATORS READ AND ERASE FAULT MEMORY	1.00 SERVICE	800.00	800.00 ?
5	TOWING SERVICE	1.00 SERVICE	120.00	? 120.00

8 Days.

part by part.

before paint photos.

After paint photos.

Guo Qiang - 82880282

Guo Qiang @ IKK Auto. Com

06/2/18.

Remarks :

**IKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before and after mounting
- To display damaged parts
- Parts prices are on a "no-haggle" basis
- The cost of repairs is on a "no-haggle" basis
- No "hidden" charges allowed
- Supplemental claims are subject to insurance company approval

Acknowledged by repairer

Signature:

Date:

**Twenty Five Thousand Ninety Two and Cents Fifty Seven Only**

The above repairs have been carried out according to the owner request.  
All parts changed are warranty for 6 months.  
The owner acknowledge the amount of repairs which has been agreed upon  
Any dispute to the invoice must be lodged within 7 days from the date of invoice  
We will not responsible for any damage not related to the above repair

Nett	23,451.00
Discount	0.00
7% GST	1,641.57
<b>Total Due</b>	<b>25,092.57</b>

Authorised Signature(s)

Received by

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***

**Thank You For Your Patronage**



# PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)  
TEL NO : 64523938 (6 LINES) FAX NO : 64527936  
A/C DEPT : 64590882  
Business Reg & GST NO : 201512120M



D161338

REPRINT

## TAX INVOICE

CHIP SOON AUTO SUPPLY CO PTE LTD

BLK 9002 TAMPINES ST 93

#01-74 IND PARK A

(BEHIND SAFRA) SINGAPORE, 528838

REMARK

DELIVER TO

INV NO I161338

DATE 08/02/2018

A/C NO 334928

TERM 30

PAGE 1 OF 1

ISSUE WILLIAM

Printed on 08/02/2018 08:55:50

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AM
1	204 524 1340MB	UNDER COVER BRACKET LH	SS2G10	1	PC	23.00	23.00
2	204 500 5100MB	CHARGER AIR COOLER	SS2B16	1	PC	960.00	960.00

SK09284 L  
00124432

RECEIVED BY

PICKED BY: 8514

SUB-TOTAL : S\$ 983.00

ADD 7% GST : S\$ 68.81

TOTAL : S\$ 1051.81

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Contact No. : 9675 8875  
 Vehicle No. : SKD9284L  
 Vehicle Model : MERCEDES BENZ E250  
 Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
 Mileage : 132,564  
 Page : 1 of 3  
 Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
<b>Parts</b>				
1	FRONT GRILLE	1.00 PCS	883.50	883.50
2	BADGE, FRONT GRILLE	1.00 PCS	40.85	40.85
3	SUPPORT, FRONT GRILLE	1.00 PCS	18.05	18.05
4	ENGINE HOOD	1.00 PCS	1,928.50	1,928.50
5	BONNET STAR, ENGINE HOOD	1.00 PCS	75.05	75.05
6	SPRING ELEMENT, ENGINE HOOD	2.00 PCS	32.30	64.60
7	SAFETY HOOK, ENGINE HOOD	1.00 PCS	70.30	70.30
8	ACTUATOR ENGINE HOOD, RH	1.00 PCS	361.00	361.00
9	ACTUATOR ENGINE HOOD, LH	1.00 PCS	361.00	361.00
10	PARKTRONIC SENSORS, FRONT	6.00 PCS	197.60	1,185.60
11	FRONT BUMPER	1.00 PCS	1,187.50	1,187.50
12	CHROME, FRONT BUMPER, RH	1.00 PCS	81.70	81.70
13	CHROME, FRONT BUMPER, LH	1.00 PCS	81.70	81.70
14	GRILLE, FRONT BUMPER	1.00 PCS	71.25	71.25
15	DAYLIGHT COVER, LH	1.00 PCS	50.35	50.35
16	NUMBER PLATE MOULDING	1.00 PCS	172.90	172.90
17	NUMBER PLATE WITH FRAME	1.00 PCS	38.00	38.00
18	IMPACT ABSORBER, CENTRE	1.00 PCS	104.50	104.50
19	FENDER, FRONT LH	1.00 PCS	1,004.00	1,004.00
20	WHEEL ARC COVER, FRONT LH	1.00 PCS	194.75	194.75
21	PLASTIC CLIPS, WHEEL ARC COVER	8.00 PCS	2.85	22.80
22	HEADLAMP ASSEMBLY, RH	1.00 PCS	874.00	874.00
23	HEADLAMP ASSEMBLY, LH	1.00 PCS	874.00	874.00
24	CROSS MEMBER, FRONT	1.00 PCS	495.90	495.90
25	SUPPORT, CROSS MEMBER, LH	1.00 PCS	270.75	270.75
26	SUPPORT PANEL, FRONT CENTRE	1.00 PCS	134.90	134.90
27	SUPPORT PANEL, FRONT LH HEADLAMP	1.00 PCS	237.50	237.50
28	SUPPORT BRACKET STRUT, LH	1.00 PCS	50.35	50.35
29	AIRCON CONDENSER	1.00 PCS	1,111.50	1,111.50
30	AIRCON REFRIGERANT GAS	1.00 PCS	23.75	23.75

The above repairs have been carried out according to the owner request.  
 All parts changed are warranty for 6 months.  
 The owner acknowledge the amount of repairs which has been agreed upon.  
 Any dispute to the invoice must be lodged within 7 days from the date of invoice.  
 We will not responsible for any damage not related to the above repair.

Opening Hours: Monday - Saturday : 9.00am - 6.30pm

Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785

For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***

**Thank You For Your Patronage**



Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Contact No. : 9675 8875  
 Vehicle No. : SKD9284L  
 Vehicle Model : MERCEDES BENZ E250  
 Chassis No. : WDD2120472A539922

Quotation No. : Q000013  
 Mileage : 132,564  
 Page : 2 of 3  
 Terms :

No.	Description of Goods / Services	QTY	Unit Price	Amount
31	RADIATOR ASSEMBLY	1.00 PCS	831.25	831.25
32	COOLANT - MERCEDES BENZ	2.00 BOTTLES	22.80	45.60
33	RADIATOR FAN ASSEMBLY	1.00 PCS	859.75	859.75
34	TURBOCHARGER INTERCOOLER	1.00 PCS	1,026.00	1,026.00
35	ENGINE BOTTOM COVER, FRONT	1.00 PCS	228.95	228.95
36	PLASTIC CLIPS, BOTTOM COVER	12.00 PCS	3.33	39.96
37	BRACKET, ENGINE BOTTOM COVER, LH	1.00 PCS	39.90	39.90
38	FAN SHROUD, RADIATOR	1.00 PCS	99.75	99.75
39	IMPACT ABSORBER, LH	1.00 PCS	58.90	58.90
40	FRONT BUMPER INNER PANEL, CENTRE	1.00 PCS	71.25	71.25
41	TOP PANEL	1.00 PCS	123.50	123.50
42	AIR DUCT, INTERCOOLER	1.00 PCS	128.25	128.25
43	BUMPER MOUNTING, LH	1.00 PCS	45.60	45.60
44	OUTSIDE AIR TEMPERATURE SENSOR	1.00 PCS	66.50	66.50
45	DAYLIGHT CHROME, LH	1.00 PCS	123.50	123.50
<b>Labour</b>				
1	LABOUR CHARGES PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD SUPPORT PANEL, TO KNOCK, RESHAPE AND ADJUST DAMAGED CHASSIS FRAME AND PANELS	1.00 SERVICE	1,000.00	1,000.00
2	LABOUR CHARGES SPRAY PAINTING CHARGES TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT RIGHT AND LEFT FENDER, WHEEL HOUSE AND AFFECTED AREAS	1.00 SERVICE	1,200.00	1,200.00
3	LABOUR CHARGES RENEW RADIATOR ASSEMBLY, AIRCON CONDENSER, TURBOCHARGER INTERCOOLER, PARKTRONIC SENSORS, HEADLAMP ASSEMBLIES, BONNET ACTUATORS AND RELATED ITEMS	1.00 SERVICE	200.00	200.00
4	LABOUR AND DIAGNOSIS CHARGES CARRY OUT DIAGNOSIS TEST CHECK PARKTRONIC SENSORS ELECTRIC CIRCUIT RESET BONNET ACTUATORS READ AND ERASE FAULT MEMORY	1.00 SERVICE	80.00	80.00
The above repairs have been carried out according to the owner request. All parts changed are warranty for 6 months. The owner acknowledge the amount of repairs which has been agreed upon Any dispute to the invoice must be lodged within 7 days from the date of invoice We will not responsible for any damage not related to the above repair				

Opening Hours: Monday - Saturday : 9.00am - 6.30pm  
 Sunday & Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785  
 For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***

**Thank You For Your Patronage**



<b>Customer Name</b> :	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD	<b>Quotation No.</b> :	Q000013
<b>Contact No.</b> :	9675 8875	<b>Mileage</b> :	132,564
<b>Vehicle No.</b> :	SKD9284L	<b>Page</b> :	3 of 3
<b>Vehicle Model</b> :	MERCEDES BENZ E250	<b>Terms</b> :	
<b>Chassis No.</b> :	WDD2120472A539922		

No.	Description of Goods / Services	QTY	Unit Price	Amount
5	TOWING SERVICE	1.00 SERVICE	120.00	120.00
Remarks :				

**Nineteen Thousand Eight Hundred Fifteen and Cents Fifty Five Only**

The above repairs have been carried out according to the owner request.  
 All parts changed are warranty for 6 months.  
 The owner acknowledge the amount of repairs which has been agreed upon  
 Any dispute to the invoice must be lodged within 7 days from the date of invoice  
 We will not responsible for any damage not related to the above repair

<b>Nett</b>	<b>18,519.21</b>
<b>Discount</b>	<b>0.00</b>
<b>7% GST</b>	<b>1,296.34</b>
<b>Total Due</b>	<b>19,815.55</b>

Authorised Signature(s)

Received by

Opening Hours: Monday - Saturday : 9.00am - 6.30pm

Sunday &amp; Public Holidays : Closed

24 hours breakdown towing service, please call : 9720 3785

For your next service appointment, please call : 6786 2811

**\* OPEN 6 DAYS A WEEK \***
**Thank You For Your Patronage**



CASH SALE / WORK ORDER

顺辉拖车服务

SOON HWEE TOWING SERVICE

Blk 9002 Tampines St 92 #01-74 Singapore 528836

Handphone : 9720 3785

24 HOURS TOWING SERVICES

No: 6586

Date: 21/1/18

宝号

Messrs:

C.S

车号

Vehicle No:

SKD 9284

Model No:

E250

由

From:

Seng Kang

到

To:

W/S

时间(日/夜)

Time (Day / Night):

☒ Accident

☐ Jump Start

☒ King Tow

☐ Hoist

☐ Others:

CASH \$:

120

CHEQUE:

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一切由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

经手人

Authorised by:

收货人

Received by:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 15:08 <a href="#">Edit Adj Rpt</a>	<b>S\$18,459.21</b> <a href="#">Edit Estimates</a>	<b>S\$18,459.21</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	POON WAI MUN, ID: S1705819C								
Vehicle Reg. No.:	SKD9284L	Date of Loss:	21/01/2018 09:00 - :59 [72 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D00412C01	Policy/Cover Note No.:	DMPCSN3011271804 (Comprehensive)						
		Excess:	S\$750.00						
Repairer:	Chip Soon Auto Supply Co Pte Ltd (HQ) BLOCK 9002 #01-74 TAMPINES STREET 93, TAMPINES INDUSTRIAL PARK A, 528836 Tampines - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/02/2018]								
Driver/Custodian:	SUTINI (49 / Female), NRIC: S68763021, Tel: +6590301340								
Adj Asg. Remarks:	SURVEY REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>CHINA_TAIPING (03/08/2018): Alert - Adj Mandate Approved (S\$18459.21) - SKD9284L - Claim Handler: Chong Boon...</li> <li>CHINA_TAIPING (08/02/2018): Alert - Adj Mandate Approved (S\$20001.00) - SKD9284L - Claim Handler: Chong Boon...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKD9284L (SNM18D00412C01)  
OD  
Jan 21 2018 9:00AM  
[POON WAI MUN]  
Chip Soon Auto Supply Co Pte Ltd

























Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 20:01	Accident Statement	Load HTM	
2	26/01/18 15:43	Addendum Sheet	Load TIF	
3	26/01/18 15:43	Accident Statement Addm. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 17:22	Adjuster Immediate Advice	Load HTM	
2	03/08/18 11:54	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 19:59	3RD PARTY CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 19:59	3RD PARTY CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 19:59	3RD PARTY CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 19:59	3RD PARTY CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	22/01/18 19:59	INSURED CAR [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	22/01/18 19:59	INSURED CAR CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 17:40	General View	Load PDF	
2	03/08/18 12:11	Reinspection Photo	Load PDF	
3	03/08/18 12:11	Reinspection Photo	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/02/18 15:06	SURVEY CONTACT DETAIL	Load PDF	
2	05/02/18 15:06	REPAIR QUOTATION	Load PDF	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 19:57	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
2	22/01/18 19:57	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	 Load TIF	
3	22/01/18 19:57	<b>CI</b> [Linked Accident Report Documents]	 Load TIF	
4	22/01/18 19:57	<b>OWNER IC N DL</b> [Linked Accident Report Documents]	 Load TIF	
5	22/01/18 19:57	<b>DRIVER IC N DL</b> [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 17:27	<b>SKD 9284L ESTIMATE</b>	 Load PDF	
2	03/08/18 11:55	<b>SKD 9284L EST</b>	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 20:01	<b>Accident Statement</b>	 Load HTM	
2	26/01/18 15:43	<b>Addendum Sheet</b>	 Load TIF	
3	26/01/18 15:43	<b>Accident Statement Addm. #1</b>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 19:59	<b>3RD PARTY CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	22/01/18 19:59	<b>3RD PARTY CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	22/01/18 19:59	<b>3RD PARTY CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	22/01/18 19:59	<b>3RD PARTY CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	22/01/18 19:59	<b>INSURED CAR</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	22/01/18 19:59	<b>INSURED CAR CHASSIS NUMBER</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 19:57	<b>Sketch Plan</b>	 Load TIF	
2	22/01/18 19:57	<b>Sketch Plan #2</b>	 Load TIF	
3	22/01/18 19:57	<b>CI</b>	 Load TIF	
4	22/01/18 19:57	<b>OWNER IC N DL</b>	 Load TIF	
5	22/01/18 19:57	<b>DRIVER IC N DL</b>	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CT118002298/GRD3E2

Date: 29/08/2018

### REFERENCE

Insured/Claimant: POON WAI MUN Policy No: DMPCSN3011271804

Date of Loss: 21/01/2018 Nature of Claim: OD Claim No: SNM18D00412C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD9284L

Make &amp; Model: MERCEDES-BENZ E250, 1.8 (A)

Engine No: 27186030373584

Reg. Date: 19/01/2012 (Man. Year: 2011)

Chassis No: WDD2120472A539922

Colour: Blue

Odometer: 132564 km

Engine Capacity: 1796 cc

Market Value/New Car Price: S\$88,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,531.00	15,859.21	1,671.79	9.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,570.00	2,600.00	3,970.00	60.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,101.00</b>	<b>18,459.21</b>	<b>5,641.79</b>	<b>23.41</b>
<b>- Excess (S\$)</b>	<b>750.00</b>	<b>750.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>23,351.00</b>	<b>17,709.21</b>	<b>5,641.79</b>	<b>24.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,634.57</b>	<b>1,239.64</b>	<b>394.93</b>	<b>24.16</b>
<b>Nett Amount (S\$)</b>	<b>24,985.57</b>	<b>18,948.85</b>	<b>6,036.72</b>	<b>24.16</b>

### INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 06/02/2018 Inspected At:

Chip Soon Auto Supply Co Pte Ltd (HQ)  
BLOCK 9002 #01-74 TAMPINES STREET  
93, TAMPINES INDUSTRIAL PARK A  
Singapore 528836

Estimated Period of Repair: 8.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2018)
<b>Parts:</b>	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKD9284L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	930.00 F	*883.50 F
2	1		*BADGE, FRONT GRILLE	Necessary	43.00 F	*40.85 F
3	1		*SUPPORT, FRONT GRILLE	Distorted	19.00 F	*18.05 F
4	1		*ENGINE HOOD	Buckled	2,030.00 F	*1,928.50 F
5	1		*BONNET STAR, ENGINE HOOD	Necessary	79.00 F	*75.05 F
6	2		*SPRING ELEMENT, ENGINE HOOD	Damaged	68.00 F	*64.60 F
7	1		*SAFETY HOOK, ENGINE HOOD	Bent	74.00 F	*70.30 F
8	1		*ACTUATOR ENGINE HOOD, RH	Activated	380.00 F	*361.00 F
9	1		*ACTUATOR ENGINE HOOD, LH	Activated	380.00 F	*361.00 F
10	6		*PARKTRONIC SENSORS, FRONT	Damaged	1,248.00 F	*1,185.60 F
11	1		*FRONT BUMPER	Cut	1,250.00 F	*1,187.50 F
12	1		*CHROME, FRONT BUMPER, RH	Deformed	86.00 F	*81.70 F
13	1		*CHROME, FRONT BUMPER, LH	Deformed	86.00 F	*81.70 F
14	1		*BUMPER SUPPORT	Not Necessary	77.00 F	*- F
15	1		*GRILLE, FRONT BUMPER	Deformed	75.00 F	*71.25 F
16	1		*DAYLIGHT COVER, RH	Not Necessary	53.00 F	*- F
17	1		*DAYLIGHT COVER, LH	Deformed	53.00 F	*50.35 F
18	1		*DAYLIGHT RUNNING LAMP, RH	Not Necessary	131.00 F	*- F
19	1		*DAYLIGHT RUNNING LAMP, LH	Not Necessary	131.00 F	*- F
20	1		*NUMBER PLATE MOULDING	Cracked	182.00 F	*172.90 F
21	1		*NUMBER PLATE WITH FRAME	Cracked	40.00 F	*38.00 F
22	1		*IMPACT ABSORBER, CENTRAL	Deformed	110.00 F	*104.50 F
23	1		*FENDER, FRONT LH	Torn	1,120.00 F	*1,004.00 F
24	1		*WHEEL ARC COVER, FRONT LH	Deformed	205.00 F	*194.75 F
25	8		*PLASTIC CLIPS, WHEEL ARC COVER	Necessary	24.00 F	*22.80 F
26	1		*HEADLAMP ASSEMBLY, RH	Cracked	920.00 F	*874.00 F
27	1		*HEADLAMP ASSEMBLY, LH	Cracked	920.00 F	*874.00 F
28	1		*CROSS MEMBER, FRONT	Bent	522.00 F	*495.90 F
29	1		*SUPPORT, CROSS MEMBER, LH	Bent	285.00 F	*270.75 F
30	1		*SUPPORT PANEL, FRONT CENTRE	Bent	142.00 F	*134.90 F
31	1		*SUPPORT PANEL, FRONT LH	Bent	250.00 F	*237.50 F
32	1		*ENGINE HOOD STICKER	Not Necessary	44.00 F	*- F
33	1		*SUPPORT BRACKET, LH	Bent	53.00 F	*50.35 F
34	1		*AIRCON CONDENSER	Bent	1,170.00 F	*1,111.50 F
35	1		*AIRCON REFRIGERANT GAS	Necessary	25.00 F	*23.75 F
36	1		*RADIATOR ASSEMBLY	Bent	875.00 F	*831.25 F
37	2		*COOLANT-MERCEDES BENZ	Necessary	48.00 F	*45.60 F
38	1		*RADIATOR FAN ASSEMBLY	Cracked	905.00 F	*859.75 F
39	1		*TURBOCHARGER INTERCOOLER	Cut	1,080.00 F	*1,026.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*ENGINE BOTTOM COVER, FRONT	Cracked	241.00 F	*228.95 F
41	12		*PLASTIC CLIPS, BOTTOM COVER	Necessary	42.00 F	*39.96 F
42	1		*BRACKET, ENGINE BOTTOM COVER, LH	Bent	42.00 F	*39.90 F
43	1		*FAN SHROUD, RADIATOR	Cracked	105.00 F	*99.75 F
44	1		*IMPACT SENSOR, FRONT BUMPER	Not Necessary	110.00 F	*. F
45	1		*PARKTRONIC WIRE HARNESS	Not Necessary	228.00 F	*. F
46	1		*IMPACT ABSORBER, BUMPER LH 212 885 0537	Bent	62.00 F	*58.90 F
47	1		*BUMPER INNER PANEL, CENTRE	Deformed	75.00 F	*71.25 F
48	1		*TOP PANEL	Bent	130.00 F	*123.50 F
49	1		*AIR DUCT, INTERCOOLER	Cracked	135.00 F	*128.25 F
50	1		*BUMPER MOUNTING, LH	Cracked	48.00 F	*45.60 F
51	1		*OUTSIDE TEMPERATURE SENSOR 0075421318	Damaged	70.00 F	*66.50 F
52	1		*DAYLIGHT CHROME LH	Broken	130.00 F	*123.50 F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>17,531.00</b>	<b>15,859.21</b>
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES - PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD SUPPORT PANEL, TO KNOCK, RESHAPE AND ADJUST DAMAGED CHASSIS FRAME AND PANELS	New	2,200.00	1,000.00
2	LABOUR CHARGES - SPRAY PAINTING CHARGES TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER, WHEEL HOUSE AND AFFECTED AREAS	New	1,800.00	1,200.00
3	LABOUR CHARGES - RENEW RADIATOR, AIRCON CONDENSER, TURBOCHARGER INTERCOOLER, PARKTRONIC SENSORS, HEADLAMP ASSEMBLIES, BONNET ACTUATORS AND RELATED ITEMS	New	1,650.00	200.00
4	LABOUR OUT DIAGNOSIS TEST - CARRY OUT DIAGNOSIS TEST. CHECK PARKTRONIC SENSORS ELECTRIC CIRCUIT. CARRY OUR PROGRAMMING AND CODING FOR HEADLAMP ASSEMBLIES. RESET BONNET ACTUATORS. READ AND ERASE FAULT MEMORY	New	800.00	80.00
5	TOWING SERVICES	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,570.00</b>	<b>2,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >