

ASS. REC. BY

REF. CS/FCI/8002304/Avd302

SURVEYOR

Adrian

ASSIGNMENT (Office)

From (Person)

CWS

Ang Yin Ming

of FCI

Date/Time

5/2/18 @ 5.19pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 769G

Insured:

SHB 2304E

at Workshop m/s

Hua Meng Spray

Tel:

67478664

of

1 kaki Bkt Ave 6 Blk C # 01-61/01-34 Autobay

Policy No:

Claim No:

D18001033MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/02/2018

CA / REV / REP. / REV 24 HRS

'up'

6/2/18

H.O.D. Endorsement:

Date/Time

12.56pm @ 5/2/18

Person Contacted

june

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SGX 769G - NA / CTI 1806082 / R3

D.O.A. 2/2/18

SHB 2304E - NA / CTI 1806082 / R3

D.O.A. 2/2/18

7/2/18

Informed FCI pending workshop est by email

9/5/18

Adrian confirmed LS \$ 7000 (Ref 801616, 531)

9/5/18

Send preli revised to FCI

FCI

ASSIGNMENT

From: _____ Date: **6/2/18**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SGX 769 G**

at Workshop no: **Hua Meng Spray**

of: **1 kaki Bkt Ave 6, Blk C #01-07**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **wp**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Gen No: **SGX769G** Reg: **2007 August**

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or _____

Make: **Honda Airwave** No: **1496**

Colour: **Grey** A/C: _____ Insured: Std / Nil / NA

So Reading: **152740** T Radio: Insured / Std / Nil / NA

Eng No: _____

C No: **GJ1118239**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: **195/55R15**

R: **195/55R15**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI

TOYO / YOKO or _____

Front: _____ Rear: _____

R.Bal. **06** mm L.Bal. **06** mm

D.O.A. _____ D.O.I. **06/02/18**

Survey held at: **Hua Meng**

Des. of Damages: Fnt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date	Time	Action / Instruction
		TP 1st Cap.

Note: MV : 34K (EST)
 PV : 20.5K
 Net : 13.5K

RECEIVED 06 MAY 2018

Date/Time File Pass to: ☐ Preli. Report ☐ Final Report

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp \$ ☐ Test Insp \$ ☐ Test Eng \$ ☐ Test Rep \$

Report Format: **CWS**

Lump Sum / Bk: **7000p**

Survey Fee: **5x15 = 75**

Transcript: **130 + 75**

Print: **50**

Cost: **50**

Net: **172**

038

01/1/18

517



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002304/Avd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2304E	Veh. Inspected	SGX 769G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001033MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MING)	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date	06/02/2018	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Job Sheet (/ClaimWS/Surveyor/JobSheet/234623)



PRI Documents



Close



PRI Header Details

Claim No	D18001033MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & HUA MEN WORKSHOP
Workshop Name	HUA MENG SPRAY PAINTING WORKSHOP (Contact Person : JUNE)	Survey Location & Contact Details	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C # Mobile: 0 , Phone: 67478064 , Fax: 67434836 EmailId: HUAMENG@LIVE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2304E	TP Vehicle No	SGX769G
PRI Recieved Date	02-02-2018 07:44:31 PM	Surveyor Appointed Date	05-02-2018 12:18:47 PM	Surveyor Accept Date	06-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 9 May 2018 11:49 AM
To: 'Claim Workflow System'
Cc: 'AUNGYINMIN@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001033MFSH/1, SGX 769G
Attachments: SGX 769G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGX 769G
Date of survey: 6/2/2018
Number of days: 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 February 2018 5:30 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001033MFSH/1, SGX 769G

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGX 769G on 6/2/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 5 February 2018 5:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001033MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 5 February 2018 12:19 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001033MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001033MFSH
Our ref: CS/FCI18002304/Avd3

Date : 9/5/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGX 769G


We thank you for your instruction on 5/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/2/2018 at the premises of M/s HUA MENG SPRAY PAINTING WORKSHOP and have the following to report:-

Workshop Estimate Amount	: S\$15,016.16
Revised Estimate Amount	: S\$7,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear poriton



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 February 2018 5:30 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001033MFSH/1, SGX 769G

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGX 769G on 6/2/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 5 February 2018 5:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001033MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 5 February 2018 12:19 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001033MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4757D

Vehicle Details

Vehicle No.: SGX769G
Vehicle to be Exported: Yes
Intended De-registration Date: 06 Feb 2018
Vehicle Make: HONDA
Vehicle Model: AIRWAVE 1.5 A
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: L15A5122111
Chassis No.: GJ11118239
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$14,457.00
Original Registration Date: 10 Aug 2007
First Registration Date: 10 Aug 2007
Transfer Count: 2
Actual ARF Paid: \$15,903.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 09 Aug 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$22,700.00
COE Rebate Amount: \$20,466.00
Total Rebate Amount: \$20,466.00

Message



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2869 Downpayment Monthly
From \$738 Onwards. Lowest
3.68% APR. All Car Hire and
GV Credit Pte Ltd. 10000000



Browse by Category

Sort by Date Posted

20 results/page

19 vehicles

airwave

Advanced Search

Search Selection	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
airwave		Any	Any	> 10 year(s) old	Any	Any	Any	Available



Honda Airwave 1.5A (COE till 06/2021)

\$28,000

\$8,320 /yr

19-Jun-2006

1,496 cc

169,481 km

Stationwagon

Available

Reliable And Comfortable, No Repair Needed, Owner Selling Off Due To Under Usage, View To Appreciate! Trade-In Welcome! Flexible Loan Available Up To 80% Don't Miss! Call/SMS For A Non-Obligatory Disc...

Posted: 25-Dec-2017 Tags: 2006 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda

PREMIUM ID



Honda Airwave 1.5A (COE till 07/2021)

\$25,800

\$7,410 /yr

10-Aug-2006

1,496 cc

Stationwagon

Available

You Wouldn't Believe The Tip Top Condition Of This Unit Without Viewing It. Better Than Rental Or For Short Term Use. Attractive Insurance Rates To Cater For All Drivers. In House Financing To Suit Yo...

Posted: 20-Jan-2018 Tags: 2006 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda



Honda Airwave 1.5A (COE till 07/2021)

\$21,800

\$6,260 /yr

17-Aug-2006

1,496 cc

162,000 km

Stationwagon

Available

Consignment Car, Good Engine Condition, Flexible Bank/In House Loan Available! Trade In Most Welcome! Call Us For Viewing.

Car Search

Posted: 24-Jan-2018 Tags: 2006 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda

CONSIGNMENT



Honda Airwave 1.5A Skyroof (COE till 05/2022)

\$37,800

\$8,770 /yr

30-May-2007

1,496 cc

125,000 km

Stationwagon

Available

Well Kept Condition, No Repairs Needed, Best For Coe Renewal. Beautiful New Paintwork. Genuine Low Mileage Done. View To Believe. In-House Loan Available, Call Now For Viewing

Tay Motor & Credit Pte Ltd

Posted: 27-Jan-2018 Tags: 2007 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Buying a pre-owned car, but
Unsure of its Condition?
Get STA Car Evaluation



Honda Airwave 1.5A M (COE till 09/2022)

\$35,800

\$7,700 /yr

01-Oct-2007

1,496 cc

Stationwagon

Available

You Wouldn't Believe The Tip Top Condition Of This Unit Without Viewing It. Better Than Rental Or For Short Term Use. Attractive Insurance Rates To Cater For All Drivers. In House Financing To Suit Yo...

Posted: 27-Jan-2018 Tags: 2007 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda



Honda Airwave 1.5A M (New 5-yr COE)

\$36,800

\$7,360 /yr

13-Dec-2007

1,496 cc

119,000 km

Stationwagon

Available

"One Year In House Warranty!", Purchase With Official Warranty Certificate With A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$465 Low Monthly Installment, ...

Carway

Posted: 02-Feb-2018 Tags: 2007 Honda Airwave, Honda Airwave, Honda, Airwave, Used Honda



Honda Airwave 1.5A M (New 5-yr COE)

\$36,800

\$7,360 /yr

14-Dec-2007

1,496 cc

143,000 km

Stationwagon

Available

"One Year In House Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$495 Low Monthly Installment, 10% Down Pa...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2018 10:48
Date Of Accident	02/02/2018 08:00
Exact Location Of Accident	FILTER LANE OF TAMPINES RD TWDS HOUGANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX769G
Insured/Policyholder	
Name Of Registered Owner	MR MUHAMMAD SELAMAT BIN IDRIS
NRIC No	S8434757D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96557950
Alternative Phone No	OTHERS-96557950
Vehicle Particulars	
Manufacturer	HONDA
Model	AIRWAVE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3063251700
Cover Note Number	
Driver	
Name of Driver	MR MUHAMMAD SELAMAT BIN IDRIS
NRIC No	S8434757D
Date Of Birth	24/10/1984
Occupation	INDOOR
Date Of Driving Pass	23/11/2010
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96557950
Fax Number	
Contact Number	OTHERS-96557950
EMail Address	NOEMAIL

Address	BLK 208B PUNGGOL PLACE #11-918
Postcode	822208
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SITI ZAHRAH BTE HASSAN GENDER: : FEMALE
Passenger 2	NAME: : NAYLAH MD SELAMAT GENDER: : FEMALE
Passenger 3	NAME: : NASYWAH MD SELAMAT GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB2304E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	S1139384E
Contact Number	98467540

• Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Group	Condition A	Condition B	Condition C	Condition D
Control	~85%	~80%	~85%	~90%
MCI	~60%	~55%	~65%	~70%
AD	~40%	~35%	~45%	~50%

[illegible]

There are no known records or evidence as to whether

- © 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 105–112

- My consent is given and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and disseminate personal data/personal information set out in this form, and any other personal information disclosed or suggested by my insurer(s) (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured (under(s)) involved in the accident (all insurers who have insured (under(s)) involved in the accident shall collectively referred to as the "Insurers"), their insurers' lawyers/firm(s), the Ministry of Justice of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) stated.

- [illegible]

- 122 —

- DOI: 10.1002/for

1. I am not a member of any club, including the making of commendation statements, I never reports or members to me which could involve a disclosure of confidential personal data about me to bring about delivery of the same as well as on the internet cover of a newspaper, magazine, website, and so on.

- Using the information you are administering, processing, handling and producing with my limited access to the
 Purpose:

10. The information collected will be shared with the following: other law enforcement agencies, state and federal agencies, and the public. The information collected will be used for the following purposes: to identify and locate missing persons, to identify and locate persons who are at risk of harm, and to identify and locate persons who are at risk of harm.

13. Personal information may also be used by any of the insurers and/or GIA to the third party service providers or agents and advisors (i.e. GIA's "GIA Affiliates") who may be located outside of Singapore, for one or more of the above Purposes.

- Personal information will also be collected and used to compile a directory for the purpose of field collection, publication and management in protected areas (see Annex 1).

1. The 1995-1996 collected period of active myxomatosis (0.1-0.2)

- To all the above, it may, simply in part, be that access to emerging, fast growing, technology markets has been restricted by the current and government sponsored, as reasonably required for the purposes stated, of

- TURKISH - TURKISH PARADOXES AND THE PROPOSITIONS OF "HUMAN RIGHTS"**

[illegible]

Accepting Centre Personnel's Signature
Name
APR 20 1991

Sketch Plan #2

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along filter lane of Tampines Road towards Hougang Ave 3 on 02.01.2018 @ 0800hrs. I was stationary my vehicle to give way to pedestrian. Suddenly, I heard a bang sound and felt an impact from my behind. vehicle B was collided with rear portion of my vehicle.

DECLARATION


I hereby declare that the above is a true and correct statement.



Driver A
Name & Title



Driver B
Name & Title

 02/02/18

Witness
Name & Title

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MUHAMMAD SELAMAT BIN IDRIS
BLK 208B PUNGGOL PLACE
#11-918
S 822208

TP 1st Cap
Veron.

Date :21.03.2018
Vehicle no :SGX 769 G
Make/Model :HONDA AIRWAVE
Accident date :02.02.2018

No	Description	Qty	Amount (\$\$)
List Items			
1	Rear windscreen rubber <i>nee</i>	1	\$ 61.6 ✓
2	Tailgate <i>Distorted</i>	1	\$ 1030.7 ✓
3	Tailgate hinges @ \$74.80 <i>nto nlu</i>	2	\$ 149.6X ✓
4	Tailgate upper lock <i>Domaged</i>	1	\$ 217.8 ✓
5	Tailgate lower lock <i>nto nlu</i>	1	\$ 68.2 X ✓
6	Tailgate shock absorber @ \$173.80 <i>nto nlu</i>	2	\$ 347.6 X ✓
7	Tailgate reflector @ \$253.00 <i>cracked</i>	2	\$ 506 ✓
8	Tailgate AIRWAVE emblem <i>nto</i>	1	\$ 39.6 ✓
9	Tailgate H logo <i>nto</i>	1	\$ 23.1 ✓
10	Tailgate centre garnish <i>Deformed</i>	1	\$ 308 ✓
11	Tailgate inner cover <i>cracked</i>	1	\$ 341 ✓
12	Tailgate centre moulding <i>cracked</i>	1	\$ 319 ✓
13	Tailgate inner handle <i>nto nlu</i>	1	\$ 176 X ✓
14	Rear bumper <i>Distorted</i>	1	\$ 547.8 ✓
15	Rear bumper side holder @ \$30.80 <i>nto</i>	2	\$ 61.6 ✓
16	Rear bumper clips (1set) <i>1 nlu</i>	1	\$ 50.30 ✓
17	Rear bumper inner top beam <i>Beut</i>	1	\$ 203.5 ✓
18	Tailgate top spoiler <i>nto nlu</i>	1	\$ 1001 X ✓
19	Tailgate outer handle <i>nto nlu</i>	1	\$ 148.5 X ✓
20	Rear lamp @ \$314.60 <i>cracked</i>	2	\$ 629.2 ✓
21	Rear lamp housing @ \$209.00 <i>Repair</i>	2	\$ 418 X ✓
22	Rear end panel <i>Dented</i>	1	\$ 558.70 ✓
23	Rear end panel inner top garnish <i>Dehd</i>	1	\$ 209 ✓
24	Rear LH fender <i>Repair</i>	1	\$ 941.6 X ✓
25	Rear fender inner garnish @ \$341.00 <i>Dehd</i>	2	\$ 682 ✓
26	Rear fender inner shield @ \$93.50 <i>nto nlu</i>	2	\$ 187 X ✓
27	Rear spare tyre top outer board <i>Deformed</i>	1	\$ 231 ✓
28	Rear spare tyre top inner board <i>Deformed</i>	1	\$ 308 ✓
29	Rear spare tyre well <i>Repair</i>	1	\$ 187 X ✓
30	Rear spare tyre well insulation @ \$115.50 <i>nto</i>	3	\$ 346.5 X ✓ 200(SN)
			10080.9

10298.6

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MUHAMMAD SELAMAT BIN IDRIS
BLK 208B PUNGGOL PLACE
#11-918
S 822208

Date :21.03.2018
Vehicle no :SGX 769 G
Make/Model :HONDA AIRWAVE
Accident date :02.02.2018

No	Description	Qty	Amount (\$\$)
31	Rear spare tyre screw <i>Best</i>	1	\$ 50 ✓
32	Rear exhaust pipe <i>Best</i>	1	\$ 748 ✓
33	Rear exhaust pipe mounting <i>Best</i>	1	\$ 30.8 ✓
34	Rear fender quarter glass rubber	1	\$ 198 ✓
			\$ 11107.7
		Less 20% Disc	\$ 2221.54
		Total	\$ 8886.16

9060.32

Special Nett Items

1	Rear bumper reverse sensor	1	\$ 380 ✓
		Total	\$ 380

Labour Cost

1	To supply rear windscreen sealant	\$ 50 ✓
2	To supply rear end panel inner sealant	\$ 200 ✓
3	Remove & reinstall reverse sensor	\$ 150 ✓
4	Remove & reinstall exhaust pipe	\$ 200 ✓
5	Remove & reinstall cushion & inner garnish	\$ 200 ✓
6	Remove ,replace & repair consistent to the accident	\$ 2800 ✓
7	Respray painting	\$ 2000 ✓
8	Tuff kote	\$ 150 ✓
	Total	\$ 5750

Grand Total \$ 15016.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 8764.48 15190.32

g/s. TK
08 Days.

TK
02/4/18




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002304/Avd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2304E	Veh. Inspected	SGX 769G	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001033MFSH	Excess (\$)	0.00	
Assign From	AUNG YIN MING	Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	GJ11118239	Colour	GREY	
Odometer	152740	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	MICHELIN	6 mm	
L/H Front Tyre	195/55 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2018	Inspection Date	06/02/2018	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 769G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN RUBBER	NECESSARY	61.60	61.60
1	TAILGATE	DISTORTED	1,030.70	1,030.70
2	TAILGATE HINGES @\$74.80	NOT NECESSARY	149.60	-
1	TAILGATE UPPER LOCK	DAMAGED	217.80	217.80
1	TAILGATE LOWER LOCK	NOT NECESSARY	68.20	-
2	TAILGATE SHOCK ABSORBER @\$173.80	NOT NECESSARY	347.60	-
2	TAILGATE REFLECTOR @\$253.00	CRACKED	506.00	506.00
1	TAILGATE AIRWAVE EMBLEM	NECESSARY	39.60	39.60
1	TAILGATE H LOGO	NECESSARY	23.10	23.10
1	TAILGATE CENTRE GARNISH	DEFORMED	308.00	308.00
1	TAILGATE INNER COVER	CRACKED	341.00	341.00
1	TAILGATE CENTRE MOULDING	CRACKED	319.00	319.00
1	TAILGATE INNER HANDLE	NOT NECESSARY	176.00	-
1	REAR BUMPER	DISTORTED	547.80	547.80
2	REAR BUMPER SIDE HOLDER @\$30.80	NECESSARY	61.60	61.60
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
1	REAR BUMPER INNER TOP BEAM	BENT	203.50	203.50
1	TAILGATE TOP SPOILER	NOT NECESSARY	1,001.00	-
1	TAILGATE OUTER HANDLE	NOT NECESSARY	148.50	-
2	REAR LAMP @\$314.60	CRACKED	629.20	629.20
2	REAR LAMP HOUSING @\$209.00	TO REPAIR SEE LABOUR	418.00	-
1	REAR END PANEL	DENTED	558.70	558.70
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	209.00	209.00
1	REAR LH FENDER	TO REPAIR SEE LABOUR	941.60	-
2	REAR FENDER INNER GARNISH @\$341.00	DEFORMED	682.00	682.00
2	REAR FENDER INNER SHIELD @\$93.50	NOT NECESSARY	187.00	-
1	REAR SPARE TYRE TOP OUTER BOARD	DEFORMED	231.00	231.00
1	REAR SPARE TYRE TOP INNER BOARD	DEFORMED	308.00	308.00
1	REAR SPARE TYRE WELL	TO REPAIR SEE LABOUR	187.00	-

Report Ref No. CS/FCI18002304/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE SCREW	BENT	50.00	50.00
1	REAR EXHAUST PIPE	BENT	748.00	748.00
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	30.80	-
1	REAR FENDER QUARTER GLASS RUBBER	NOT NECESSARY	198.00	-
	LESS 20% DISCOUNT		-2,195.78	-1,421.12
			8,783.12	5,684.48
3	REAR SPARE TYRE WELL INSULATION @\$115.50 (SN)	NECESSARY	346.50	200.00
	LESS 20% DISCOUNT		-69.30	-
			277.20	200.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
			380.00	200.00
	LABOUR			
	TO SUPPLY REAR WINDSCREEN SEALANT.		50.00	50.00
	TO SUPPLY REAR END PANEL INNER SEALANT.		200.00	60.00
	REMOVE & INSTALL REVERSE SENSOR.		150.00	50.00
	REMOVE & REINSTALL EXHAUST PIPE.		200.00	80.00
	REMOVE & REINSTALL CUSHION & INNER GARNISH.		200.00	60.00
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR LAMP HOUSING, REAR LH FENDER AND REAR SPARE TYRE WELL.		2,800.00	1,200.00
	RESPRAY PAINTING.		2,000.00	1,100.00
	TUFF KOTE.		150.00	80.00
			-	-
			-	-
			-	-
			-	-
			-	-
			5,750.00	2,680.00
	GRAND TOTAL		15,190.32	8,764.48

Report Ref No. CS/FC118002304/Avd3e2



**RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)**

7,000.00

Report Ref No. CS/FCI18002304/Avd3e2

MARKET VALUE: \$34,000.00(EST)-PAPER VALUE: \$20,500.00=NETT VALUE: \$13,500.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.