

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5805B -**AAD1802-010***Not Authen
Resumy B4 painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5805B - CANDY

VF1ABL15AUC283195

RENAULT

LATITUDE

01.02.2018

TOKIO**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>CM</i>	1,259.42	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i>	394.68	X
3	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80	X
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.22	✓
7	1	BUMPER RETAINER FRT LH	\$	<i>CM</i>	151.41	✓
8	1	BUMPER BRACKET FRT LH	\$	<i>R</i>	181.75	X
9	1	HEADLAMP LH	\$	<i>CM</i>	1,184.43	✓
10	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
11	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	✓
12	1	FENDER INSULATOR LH	\$	<i>Sn</i>	130.84	X
13	1	FENDER BRACKET FRT LH	\$	<i>R</i>	34.14	X
14	1	WHEELARCH FRT LH	\$	<i>Sn</i>	278.84	✓
15	1	AIR CLEANER LOWER	\$	<i>Sn</i>	352.64	X
16	1	AIR CLEANER HOSE	\$	<i>Sn</i>	76.14	X
17	1	RADAITOR GRILLE	\$	<i>mj CM</i>	1,707.78	✓
18	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>R</i>	173.36	✓
19	1	RADAITOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
20	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	X
21	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	X
22	1	BONNET	\$	<i>R</i>	1,941.63	✓
23	1	BONNET HINGE LH	\$	<i>R</i>	348.31	X
24	1	BONNET HINGE RH	\$	<i>R</i>	348.31	X
25	1	WHEEL HOUSING PANEL FRT LH	\$	<i>R</i>	5,173.47	X
26	1	LOWER ARM LH	\$		685.76	?
27	1	KUNCKLE ARM LH	\$		846.98	?
28	1	ABSORBER FRT LH	\$		360.54	?
48	1	AIR CLEANER LOWER	\$	<i>mi</i>	271.26	✓
49	1	AIR CLEANER HOSE	\$	<i>CM</i>	76.14	✓
51	1	AUTO COMPUTER	\$		5,032.17	?
52	1	STEERING PUMP ELECTRIC	\$	<i>no</i>	2,306.90	✓
29	1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66	X
30	1	DOOR MIRROR LH	\$	<i>R</i>	1,483.40	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-010**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5805B -

31	1	DOOR MIRROR GLASS LH	\$	<i>sn</i>	148.20	X
32	1	DOOR MIRROR BACK COVER LH	\$	<i>sn</i>	218.46	X
33	1	ROCKER PANEL OUTER LH	\$	<i>na</i>	987.49	X

TOTAL	\$	33,564.39
10%	\$	3,356.44
	\$	30,207.95

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i>	66.00	—
2	1SET	FRONT BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1	RIM LH FRT	\$	<i>na</i>	385.00	—
4	1	TYRE LH FRT	\$	<i>sn</i>	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	<i>na</i>	80.00	X
6	1	DOOR STICKER "Classic"	\$	<i>na</i>	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	<i>na</i>	80.00	X
8	1	FENDER ADVERTISEMENT STICKER FRT LH	\$	<i>na</i>	300.00	<i>150.00</i>
9	1	DOOR ADVERTISEMENT STICKER FRT LH	\$	<i>na</i>	300.00	X

TOTAL	\$	1,637.00
TOTAL PARTS	\$	31,844.95

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	<i>500</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>700</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-010**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5805B -

Towing fees	\$	120.00	
To rust-proofing of the affected areas.	\$	170.00	301
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?

TOTAL \$ 7,540.00**Over All Total \$ 39,384.95****(PARTS BY PARTS) Repair Days****10 Days***4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: