

## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 3296T

DATE 5/2/2018 14:56

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Lamp (RH) ✓			\$ 344.00
	Rear Fender (RH) X repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) X			\$ 74.10
	Rear Windscreen Moulding X			\$ 60.00
	Rear Bumper X repair			
	<b>SUB TOTAL</b>			<b>\$ 2,414.00</b>
	<b>LESS 20%</b>			<b>\$ 482.80</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,931.20</b>
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Fender Comfort Sticker (RH) ✓			\$ 30.00
	Rear Windscreen Sealant X			\$ 46.00
				<b>\$ 126.00</b>
	<b>Labour Charge</b>			<b>400</b>
	Panel Beating			\$ <del>850.00</del>
	Spray Painting Charge			\$ <del>400.00</del>
	Wiring Charge			\$ <del>50.00</del>
	Tuff Kote			\$ <del>50.00</del>
	Remove/Refix Cushion & Upholstery Rear			\$ <del>150.00</del>
	Remove/Refix Rear Windscreen Glass			\$ <del>120.00</del>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del>
	<b>TOTAL LABOUR</b>			<b>\$ 1,740.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,797.20</b>
	<i>Ka/m 16/15</i>			
	<i>5/2/18 1600 hrs</i>			
	<i>2 Pys</i>			
	<i>4/5</i>			
	<i>After Repair photo</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.