COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE* VEHICLE NO: SH 9736J

MAKE

Hlum AlG

MODEL	: HYUNDAI SONATA	4	re			
Qty	Parts Description/ Labour	Туре	Unit Price		Amount]
	Front Fender (RH)			\$	593.00	
	Front Fender Shield (RH)		;	\$	86.00	
	Front Fender Retainer 🗶			\$	9.20	
	Front Wheel Hub Cap (RH)			\$	145.00	
	Food Buper X Agran SUB TOTAL					l
				\$	833.20	
	LESS 20%			\$	166.64	
	DISCOUNTED TOTAL			\$	666.56	
	Front Fender Advertisement Logo (RH)			\$	100.00	Neti
				\$	100.00	
	Labour Charge				700	
	Panel Beating			\$	560.00	12/
	Spray Painting Charge		·	\$	400.00 50.00	56
	Tuff Kote			\$	€	120
	FRT Wheel Alignment			\$	120,00	†×
	TOTAL LABOUR		r.	\$	1,130.00	
	ESTIMATE TOTAL			\$	1,896.56	
	Kahil (1944) 1 5/4/3 1035/2 2 hgs					
	2 /12	[KK Auto Consultants he he Repairer of the follow	nce n	Ootify	
	Affe Reporp the	1	To display dame after spray	rng: paintir	na	1
	4)	:	Parts prices are subject to conf	ring rea	SURVAY	
	After Report		No illegal modification(s) is allow	out Pre	ejudice" basis	
		Aci	subject to final approval from It owledged by Repairer nature:	resurve Nsuran	eyed <u>and</u> ice Company	
		Det				
	This is an initial estimate based on a visual inspection of the					
	be prepared after the vehicle is surveyed by a motor Surve	yor appoin	ted by the insurance con	mpan	ıy.	_