

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 8261A

DATE 5/2/2018 9:48

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Clips 10 pcs ✓			\$ 22.00	
	Tail Lamp (RH) ✓			\$ 565.60	
	Rear Fender (RH) ✓			\$ 2,020.10	
	Rear Fender Inner Panel (RH) X 1/2 ✓			\$ 1,190.50	
	Rear Fender Inner Lining (RH) ?			\$ 164.40	
	Rear Windscreen Moulding ✓			\$ 60.00	
	Rear Door (RH) ✓			\$ 1,351.10	
	Rocker Panel Outer Garnish (RH) X 1/2 ✓			\$ 483.60	
	Rear Wheel Hup-Cap (RH) ✓			\$ 150.70	
	SUB TOTAL			\$ 6,611.60	
	LESS 20%			\$ 1,322.32	
	DISCOUNTED TOTAL			\$ 5,289.28	
	Rear Windscreen Sealant ✓			\$ 46.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00	Nett
				\$ 126.00	
	Labour Charge				
	Panel Beating			\$ 1,600.00 800	
	Spray Painting Charge			\$ 1,000.00 720	
	Wiring Charge			\$ 50.00 20	
	Tuff Kote			\$ 50.00 20	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50	
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100	
	Remove/Refix Reverse Sensor			\$ 120.00 20	
	Transfer of Door			\$ 120.00 50	
	Rear Wheel Alignment			\$ 120.00 X	
	TOTAL LABOUR			\$ 3,330.00	
	ESTIMATE TOTAL			\$ 8,745.28	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: _____
 Signature: _____
 Date: _____

Ka ha 11/11/18
 5/2/18 11:40h
 4 Pys
 Bedone Part phl