

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Yee Pei Li

of

EGI

Date/Time: 6/2/18 @ 10:19am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SKR 25754

Insured:

XD8909X

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of

No. 10, AMK Ind. Prk A #01-09

Policy No:

Claim No:

DSM CV1800238/SE/PI

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/01/2018

7/2/18 @ 10:30am @ owner waiting

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

10:50am @ 6/2/18

Person Contacted:

Zila

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKR 25754 - CC4/AXA16002080/Kug3q2

D.O.A.: 29/01/16

XD8909X-X

8/2/18

Email preli revised to Pei Li

18/3/18

@ 416pm Mui Hong will email us finalise

5/9/18

@ 408pm Mui Hong will email us finalise

REF: EGI

ASSIGNMENT

Form: Date: 7/2/18

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKR 2575U

at Workshop via: Ah Lim Motor

of: No. 10 AMK Ind. Prk 2A #01-09

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

10:30 am owner
waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lim Sum: % G Val: Yes or No

CA / REV / REP / 24 HRS 1up

Vehicle IN / OUT

Date: Person Contacted:

Ver No: SKR 2575U Reg: 09 09

Type: M/Car / M/Cycle / Bus/Van / Lorry / Taxi / Prime Mover

Truck / Trailer:

Make:

Volvo S40 A1

1999

Colour:

M. Gray

A/C Insured / Std / Nil / NA

Sp. Reading:

199640

T. Rep'd Insured / Std / Nil / NA

Eng No:

C No:

YVIMS434B-92466416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S Rim / STD A/Rim or

Tyre Size:

Falken 205/55R16

R/L King

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

9

mm

R/Bal:

7

L/Bal:

9

mm

L/Bal:

7

D.O.A:

30/11/18

D.O.A:

7/2/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

O/S Acc

The U/O / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

8/2 15h pc ss to Corhome

24/9/18 @ 406pm Mui Hong will email us finalise

25/10/18 @ 1255pm LS \$4100 confirmed with Mui Hong (Red 2844.19, 410)

RECEIVED 25 OCT 2018

Date Time File Pass to?



: Prel. Report

Days Of Repair: 5

1



: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transcription:

Date Time File Return to?

25/10 - typist

Add Fee:



Steel Fac:

\$



Interplay:

\$



Technic:

\$



Vibe-rep:

\$

Report Format:

TP

Lim Sum / L.B.:

4100p

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18002333/Kvd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 06-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 8909X	Veh. Inspected	SKR 2575U
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800238	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/01/2018	Inspection Date	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 1996071981

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 6256431

Your ref: DSMCV1800238
Our ref: CS/EG118002333/Kvd3

Date: 8/2/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKR 2575U


We thank you for your instruction on 6/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle c
7/2/2018 at the premises of M/s AH LIM MOTOR CO
and have the following to report:-

Workshop Estimate Amount	: S\$6,944.19
Revised Estimate Amount	: S\$4,884.82
"Check" Items Amount	: S\$200.07
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS/EGI/18002333/Kvd3
Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (

): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

VERON

Case Handler

Date

25/10/18

*C: Critical *N: Non-Critical

21/05/2

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 6 February 2018 10:19 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD8909X / TP : SKR2575U/LKK / DOA : 30/01/2018 (DSMCV1800238)
Attachments: XD8909X - SAS.pdf; SKR2575U - SAS.pdf; SKR2575U - ESTIMATE.pdf; SKR2575U - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AH LIM MOTOR COMPANY**,

ADDRESS : NO 10 ANG MO KIO IND. PARK 2A
#01-09 AMK AUTOPOINT
SINGAPORE 568047

PERSON TO CONTACT : ZILA @ 6483 1244

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured's and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 06.02.2018
Our Reference: DSMCV1800238/SE/pl
Your Reference: SKR 2575U

To: AH LIM MOTOR COMPANY

Sent via Fax
or
Email zila@ahlimmotor.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKR 2575U
Insured's Vehicle: XD 8909X
Date Of Accident: 30.01.2018


We acknowledge receipt of your request for PRS on: 05.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd ✓
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE- SITI

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 8 February 2018 12:30 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: XD8909X / TP : SKR2575U/LKK / DOA : 30/01/2018 (DSMCV1800238)
Attachments: PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SKR 2575U
Date of survey: 7/2/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 February 2018 10:52 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XD8909X / TP : SKR2575U/LKK / DOA : 30/01/2018 (DSMCV1800238)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 07/02/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 6 February 2018 10:19 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XD8909X / TP : SKR2575U/LKK / DOA : 30/01/2018 (DSMCV1800238)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AH LIM MOTOR COMPANY**,

ADDRESS : NO 10 ANG MO KIO IND. PARK 2A
#01-09 AMK AUTOPOINT
SINGAPORE 568047

PERSON TO CONTACT : ZILA @ 6483 1244

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured's and TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2785C

Vehicle Details

Vehicle No.: SKR2575U
Vehicle to be Exported: Yes
Intended De-registration Date: 31 Jan 2018
Vehicle Make: VOLVO
Vehicle Model: S40 2.0L A/T ABS
D/AIRBAG 2WD 4DR
Primary Colour: Grey
Manufacturing Year: 2009
Engine No.: B4204S3163093
Chassis No.: YV1MS434B92466416
Maximum Power Output: 107.0 kW (143 bhp)
Open Market Value: \$31,443.00
Original Registration Date: 16 Sep 2009
First Registration Date: 16 Sep 2009
Transfer Count: 1
Actual ARF Paid: \$31,443.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Sep 2019
PARF Rebate Amount: \$17,293.00


Intended COE Rebate Details

COE Expiry Date: 15 Sep 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$17,905.00
COE Rebate Amount: \$2,647.00
Total Rebate Amount: \$19,940.00

The information contained herein is correct as at 31 Jan 2018


OK

Sketch Plan Pg. 3



1px
no video
no injury
clear + dry

91081373





redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 ☎ (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

account number
 04817

Certificate of Insurance

Motor Vehicle (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicle (Third-Party Risks and Compensation) Rules, 1987 Road Transport Act, 1987 (Malaysia)
 Motor Vehicle (Third-Party Risks and Compensation) Rules, 1987 (Malaysia)

Policy details

Policyholder name	LEETECH PEIR	Certificate number	GA093897 / 1
Cover	Comprehensive	Chassis number	YV1MS434B92466416
Plan name	Private APW	Engine number	84204S3163093
NCD applicable	50%		
Vehicle registration number	SKR207BU		
Period of insurance	from 16/03/2017 to 15/03/2018 (both dates inclusive)		
Finance loan company	MAYBANK		

Persons or classes of persons entitled to drive*

in The Policyholder
 in Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

The policy is for normal, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trades or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, race, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitation as to use does not apply to the Motor Vehicle (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 96 of the Road Transport Act, 1987 (Malaysia) and the Motor Vehicle (Third-Party Risks and Compensation) Rules, 1987 (Malaysia).

EXCESS	Basic (Less Damage Excess)	500 0.00
	Windscreen Excess	500 100.00

An Additional Excess is applicable as follows:
 1. S\$500 for unnamed Authorised Driver
 2. S\$500 for declared Young and Inexperienced Driver
 3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

[We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicle (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature



Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

Search for best motor insurance premium?

LTC Resources

Kindly contact : 9061 5988

Jeffrey Tan (Tel: 6299 3066)

Block 1022 Tai Seng Ave,
 #02-3528 Singapore 534415
 Fax: 6842 6506 Email: jettnc03@gmail.com

AXA Insurance Pte Ltd (109903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE TECK PEIR
BLK 446 YISHUN AVENUE 11
#06-60
SINGAPORE 760446

TEL: 91081373

ATTN:

Your Ref No: SKR2575U

Claim Type: Third Party.

Accident Date: 30/01/2018

TP Veh Reg No: XD8909X

Estimate No: MC0912822

Date: 05 Feb 2018

Policy No: GA093897/1

Veh Reg No: SKR2575U

Make/Model: VOLVO S40

Excess Ins

10:30 AM

Not Authorized

Repairing by name 5 days

Estimate Repair Cost to Vehicle No :SKR2575U

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILAMP RH	1 PC	Sen 345.30	✓
2 REAR BUMPER	1 PC	cm 1,285.40	✓
3 REAR BUMPER SIDE RETAINERS RH	1 PC	Sen 77.00	X
4 REAR BUMPER CLIPS	10 PC	me 48.00	✓
5 REAR FENDER RH	1 PC	Bz 1,871.10	✓
6 REAR FENDER COWLING RH	1 PC	cm 170.30	✓
7 REAR FENDER COWLING CLIPS	8 PC	me 52.00	✓
8 REAR WINDSCREEN MOULDING TOP - CHECK PRICE	1 PC	me 0.00	✓
9 REAR WINDSCREEN MOULDING SIDE LH & RH - CHECK PRICE	2 PC	me 0.00	✓
10 REAR WINDSCREEN MOULDING LOWER - CHECK PRICE	1 PC	me 0.00	✓
		3,849.10	
	Less 10%	384.91	3,464.19
Special Nett			
11 SPORT RIM RHR	1 PC	Sen 650.00	* 800
12 INNER SEAL	1 PC	me 20.00	✓
13 WINDSCREEN SEALANT	1 PC	me 40.00	✓
		710.00	710.00
LABOUR			
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
15 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	600
16 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	150.00	1000
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	500
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER RH. TO KNOCK & REPAIR REAR FENDER INNER PANEL RH, REAR DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,300.00	7000
20 TO SPRAY REAR FENDER RH, REAR BUMPER, REAR FENDER INNER PANEL RH, REAR DOOR RH.	1 PC	1,000.00	5000
		2,770.00	2,770.19





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE TECK PEIR
BLK 446 YISHUN AVENUE 11
#06-60
SINGAPORE 760446
TEL: 91081373
ATTN:
Your Ref No: SKR2575U
Claim Type:
Accident Date: 30/01/2018
TP Veh Reg No: XD8909X

Estimate No: MC0912822
Date: 05 Feb 2018
Policy No: GA093897/1
Veh Reg No: SKR2575U
Make/Model: VOLVO S40

Estimate Repair Cost to Vehicle No :SKR2575U

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 6,944.19
		Add GST @ 7%	486.09
		Total Amount Payable	S\$ 7,430.28

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED THIRTY AND CENTS TWENTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18002333/Kvd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 30-10-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 8909X	Veh. Inspected	SKR 2575U	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800238/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S40 (A)	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	YV1MS434B92466416	Colour	METALLIC GREY	
Odometer	199640	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	9 mm	
L/H Front Tyre	205/55 R16	FALKEN	9 mm	
R/H Rear Tyre	205/55 R16	VIKING	7 mm	
L/H Rear Tyre	205/55 R16	VIKING	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/01/2018	Inspection Date	07/02/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 2575U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILAMP RH	SCRATCHED	345.30	345.30
1	REAR BUMPER	CRACKED	1,285.40	1,285.40
1	REAR BUMPER SIDE RETAINERS RH	SERVICEABLE	77.00	-
10	REAR BUMPER CLIPS	NECESSARY	48.00	48.00
1	REAR FENDER RH	BENT	1,871.10	1,871.10
1	REAR FENDER COWLING RH	CRACKED	170.30	170.30
8	REAR FENDER COWLING CLIPS	NECESSARY	52.00	52.00
1	REAR WINDSCREEN MOULDING TOP (NPA)	NECESSARY	-	-
2	REAR WINDSCREEN MOULDING SIDE LH & RH (NPA)	NECESSARY	-	-
1	REAR WINDSCREEN MOULDING LOWER (NPA)	NECESSARY	-	-
	LESS 10% DISCOUNT		-384.91	-377.21
			3,464.19	3,394.89
SPECIAL NETT ITEMS				
1	SPORT RIM RHR (LOCAL REPAIR)(SN)	SCRATCHED	650.00	80.00
1	INNER SEAL (SN)	NECESSARY	20.00	20.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			710.00	140.00
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS.TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		120.00	120.00
	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		150.00	100.00
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		80.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH.TO KNOCK & REPAIR REAR FENDER INNER PANEL RH.REAR DOOR RH.INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.		1,300.00	700.00
	TO SPRAY REAR FENDER RH,REAR BUMPER,REAR FENDER INNER PANEL RH,REAR DOOR RH.		1,000.00	500.00
			2,770.00	1,550.00
GRAND TOTAL			6,944.19	5,084.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/EGI18002333/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.