

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL,NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9753X -**AAD1802-006***Not Authorized
1 Sep 8/8501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9753X - CANDY

VF1ABL15AUC273225

RENAULT

LATITUDE

01.02.2018

III**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i>	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>na/bu</i>	768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>su</i>	113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>su</i>	135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>su</i>	44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>su</i>	43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>su</i>	135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>su</i>	44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>su</i>	43.61	X
10	1	BUMPER BEAM REAR	\$	<i>n</i>	777.52	X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i>	225.95	X
13	1	BOOT REAR	\$	<i>n</i>	2,872.68	} X
14	1	BOOT FINISHER	\$	<i>su</i>	470.06	
15	1	BOOT WHEATERSTRIP	\$	<i>su</i>	323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	<i>su</i>	493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	<i>su</i>	493.35	
18	1	BOOT BADGE 'RENAULT'	\$	<i>ni</i>	225.36	
19	1	BOOT BADGE	\$	<i>ni</i>	225.36	
20	1	BOOT INNER TRIM	\$	<i>su</i>	586.45	
21	1	BOOT SWITCH	\$	<i>su</i>	168.13	
22	1	BOOT LOCK	\$	<i>n</i>	202.67	
23	1	BOOT LOCK CATCH	\$	<i>su</i>	74.40	
24	2	LICENCE PLATE LAMP	\$	<i>su</i>	50.52	
25	2	BOOT RUBBER PLUG	\$	<i>su</i>	221.81	
26	1	FENDER PANEL REAR LH	\$	<i>n</i>	3,299.13	
27	1	WHEELARCH REAR LH	\$	<i>su</i>	543.47	
28	1	FENDER PANEL REAR RH	\$	<i>n</i>	3,299.13	
29	1	WHEELARCH REAR RH	\$	<i>su</i>	543.47	
30	1	TAILLAMP RH	\$	<i>su</i>	552.55	
31	1	TAILLAMP PANEL RH	\$	<i>n</i>	986.70	
32	1	TAILLAMP LH	\$	<i>su</i>	552.55	
33	1	TAILLAMP PANEL LH	\$	<i>n</i>	986.70	
34	1	OUTER PANEL REAR (End Panel)	\$	<i>n</i>	1,471.77	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9753X -**AAD1802-006**

35	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	} X
36	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88	
37	1	SPARE WHEEL PANEL TRIM	\$	612.21	
38	1	EXHAUST REAR	\$	7,489.05	
39	1	EXHAUST CAP REAR	\$	230.49	

TOTAL	\$	33,238.20
--------------	----	------------------

10%	\$	3,323.82
------------	----	-----------------

	\$	29,914.38
--	----	------------------

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	30.00	
13	1	BOOT STICKER "6555-3333"	\$	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	} X
16	1	TAILLAMP CLIP RH	\$	5.00	
17	1	TAILLAMP CLIP LH	\$	5.00	
18	2	REAR WINDSCREEN SELANT	\$	80.00	
19	1	WINDSCREEN MOULDING	\$	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
22	1	SPARE TYRE	\$	330.00	

TOTAL	\$	2,124.02
--------------	----	-----------------

TOTAL PARTS	\$	32,038.40
--------------------	----	------------------

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00
---	----	----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00
---	----	----------

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-006**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9753X -

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>1</i>

TOTAL \$ 7,710.00**Over All Total \$ 39,748.40****(PARTS BY PARTS)****Repair Days***10 Days*
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: