

M/S AXA INS (S'PORE) PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

ESTIMATE

DATE : 04/01/2018
ACC DATE : 22/12/2017
REF NO. : VFIX-TP20170388
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO.PC327C BUS

DESCRIPTION	AMOUNT S\$
1 1 REAR BUMPER	3,221.00
2 1 SIDE REAR COMPARTMENT DOOR RH	1,850.00
	\$ 5,071.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear side panel repair/reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments	2,000.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	2,000.00
	\$ 4,000.00

GRAND TOTAL : \$ 9,071.00

SINGAPORE DOLLARS : NINE THOUSAND & SEVENTY ONE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Authorized
LKK
2/5 \$2600
3 day.
take right after repair
8/1/18