

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8807 G

1 pc	Wheel cover	X	\$	116.00
			Less 10%	\$ 11.60
				<u>\$ 104.40</u>

### S/NETT

1 set	Front n/s fender sticker	X	\$	30.00
	Sundry		\$	<del>50.00</del> 20
	To check wheel alignment		\$	<del>80.00</del> X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of front bumper, front n/s fender		\$	<del>650.00</del> 200
	To putty and spray painting on front bumper, front n/s fender		\$	<del>400.00</del> 360
	To apply rustproofing on the repaired and replaced panels.		\$	<del>120.00</del> X
			\$	<u>1,434.40</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Ka/wh r/ck  
12/2/18 1315 hrs.  
2 Days  
4/5  
After Repair plh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: