

INS. CASE OWNER:

Nabatie

CC 4 / III1800

2340

U² Koz G

LKK:

IDAC:

Surveyor:

marrus

DOI:

ASSIGNMENT

6/2/18

Date / Time:

5/2/18

Registered in Merimen:

6/2/18

Pre-assign / CCU / FTE

SHA 2854P



Insured Vehicle No.:

CPL

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A. 4/2/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ZAN 500 NGAP

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SGD 1293K



INSRS:

WSP: Yaw Tee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

9/2/18
20miSGD 1293K
SHA 2854PMS/INC/180719/2/18; OIA 01/02/18
013/01/14 0053001 Spas W2; OIA 12/1/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

09022018

FILES REVIEWED, CASE OF CONFLICTING VERSION
Seek liability mandate via merimen.

14022018

File fail to type mandate report.

RECEIVED 13 NOV 2018

Mandate:

COR: 1284.00

OFF:

LTA: 6 x 60 = 360

CAP: 1284.00

LTA: 29.00

CON: 6 x 50 = 300.00

Total: 1673.00

LTA: 29.00

(@ 20%) : 851.00

Total: 0.50

1 9821.00

RECEIVED 13 FEB 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

%

50

(

Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

SS

1,284.00

Loss of Rental (LOR):

SS

-

(

days)

Loss of Use (LOU):

SS

300.00

(\$

50 x 6

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

29.00

Medical:

SS

Disbursement:

SS

Legal Cost:

SS

(e.g. Tow/ Independent)

Total:

SS

821.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

821.00

Name 1:

Yaw Tee Automobile Tech Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 2300.00

* Wt invoice not tally w settlement amount.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SAD1293Kat Workshop m/s 1/ew tee

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8500

IDAC Accident Rpt. _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: SAD1293K Yr Regn: 28/3/08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Nissan Xetio C.C. 1458Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 220114 T/Radio: Insured / Std / NI / NA

Engl No: _____

C/No: JN13AAC112.0009194Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 1/2/18 D.O.I. 6/2/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 2747165 1st 27 Aug. Not 1335ashy 1k. Reporting rear bumper already missing6/2/18 confirmed L/S @ 1200 with Sharon.(Red: \$3,567.50 / 75%)surveyor recommended days (4 days) + 1 weekend + 1 inspection = 6 days.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18002340/Uka3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 06-02-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2854P	Veh. Inspected	SGD 1293K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/02/2018	Inspection Date	06/02/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

02/03/2018

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Bik 6 Woodlands Road 399F, Yew Tee Ind Estate
Singapore 678006

Tel: 67622081 Fax: 67804895 Email: utauto@singnet.com.sg

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5039532089-07	Date of Loss:	01/02/2018
Vehicle Reg. No.:	SGD1293K	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHA2854P
Any Injuries?	no	Contact No:	
Insured/Claimant:	SINGHANIA DEEP SANWARMAL	Driver:	SINGHANIA RESHMA DEEP

Make/Model:	Nissan, Latio - JN1FAAC11Z0010170	Vehicle Reg. Date:	28/03/2008
Vehicle Colour:	GREY	Engine Number:	HR15251192A
Chassis No:	JN1BAAC11Z0009194	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	5

Description of Accident/loss ON ECP HIHWAY, A COMFORT TAXI CAME FROM BEHIND ON THE RIGHT SIDE AND BANGED THE CAR FROM BEHIND ON THE RIGHT SIDE. IT WAS RAINING AND CAR MUST BE AT 50KM/H, TRAFFIC WAS NORMAL AND SLOW.

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,223.50
Miscellaneous Items	200.00
Labour	700.00
Paintwork Labour	640.00
Towing	0.00
Gross Total(S\$):	4,763.50
GST 7.00%(S\$):	333.44
Nett Amount(S\$):	5,096.94

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (legal/ modification/s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
sh
a/s \$1200/-
take photo after repair.
Hdy.
6/2/18

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BOOT LID	717.90	717.90	-30.00	502.53
2	1	BOOT LID LATIIO EMBLEM	52.70	52.70	-10.00	47.43
3	1	BOOT LID LOCK	91.80	91.80	-10.00	82.62
4	1	REAR BUMPER 509.90	1,029.00	1,029.00	-30.00	720.30
5	1	REAR BUMPER BRACKET LH	80.40	80.40	-10.00	72.36
6	1	REAR BUMPER BRACKET RH	80.40	80.40	-10.00	72.36
7	1	REAR BUMPER INNER SPONGE	32.70	32.70	-10.00	29.43
8	1	REAR BUMPER LOWER SPOILER 340	450.00	450.00	-10.00	405.00
9	1	REAR BUMPER SIDE RETAINER LH 36.20	63.00	63.00	-10.00	56.70
10	1	REAR BUMPER SIDE RETAINER RH 36.20	63.00	63.00	-10.00	56.70
11	1	REAR END PANEL	407.70	407.70	-30.00	285.39
12	1	REAR EXHAUST SILENCER	709.80	709.80	-30.00	496.86
13	1	REAR TAILLAMP LH	219.90	219.90	-10.00	197.91
14	1	REAR TAILLAMP RH	219.90	219.90	-10.00	197.91

Total Parts (\$\$) 3,223.50**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR REVERSE SENSOR 200.00 / 200.00	200.00	200.00	0.00	200.00

Sub Total (\$\$) 200.00**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	700.00	700.00	0.00	700.00

Gross Labour Cost (\$\$) 700.00**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	20.00	20.00	0.00	20.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	20.00	20.00	0.00	20.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00

Gross Labour Cost (\$\$) 640.00

< END OF ESTIMATES >

2-386.93 683
614.7 102

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Friday, 6 April 2018 9:30 AM
To: 'YT(HQ)'
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: SGD 1293K_ACCIDENT INVOLVING SHA 2854P AND SGD 1293K ON 01.02.2018
Attachments: RV III SGD1293K 01022018.pdf

WITHOUT PREJUDICE

Your Ref: SGD 1293K
Our Ref: CC4/III18002340/Uka3

Dear Shawn,

ACCIDENT INVOLVING SHA 2854P & SGD 1293K ON 01/02/2018

We refer to the above matter.

We confirmed settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,284.00
2. Loss of Use(6days x \$50.00)	\$ 300.00
3. LTA/GIA Search Fee	\$ 29.00
TOTAL (@100%)	<u>\$ 1,613.00</u>
(@50%)	<u>\$ 821.00</u>

Kindly refer to the attached DV above and forward your DV in **ORIGINAL HARDCOPY** via post for our necessary action.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

MOB: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk S1, PoyuUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) [mailto:utauto@singnet.com.sg]
Sent: Tuesday, 3 April 2018 3:55 PM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Your Ref: SGD 1293K_ACCIDENT INVOLVING SHA 2854P AND SGD 1293K ON 01.02.2018

Hi Zani

We propose settlement at \$821.00

COR	\$1284.00
LOU	\$300.00
Liability 50%	\$792.00
GIA	\$29.00
Settlement	\$821.00

Best Regards

Shawn Teh L.M

9743 2262 / 8100 7999

www.yewteegroup.com

info@yewteegroup.com

Like Us On Facebook

Managing Director of

-YEW TEE AUTOMOBILE TECH PTE LTD

-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD

-ULTIMAX LEASING PTE LTD

-SKT TYRE & BATTERY SERVICES PTE LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856

Please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Zaini (LKK Auto) <Zaini@lkkauto.com>

Sent: Monday, 2 April, 2018 1:42 PM

To: YT(HQ) <utauto@singnet.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: SGD 1293K_ACCIDENT INVOLVING SHA 2854P AND SGD 1293K ON 01.02.2018

WITHOUT PREJUDICE

Dear Shawn,

We refer to our email dated 13.03.2018.

Kindly be informed that we are currently pending for your offer acceptance for our next course of actions.

Appreciate an early reply.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DDD: 6841-3132 | email: zaini@lkkauto.com | fax: 6741-4108

88K 51, PoyuLbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zaini (LKK Auto)

Sent: Tuesday, 13 March 2018 2:45 PM

To: 'YT(HQ)' <utauto@singnet.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: SGD 1293K_ACCIDENT INVOLVING SHA 2854P AND SGD 1293K ON 01.02.2018

WITHOUT PREJUDICE

Your Ref: SGD 1293K

Our Ref: CC4/III18002340/Uka3

Dear Sirs,

ACCIDENT INVOLVING SHA 2854P & SGD 1293K ON 01/02/2018

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 800.00 (all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DDD: 6841-3132 | email: zaini@lkkauto.com | fax: 6741-4108

88K 51, PoyuLbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) [<mailto:utauto@singnet.com.sg>]

Sent: Wednesday, 21 February 2018 4:04 PM

To: Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: SGD 1293K_ACCIDENT INVOLVING SHA 2854P AND SGD 1293K ON 01.02.2018

Hi

Print Received Message

This mail is associated with :

***SGD1293K (MCT18020019)**
[SHA2854P]

TP

SINGHANIA DEEP SANWARMAL

Feb 1 2018 4:00PM

[COMFORT TRANSPORTATION PTE LTD]

Yew Tee Automobile Tech Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/04/2018 10:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$851.00) - SGD1293K - Claim Handler: NATALIE LEE

Approved:851.00.

Claim Audit

AUDIT TRAIL

Sl No.	On	Description	By
1	06 Feb 2018 15:30	Cim Veh Model Changed (204487) NISSAN LATIO 1.5 L (A).	[A] HOW MEI KWAN
2	06 Feb 2018 15:30	Cim Created Reg No: SGD1293K, Acct Date: 2018/02/01, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	[A] HOW MEI KWAN
3	06 Feb 2018 15:30	Adj Co Assigned LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	06 Feb 2018 15:30	Adj Next Rpt Changed Next Rpt:Final Rpt, Due Date:2018/02/15	[A] HOW MEI KWAN
5	06 Feb 2018 15:30	Adj Mandate Set Approved:0.00, Reinsp:Adj decides.	[A] HOW MEI KWAN
6	06 Feb 2018 15:31	Label Added (30653):Direct Settlement,	[A] HOW MEI KWAN
7	06 Feb 2018 15:31	Adj Adjuster Assigned [None] -> MARCUS CHUA	[A] HOW MEI KWAN
8	07 Feb 2018 11:54	Cim Dtl Modified Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: -> 199303821R.	[A] HOW MEI KWAN
9	07 Feb 2018 11:56	Adj Rpt Initiated	[A] HOW MEI KWAN
10	07 Feb 2018 11:56	Cim Details Notified	[A] HOW MEI KWAN
11	09 Feb 2018 11:46	Adj Mandate Request Cur.Req:0.00;PODS Liability: TBA Remarks: FILES REVIEWED. Case of conflicting version, Request to view OI CCTV footage for further review. For your approval in merimen please.	[A] Zaini Bin Kusaini
12	14 Feb 2018 15:00	Video Downloaded Downloaded Video - Accident	[I] NATALIE LEE
13	20 Feb 2018 15:43	Adj Mandate Request Cancelled	[A] JOANNE LEE KHANG MIN
14	21 Feb 2018 14:46	Video Downloaded Downloaded Video - Accident	[I] NATALIE LEE
15	21 Feb 2018 15:04	Adj Mandate Request Cur.Req:1200.00;PODS Liability: 50% Remarks: FILES REVIEWED. Case of both vehicles changing lane, For your approval in merimen please.	[A] Zaini Bin Kusaini
16	21 Feb 2018 15:44	Adj Next Rpt Changed Next Rpt:Final Rpt, Due Date:2018/02/15	[I] NATALIE LEE
17	21 Feb 2018 15:44	Adj Mandate Set Approved:0.00.	[I] NATALIE LEE
18	02 Mar 2018 10:31	Adj Mandate Request Cur.Req:809.00;LIABILITY: 50% QUANTUM: (a) COR(w/GST):\$1,200.00 + (b)LOU(6 DAYS X \$60.00):\$360.00 + (c)LTA/GIA search fee: \$29.00= Total: (@100%): 1,589.00 (@50%): 809.00 Vehicle Model: NISSAN LATIO For your approval please	[A] Zaini Bin Kusaini
19	02 Mar 2018 14:53	Video Downloaded Downloaded Video - Accident	[I] NATALIE LEE
20	02 Mar 2018 14:57	Video Downloaded Downloaded Video - Accident	[I] Sherini Pillai
21	02 Mar 2018 14:57	Adj Mandate Set Approved:809.00.	[I] Sherini Pillai
22	04 Apr 2018 11:25	Adj Mandate Request Cur.Req: 851.00;PODS LIABILITY: 50% QUANTUM: (a) COR(w/GST):\$1,284.00 + (b)LOU(6 DAYS X \$60.00):\$360.00 + (c)LTA/GIA search fee: \$29.00= Total: (@100%): 1,673.00 (@50%): 851.00 Vehicle Model: NISSAN LATIO For your approval please	[A] Zaini Bin Kusaini
23	05 Apr 2018 10:17	Video Downloaded Downloaded Video - Accident	[I] Lalitha Krishnan
24	05 Apr 2018 10:18	Adj Mandate Set Approved:851.00.	[I] Lalitha Krishnan

Date From



Date To



Audit Type None

Go

ACTIVITY

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp_viewhistory&caseid=681786&extid=263861&CFID=31658991&CFTOKEN=1234567890

22.02.2018

India International Insurance Pte Ltd
64 Cecil Street
#04-00/#05-00 IOB Building
Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: SGD1293K & SHA2854P on 01.02.2018

We are the authorized repair workshop for the owner of motor vehicle no: SGD1293K which was involved in the captioned accident with your insured vehicle: SHA2854P. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Lump Sum	\$	1,200.00
02)	TP Search Fee	\$	27.10
		\$	1,227.10
	GST 7%	\$	85.90
	Sub Total	\$	1,313.00
	Loss of Use 6 day @ \$60/day	\$	360.00
	Grand Total	\$	1,673.00


We enclosed herewith the following documents to support the claims:-

- a) GIA report
- b) Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully


Shaun
97432262

LETTER OF AUTHORITY

To whom it may concern,

ACCIDENT INVOLVING : SGD1293K and SHA2854P on 01/02/2018

I/We SINGHANIA DEEP SANWARMAL Reg No.: S6968826H

Owner of motor vehicle no : SGD1293K do hereby appoint M/S YEW TEE AUTOMOBILE TECH PTE LTD as my/our authorized representative to write, negotiate and settle my/our claims against the other party involved in the abovementioned accident. M/S YEW TEE AUTOMOBILE TECH PTE LTD shall have absolute discretion to settle the matter at the best terms.

I/WE also confirm and instruct that any agreed settlement sum in respect of my/our claims be paid to M/S YEW TEE AUTOMOBILE TECH PTE LTD and such payment will constitute a full and final discharge of my/our claims.

I/WE further authorize M/S YEW TEE AUTOMOBILE TECH PTE LTD to execute the discharge voucher on my/our behalf.



Signature of Owner.

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18020019
 Claimant Ref: SGD1293K

We/I, Yew Tee Automobile Tech Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 642.00 (repair cost), S\$ 150.00 (loss of use/~~rental~~), S\$ 29.00 (search fee), vehicle no. SGD1293K that was damaged pursuant to the accident which occurred on 01/02/2018 (date) at ECP TOWARDS CHANGI (location) involving vehicle no. SHA2854R (insured vehicle). This is pursuant to the inspection conducted on 06/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SINGHANIA DEEP SANWARMAL ("the third party claimant") of vehicle no. SGD1293K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGD1293K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 821.00 to Yew Tee Automobile Tech Pte Ltd

Dated this 6 day of April, 20 18

CLAIMANT:

Signature: [Signature]

Name: May

NRIC: G6918492G

Address: _____

Nationality: Malaysian

Occupation: Admin

WITNESS:

Signature: [Signature]

Name: LKK AUTO CONSULTANTS PTE LTD

NRIC: 1986071982

Address: 51 UBI AVE 1, PETA UBI INDI PK
#02-25 2408933

Nationality: _____

Occupation: _____



Signed by appointed Surveyor cks

**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399-F YEW TEE IND EST S(678006)
BR: SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #01-61 S(417800)
BR: MEGA@WOODLANDS, 39 WOODLANDS CLOSE #01-12 S(737856)
GST Reg No. 200311009C
Singapore
67653373 / 67023113
INFO@YEWTEEGROUP.COM
WWW.YEWTEEGROUP.COM
Company Registration No. 200311009C

ADDRESS

INDIA INTERNATIONAL
INSURANCE PTE LTD
INDIA INTERNATIONAL
INSURANCE PTE LTD

TP TAX INVOICE MC1802004**DATE 22/02/2018**

VEHICLE NO.
SGD1293K

CONTACT**ATTN**

ACTIVITY	QTY	RATE	TAX	AMOUNT
Lump Sum Repair	1	1,200.00	7% SR	1,200.00
Survey & Search fee	1	27.10	7% SR	27.10
Loss of Use	6	60.00	Out of Scope	360.00

Cheque should be crossed & made payable to "YEW TEE AUTOMOBILE TECH PTE LTD" and strictly send to our HQ address.

SUBTOTAL 1,587.10
GST TOTAL 85.90

TOTAL SGD 1,673.00

Accepted By

Accepted Date

RECEIVED BY

ISSUED BY

E. & O.E.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-018277

Date of Request: 02/02/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd
Blk 6 Woodlands Road 399F,
Yew Tee Ind Estate
Singapore 678006

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 01/02/2018

Place of Accident: ECP TOWARDS CHANGI

Client Vehicle No: SGD1293K

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-18-018282
Date of Request: 02/02/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd
Blk 6 Woodlands Road 399F,
Yew Tee Ind Estate
Singapore 678006

Dear Sir/Madam,

Date of Accident: 01/02/2018
Vehicle No: SGD1293K
Place of Accident: ALONG ECP TOWARDS CHANGI
Involving Vehicle No: SHA2854P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA2854P	ALONG ECP TOWARDS CHANGI	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	\$51,200.00 Edit Estimates	\$51,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	SINGHANIA DEEP SANWARMAL , ID: S6968826H								
Vehicle Reg. No.:	SGD1293K	Date of Loss:	01/02/2018 16:00 - :59 [118 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18020019	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA2854P	Policy No. (Claimant):	5039532089-07						
		Excess:							
Repairer:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (05/04/2018): Alert - Adj Mandate Approved (\$851.00) - SGD1293K - Claim Handler: NATALIE LEE III_SG (02/03/2018): Alert - Adj Mandate Approved (\$809.00) - SGD1293K - Claim Handler: NATALIE LEE III_SG (21/02/2018): Alert - Adj Mandate Approved (\$0.00) - SGD1293K - Claim Handler: NATALIE LEE 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGD1293K (MCT18020019)
 [SHA2854P]
 TP
 SINGHANIA DEEP SANWARMAL
 Feb 1 2018 4:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Yew Tee Automobile Tech Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/02/18 14:46	Video - Accident	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 19:00	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/02/18 19:00	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
4	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
19	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
20	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
21	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
22	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
23	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
24	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
25	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
26	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
27	06/02/18 19:00	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 15:31	TP ESTIMATE	Load PDF	
2	06/02/18 15:31	TP GIA REPORT	Load PDF	
3	06/02/18 15:31	ACKNOWLEDGEMENT EMAIL TO III DD 06.02.2018	Load PDF	
4	09/02/18 11:21	TP ESTIMATE - MARKED	Load PDF	
5	02/03/18 10:25	LOD AND ATA FORM	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
6	02/03/18 10:25	FINAL REPAIR BILL	Load PDF	
7	16/11/18 08:38	AUTHORISATION TO ACT FORM	Load PDF	
8	16/11/18 08:38	DISCHARGE VOUCHER	Load PDF	
9	16/11/18 08:38	GIA SEARCH	Load PDF	
10	16/11/18 08:38	LOD	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 09:27	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002340/UEA3Q2

Date: 16/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : SGD1293K	Insured Vehicle No : SHA2854P
Date of Loss: 01/02/2018	Nature of Claim: TP Claim No: MCT18020019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD1293K	Engine No:	HR15251192A
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0009194
Reg. Date:	28/03/2008 (Man. Year: 2007)	Odometer:	220114 km
Colour:	Brown		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,423.50	1,201.06	2,222.44	64.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	900.00	440.00	32.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,763.50	2,101.06	2,662.44	55.89
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	4,763.50	1,200.00	3,563.50	74.81
+ GST 7.00/7.00% (S\$)	333.45	84.00	249.45	74.81
Nett Amount (S\$)	5,096.95	1,284.00	3,812.95	74.81
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
(S\$)		1,584.00		
Liabe Amount (50.00%) (S\$)		792.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		821.00		

INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 06/02/2018 Inspected At: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
BLK 25 KAKI BUKIT ROAD 4, #01-61
SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2018)
Parts: 143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGD1293K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	717.90 FL	*- FL
2	1		*REAR BUMPER	Missing	1,029.00 FL	*509.90 FL
3	1		*REAR END PANEL	Repair	407.70 FL	*- FL
4	1		*REAR EXHAUST SILENCER	Not Necessary	709.80 FL	*- FL
5	1		*BOOT LID LATIO EMBLEM	Necessary	52.70 FN	*52.70 FN
6	1		*BOOT LID LOCK	Not Necessary	91.80 FN	*- FN
7	1		*REAR BUMPER BRACKET LH	Not Necessary	80.40 FN	*- FN
8	1		*REAR BUMPER BRACKET RH	Not Necessary	80.40 FN	*- FN
9	1		*REAR BUMPER INNER SPONGE	Missing	32.70 FN	*32.70 FN
10	1		*REAR BUMPER LOWER SPOILER	Missing	450.00 FN	*340.00 FN
11	1		*REAR BUMPER SIDE RETAINER LH	Cracked	63.00 FN	*35.20 FN
12	1		*REAR BUMPER SIDE RETAINER RH	Cracked	63.00 FN	*35.20 FN
13	1		*REAR TAILLAMP LH	Not Necessary	219.90 FN	*- FN
14	1		*REAR TAILLAMP RH	Broken	219.90 FN	*219.90 FN
15	1		*SET REAR REVERSE SENSOR	Torn / Missing	200.00 FS	*200.00 FS
					Sub Total (\$\$)	4,418.20 1,425.60
					- List Item Discount on L Items 30.00/30.00% (\$\$)	859.32 152.97
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	135.38 71.57
					Total Parts (\$\$)	3,423.50 1,201.06

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	700.00	400.00
2	TO CARRY -OUT BODY CAVITY PRESERVATION	New	20.00	0.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	20.00	0.00
4	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	500.00
Gross Labour Cost (\$\$)			1,340.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >