

02/03/2018

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Blk 6 Woodlands Road 399F, Yew Tee Ind Estate
Singapore 678006

Tel: 67622081 Fax: 67804895 Email: utauto@singnet.com.sg

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5039532089-07	Date of Loss:	01/02/2018
Vehicle Reg. No.:	SGD1293K	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHA2854P
Any Injuries?	no	Contact No:	
Insured/Claimant:	SINGHANIA DEEP SANWARMAL	Driver:	SINGHANIA RESHMA DEEP

Make/Model:	Nissan, Latio - JN1FAAC11Z0010170	Vehicle Reg. Date:	28/03/2008
Vehicle Colour:	GREY	Engine Number:	HR15251192A
Chassis No:	JN1BAAC11Z0009194	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	5

Description of Accident/loss ON ECP HIHWAY, A COMFORT TAXI CAME FROM BEHIND ON THE RIGHT SIDE AND BANGED THE CAR FROM BEHIND ON THE RIGHT SIDE. IT WAS RAINING AND CAR MUST BE AT 50KM/H, TRAFFIC WAS NORMAL AND SLOW.

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,223.50
Miscellaneous Items	200.00
Labour	700.00
Paintwork Labour	640.00
Towing	0.00
Gross Total(S\$):	4,763.50
GST 7.00%(S\$):	333.44
Nett Amount(S\$):	5,096.94

This claim is handled by: Shaun Toh L M

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BOOT LID	717.90	717.90	-30.00	502.53
2	1	BOOT LID LATIO EMBLEM	52.70	52.70	-10.00	47.43
3	1	BOOT LID LOCK	91.80	91.80	-10.00	82.62
4	1	REAR BUMPER	1,029.00	1,029.00	-30.00	720.30
5	1	REAR BUMPER BRACKET LH	80.40	80.40	-10.00	72.36
6	1	REAR BUMPER BRACKET RH	80.40	80.40	-10.00	72.36
7	1	REAR BUMPER INNER SPONGE	32.70	32.70	-10.00	29.43
8	1	REAR BUMPER LOWER SPOILER	450.00	450.00	-10.00	405.00
9	1	REAR BUMPER SIDE RETAINER LH	63.00	63.00	-10.00	56.70
10	1	REAR BUMPER SIDE RETAINER RH	63.00	63.00	-10.00	56.70
11	1	REAR END PANEL	407.70	407.70	-30.00	285.39
12	1	REAR EXHAUST SILENCER	709.80	709.80	-30.00	496.86
13	1	REAR TAILLAMP LH	219.90	219.90	-10.00	197.91
14	1	REAR TAILLAMP RH	219.90	219.90	-10.00	197.91

Total Parts (S\$) 3,223.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR REVERSE SENSOR	200.00	200.00	0.00	200.00

Sub Total (S\$) 200.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	700.00	700.00	0.00	700.00

Gross Labour Cost (S\$) 700.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	20.00	20.00	0.00	20.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	20.00	20.00	0.00	20.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00

Gross Labour Cost (S\$) 640.00

< END OF ESTIMATES >