

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

Chinua Taping
Monday
05/02/18
(Kenneth Kay)

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

Not Authorised
1/1/18
Resony After Painting
Today

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

1pc	front centre grille	\$	527.33	?
1pc	front "MITSUBISHI" logo	\$	82.54	?
1pc	front "FUSO" emblem	\$	154.95	?
1pc	front bumper	Bu	\$ 821.47	✓
1pc	front RH corner panel	\$	564.37	?
1pc	front RH headlamp	\$	768.10	?
1pc	front RH corner lamp	CM	\$ 159.75	—
1pc	front RH side lamp	CM	\$ 227.63	—
1pc	front RH door	Ry	\$ 1,969.30	✓
2pcs	front RH door hinge @\$162.54	Ry	\$ 325.08	—
1pc	front RH door inner lock	nu	\$ 389.21	—
1pc	front RH door inner rubber	CM	\$ 216.50	<i>Sofra</i>
1pc	front RH door inner trim panel	\$	565.92	?
1pc	front RH door lower garnish	CM	\$ 542.70	—
1pc	front RH door lower garnish rubber	CM	\$ 154.00	—
1pc	front RH door glass gear & motor	BH/Ru	\$ 1,317.05	✓
1pc	front RH door glass moulding	\$	181.05	?
1pc	front RH door front garnish	Sn	\$ 138.00	X
1pc	front RH door rear garnish	Sn	\$ 158.00	X
1pc	front RH pillar	Ry	\$ 1,533.24	✓
1pc	front RH pillar rubber	CM	\$ 138.15	<i>Sofra</i>
1pc	front RH step panel	Ry	\$ 496.36	✓
1pc	front RH step panel lower rubber	CM	\$ 36.15	✓
1pc	front RH step panel garnish	CM	\$ 339.36	✓
1pc	front RH wheel top panel	Bu	\$ 537.95	✓
1pc	front RH wheel top panel rubber	nu	\$ 77.40	✓
1pc	front RH wheel top panel garnish	CM	\$ 175.10	✓
1pc	front RH wheel rear garnish	\$	173.45	?
1pc	front RH wheel rear garnish lower rubber	\$	68.10	?
1pc	front RH rim	Ry	\$ 612.50	✓
1pc	front RH top arm	\$	914.09	?
1pc	front RH lower arm	\$	3,812.10	?
1pc	front RH absorber	\$	202.30	?
1pc	front RH knuckle arm	Ry	\$ 2,400.05	✓
balance c/f			\$ 20,779.25	



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

	balance b/f		\$ 20,779.25
1pc	front RH knuckle bearing	RM	\$ 95.68 ✓
1pc	front RH tie rod		\$ 206.12 ?
1pc	front RH steering rack		\$ 7,430.80 ?
1pc	front RH rotor disc	RM	\$ 440.28 X
1pc	front RH brake caliper	RM	\$ 1,786.60 X
1pc	front crossmember		\$ 2,131.95 ?
1pc	radiator spare tank	RM	\$ 184.85 X
1pc	air cleaner tank	RM	\$ 813.35 ?
1pc	air cleaner chamber	RM	\$ 184.62 ?
1pc	diesel tank	RM	\$ 1,609.10 X
	less 20%		\$ 35,662.60 35,307.95
			\$ 7,132.52 7,061.50
			\$ 28,530.08 29,246.30

remove & refit front windscreen & door glass	\$ 200.00	1201
remove & refit front dashboard	\$ 300.00	2401
remove & refit front undercarriage	\$ 480.00	2401
remove & refit diesel tank	\$ 250.00	601
alignment	\$ 150.00	601
wiring	\$ 180.00	301
tuffkote	\$ 250.00	901
sealant	RM \$ 120.00	X
Spary Painting	\$ 1,800.00	10001
Labour Charge	\$ 1,700.00	11001

Total

~~\$ 33,960.08~~

34,031.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____