



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



165

Dr. —

As per telephone conversation yesterday, we have checked with our Surveyor who had physically inspected the IP vehicle.

The RH rear door is dented at the re-inforced area ^(double layer) at the edge of the door. Pls see photo.