

View Sent Message

This mail is associated with :

*SLV6128T (548637)
[SFA9993Z]
TP
TAY SONG WEE
Feb 4 2018 12:00PM
[CHENG SIN LAI]
Yi Heng Motor Workshop

ResendView RecipientsPrint MessageDelete MessageForward

FromLKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/05/2018 17:04 PM.
ToMSI_WCS
SubjectTP SURVEY SLV 6128T

Dear Ms Katherine,

As per telephone conversation with Ms Jasmine yesterday, we have checked with our surveyor who had physically inspected the TP vehicle. The RH rear door is dented at the re-inforced area (double layer) at the edge of the rear door. Please see photo attached as below.

Thanks Veron Chen

DOCUMENTS SUMMARY

Mail Attachments

- LKK Auto Consultants Pte Ltd (HQ) [Thumbnails]:(17/05/18) Attachment

