

12/03/2012

SS. EC. BY:

REF: CS/EGN18003360 / AHb

Special Instruction:

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 06022018 249pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBU 51T Insured: SKD 6387T

at Workshop m/s Mh Solution Tel: 6744 4165

of 23 Kaki Bukit Ave 4 #02-18B

Policy No: Claim No: DSMPC1800248/SL

Sum Insured: Excess:

D.O.A. 05122018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 06022018 3:41pm Person Contacted: Jia mi Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SBU 51T - x
	SKD 6387T - x
	Lump Sum \$9900 (Red: 13107.81; 56%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S BUSIT Yr Regn: 2009 / SeptType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E250 c.c. 1796Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 219278 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120472A070708Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R17R: 245/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/02/18Survey held at MG SolutionDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP Ergo.

MV : 50K
 PV : 35.3K
 Netf : 14.7K.

RECEIVED 26 JUL 2018

Date/Time, File Pass to?

1) 26th Typist

Date/Time, File Return to?

☐ : Preli. Report☒ : Final ReportDays Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ - RS. \$

) Photos

) Others

TOTAL

350

TP
 99001-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18002360/Atb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 06-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 6387T	Veh. Inspected	SBU 51T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/02/2018	Inspection Date	06/02/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 6 February, 2018 2:49 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SKD6387T / TP : SBU51T/LKK / DOA : 05/02/2018
Attachments: SBU51T - SAS.pdf; SBU51T -(Pre-Inspection)-ACCIDENT ON 05/02/2018 (840 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – Adrian Ling** to be the "Single Joint Expert".

Please assist to conduct this survey from **MG SOLUTION PTE LTD**,

ADDRESS : 23 KAKI BUKIT AVE 4 (SOUTH WING)
#02-03B VICOM INSPECTION CENTRE
SINGAPORE 415933

PERSON TO CONTACT : DOEN ANG @ 6744 4165

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 25 July 2018 5:35 PM
To: Steve Lim; Admin-D (LKKAuto); Survey Report (ERGO Insurance Pte. Ltd.); SUR
Cc: assignments
Subject: RE: SKD6387T / TP : SBU51T/LKK / DOA : 05/02/2018 (DSMPC1800248/SL)

Dear Steven,

Midst of preparing the report, soft copy will sent to you shortly

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Lim [<mailto:steve.lim@ergo.com.sg>]
Sent: Wednesday, 25 July 2018 2:44 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: SKD6387T / TP : SBU51T/LKK / DOA : 05/02/2018 (DSMPC1800248/SL)

Dear Both,

Please advise status of report.

Regards,
Steve Lim

DID.: +65 6829 9197
Fax.: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Tuesday, 10 July, 2018 4:47 PM
To: Steve Lim; Survey Report (ERGO Insurance Pte. Ltd.); sur@lkkauto.com
Cc: 'assignments'
Subject: RE: SKD6387T / TP : SBU51T/LKK / DOA : 05/02/2018 (DSMPC1800248/SL)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 12:00
Date Of Accident	05/02/2018 13:00
Exact Location Of Accident	JUNCTION OF STADIUM CRESENT & STADIUM WALK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBU51T
Insured/Policyholder	
Name Of Registered Owner	IBUILDERS PTE LTD
Co Reg No	200509473D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-60000000

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C250-1.8 CGI BLUEEFFICIENCY (C204) (A)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA024829/1
Cover Note Number	

Driver

Name of Driver	TAN KOK THYE
NRIC No	S2613100F
Date Of Birth	18/04/1946
Occupation	INDOOR
Date Of Driving Pass	26/04/1974
Driving Experience	43 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96695334
Fax Number	
Contact Number	
Email Address	KTTAN@IBUILDERS.SG

Address	BLK 223 SERANGOON AVE 4 #12-185
Postcode	550223
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WENDY TAN SOON HWA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD6387T
Vehicle Make/Model/Colour	BWM
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

1. Police report integrity the nature of the incident to speed up the claim process.
2. This form must be completed by the Police officer and/or the Insurance company.
3. Information provided must be as truthful and accurate as possible. Any fraud or misrepresentation may allow insurers to deny or postpone any liability.
4. The issue and existence of this liability shall be complete as stated on the Police Officer's report and Insurance company's report.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurer to the GIA Records Manager who will be circulating the Police Officer's Association of Singapore (GIA) for review and that report of this report will for a case may make make a claim and submit to the interested parties.
7. By reimbursement of this report to the insurer, it is only to make a claim and submit to the insurer and the claim is not the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA).

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of:

limiting output for dealing with my instructions or responding to my style, if I have the

by administering my claims (including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to the bank about, delivery of the same as well as doing the internal support of my claims) and not disclose to the bank

For the 1995-96 requirements and comparisons, see the next page.




Copyright © 1997 by John Wiley & Sons, Inc.

¹⁰ For a detailed discussion of driver's use of the polynomial fit, see Table 8, Figure 1.

1. Project Name
 2. Project Number
 3. Project Description
 4. Project Location
 5. Project Status
 6. Project Manager
 7. Project Sponsor
 8. Project Budget
 9. Project Timeline
 10. Project Risks
 11. Project Deliverables
 12. Project Stakeholders
 13. Project Communication
 14. Project Reporting
 15. Project Review
 16. Project Closure
 17. Project Archiving
 18. Project Evaluation
 19. Project Improvement
 20. Project Success

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/02/2018 at about 1300 hrs at Junction of Stadium Crescent and Stadium Walk. I was travelling on the extreme Right Lane along Stadium Crescent and when coming towards the junction of Stadium Walk, a vehicle (B) exited out without stopping and without giving way to my on coming vehicle hence collided onto my whole Right Portion of my vehicle (A) causing damages to my vehicle. I have one passengers inside my vehicle.

(A) SRU 51 T

(B) SKD 6384 T

DECLARATION

I hereby declare that the above information is true and correct.

Signature
Date & Time



Signature
Date & Time

Signature
Date & Time

3713 10 90

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: ERGO INSURANCE	DATE	: 06/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<i>Denise</i>			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SBU51T		
MODEL	: MERCEDES BENZ E250	<i>WDD2120472A070708</i>	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE	: 5-Feb-18		
TIME	: 13:00HRS		
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Ryic</i>	1	\$ 1,700.00	\$ 1,700.00
2	SIDE SKIRT RH <i>Best Wheel</i>	1	\$ 855.00	\$ 855.00
3	REAR DOOR RH <i>Best Wheel</i>	1	\$ 1,630.00	\$ 1,630.00
4	REAR DOOR LOCK <i>Best</i>	1	\$ 320.00	\$ 320.00
5	REAR DOOR CATCH <i>Best</i>	1	\$ 96.00	\$ 93.00
6	REAR DOOR WEATHERSTRIP <i>Best</i>	1	\$ 310.00	\$ 310.00
7	REAR DOOR OUTER CHROME PROTECTOR <i>Best</i>	1	\$ 103.00	\$ 103.00
8	REAR DOOR INNER BOARD <i>Best</i>	1	\$ 1,030.00	\$ 1,030.00
9	REAR DOOR GLASS REGULATOR <i>Best</i>	1	\$ 530.00	\$ 530.00
10	REAR DOOR POWER WINDOW MOTOR <i>Best</i>	1	\$ 655.90	\$ 655.90
11	REAR KNUCKLE ARM <i>Best</i>	1	\$ 1,200.00	\$ 1,200.00
12	REAR WHEEL HUP WITH BEARING <i>Best</i>	1	\$ 630.00	\$ 630.00
13	REAR UPPER ARM <i>Best</i>	1	\$ 520.00	\$ 520.00
14	REAR SHOCK ABSORBER <i>Best</i>	1	\$ 820.00	\$ 820.00
15	REAR LOWER ARM (STRAIGHT) <i>Best</i>	1	\$ 520.00	\$ 520.00
16	REAR LOWER ARM (BENT) <i>Best</i>	1	\$ 490.00	\$ 490.00
17	REAR ADJUSTABLE ARM <i>Best</i>	1	\$ 520.00	\$ 520.00
18	REAR STABILIZER LINKAGE <i>Best</i>	1	\$ 180.00	\$ 180.00

561
198
460
295
258
185

19	REAR STABILIZER BAR <i>1st</i>	1	\$ 290.00	\$ 290.00
20	REAR STABILIZER BAR BUSH <i>1st</i>	1	\$ 90.00	\$ 90.00
21	REAR FENDER RH <i>Dislaid</i>	1	\$ 1,600.00	\$ 1,600.00
22	REAR FENDER INNER COWLING <i>2nd</i>	1	\$ 198.00	\$ 198.00
23	REAR BUMPER <i>Pyro torn</i>	1	\$ 1,593.00	\$ 1,593.00

TOTAL PRICE \$ 15,930.90

LESS 10% \$ 1,593.09

SUB TOTAL PRICE \$ 14,337.81

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR FENDER INNER COWLING CLIPS(SET) <i>1st</i>	1	\$ 20.00	\$ 20.00
2	REAR DOOR INNER BOARD CLIPS(SET) <i>1st</i>	1	\$ 20.00	\$ 20.00
3	SIDE SKIRT CLIPS(SET) <i>1st</i>	1	\$ 20.00	\$ 20.00
4	REAR BUMPER CLIP(SET) <i>1st</i>	1	\$ 20.00	\$ 20.00
5	WHEEL TYRE <i>1st Purchased</i>	1	\$ 1,300.00	\$ 1,300.00
6	WHEEL RIM <i>1st</i>	1	\$ 2,800.00	\$ 2,800.00

990 TOTAL \$ 4,420.00

4180

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,800.00	800	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,400.00	1000	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 120.00	30	
5	TO REMOVE AND REFIX FRONT & REAR DOOR <i>ittings</i>	\$ 250.00	80	
6	TO REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	220	
7	WHEEL ALIGHMENT	\$ 100.00	30	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	4	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL	\$ 280.00	100	
10	RESET REVERSE SENSOR WIRE	\$ 120.00	4	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL

\$4,550.00

2360

ESTIMATE REPORT

TOTAL PARTS COST: \$

18,457.81

TOTAL LABOUR COST: \$

4,550.00

Adrian Ling

L/S 06/02/18.

07 Days.

total 124562

L/S 9.9K

9.9K

TOTAL REPAIR COST: \$ 23,067.81

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

10,700.10
+ 9040.00
+ 2,360.00

14,100.10
+ 2,800.00

11,280.08

Lump Sum
\$ 11,250.00
7 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18002360/Atbs2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 26-07-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKD 6387T	Veh. Inspected	SBU 51T
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800248/SL	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2120472A070708	Colour	BRONZE
Odometer	219278	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45R17	MICHELIN	6 mm
L/H Front Tyre	245/45R17	MICHELIN	6 mm
R/H Rear Tyre	245/45R17	MICHELIN	6 mm
L/H Rear Tyre	245/45R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/02/2018	Inspection Date	06/02/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 51T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,700.00	-
1	SIDE SKIRT RH	DEFORMED	855.00	855.00
1	REAR DOOR RH	DISTORTED	1,680.00	1,680.00
1	REAR DOOR LOCK	DAMAGED	320.00	320.00
1	REAR DOOR CATCH	NOT NECESSARY	96.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	310.00	310.00
1	REAR DOOR OUTER CHROME PROTECTOR	DENTED	103.00	103.00
1	REAR DOOR INNER BOARD	NOT NECESSARY	1,030.00	-
1	REAR DOOR GLASS REGULATOR	DAMAGED	530.00	530.00
1	REAR DOOR POWER WINDOW MOTOR	NOT NECESSARY	655.90	-
1	REAR KNUCKLE ARM	BENT	1,200.00	1,200.00
1	REAR WHEEL HUP WITH BEARING	NECESSARY	630.00	561.00
1	REAR UPPER ARM	BENT	520.00	198.00
1	REAR SHOCK ABSORBER	BENT	820.00	460.00
1	REAR LOWER ARM (STRAIGHT)	BENT	520.00	295.00
1	REAR LOWER ARM (BENT)	BENT	490.00	258.00
1	REAR ADJUSTABLE ARM	BENT	520.00	155.00
1	REAR STABILIZER LINKAGE	NOT NECESSARY	180.00	-
1	REAR STABILIZER BAR	NOT NECESSARY	290.00	-
1	REAR STABILIZER BAR BUSH	NOT NECESSARY	90.00	-
1	REAR FENDER RH	DISTORTED	1,600.00	1,600.00
1	REAR FENDER INNER COWLING	DEFORMED	198.00	198.00
1	REAR BUMPER	TORN	1,593.00	1,395.00
	LESS 10% DISCOUNT		-1,593.09	-1,011.80
			14,337.81	9,106.20
SPECIAL NETT ITEMS				
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR DOOR INNER BOARD CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET SIDE SKIRT CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00

Report Ref No. CS/EGI18002360/Atbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL TYRE (SN)	PUNCTURE	1,300.00	250.00
1	WHEEL RIM (SN)	CUT	2,800.00	700.00
			4,180.00	990.00
	LABOUR			
	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		1,600.00	800.00
	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS.		1,400.00	1,000.00
	TUFF COAT.		250.00	50.00
	WIRING CHECK.		120.00	30.00
	TO REMOVE AND REFIX FRONT & REAR DOOR FITTINGS.		250.00	80.00
	TO REMOVE AND REFIX REAR UNDERCARRIAGE.		350.00	220.00
	WHEEL ALIGNMENT.		100.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL.		280.00	100.00
	RESET REVERSE SENSOR WIRE HARNESS.	NOT NECESSARY	120.00	-
			4,550.00	2,360.00
GRAND TOTAL			23,067.81	12,456.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,900.00

Report Ref No. CS/EGI18002360/Atbs2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.