

22/03/2002

ASS. REC. BY:

REF:

CS/EGL18002362/Agbm

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 06/02/2018 3:31pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SCV 77126 Insured: XD 9019H

at Workshop m/s New Hock Teck Tel: 6747 9241

of Bille 1 Kaki Bulkit Ave 6 #01-43

Policy No: Claim No: XD9019H/SA/pl

Sum Insured: Excess:

Make of Veh: D.O.A. 05/02/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp' H.O.D. Endorsement:

Date/Time: 06/02/2018 3:57pm Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SCV 77126 - X
	XD 9019H - X
09/2/18 @	10.06am informed SITI, we are pending estimate from repairer.
18/5/18 @	11.34am revised to SITI by email.
	submit US \$7500, 5 days (Red \$12855.90, 84%)
19/7/18 @	10.46am checked with SITI, the vehicle has not repair due to liability unclear.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCV 7712 G. Yr Regn: 1999 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: _____

Make: Toyota Corolla C.C. 1332Colour: Green A/C: Insured / Std / NI / NASp. Reading: 324068 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: EE1115050675Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R14R: 185/60R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 07/02/18Survey held at NHTDes. of Damages: Frt / Rear (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ergo

COE Expiry: 2019 Jan.

RECEIVED 20 JUL 2018

MV: 61K
PV: 750
Nett: 5250

Date/Time, File Pass to?

☐ : Preli. Report

11/9/2 turnst

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: TPLump Sum / I.B.I: (\$ 7500)

350

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18002362/Aqb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 06-02-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9019H	Veh. Inspected	SCV 7712G	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD9019H/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/02/2018	Inspection Date	06/02/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD9019H/SA/pl

Date: 18th May 2018

Our Ref: CS/EGI18002362/Aqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Siti

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCV 7712G .


We thank you for the instruction on 06/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/02/2018 at the premises of M/s NEW HOCK TECK and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,359.90</u> .
Revised Estimate Amount	: S\$ <u>2,500.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 6 February, 2018 3:31 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018
Attachments: SCV7712G - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR WORKSHOP**,

ADDRESS : 1 KAKI BUKIT AVE 6
BLK C #01-43 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUKYI / REENA @ 6747 9241

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 06.02.2018
Our Reference: XD 9019H/SA/pl
Your Reference: SCV 7712G
To: NEW HOCK TECK MOTOR WORKSHOP

Sent via Fax

6741 7276

or

Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SCV 7712G
Insured's Vehicle: XD 9019H
Date Of Accident: 05.02.2018



We acknowledge receipt of your request for PRS on: 06.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	LB.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us today.
- ☒ Others: OFFICER-IN-CHARGE - SITI

Prepared by: 
Signature:  Pei Li 6829 9194 claims@ergo.com.sg
FAX: 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

ERGO

Date: 06.02.2018
Our Reference: XD 9019H/SA/pl
Your Reference: SCV 7712G

Sent via Fax

6741 7276

or

Email

To:

NEW HOCK TECK MOTOR WORKSHOP**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: SCV 7712G
Insured's Vehicle: XD 9019H
Date Of Accident: 05.02.2018


We acknowledge receipt of your request for PRS on: 06.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input checked="" type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - SITI</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:**Assessor attended workshop on:**

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 18 May 2018 11:39 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); 'Siti A Thikah AB Rahman'
Cc: SUR; assignments
Subject: RE: XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018
Attachments: CSEGI18002362Aqb.pdf

Dear Siti,

Enclosed herewith preliminary advice of SCV 7712G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 February 2018 10:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; 'Siti A Thikah AB Rahman' <siti.rahman@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018

Dear Siti,

Please be informed that we have inspected the vehicle SCV 7712G on 07/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 February 2018 4:27 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 February 2018 10:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; 'Siti A Thikah AB Rahman'
Cc: SUR; assignments
Subject: RE: XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018

Dear Siti,

Please be informed that we have inspected the vehicle SCV 7712G on 07/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 February 2018 4:27 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 6 February, 2018 3:31 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XD9019H / TP : SCV7712G/LKK / DOA : 05/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR WORKSHOP**,

ADDRESS

: 1 KAKI BUKIT AVE 6
BLK C #01-43 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8970H

Vehicle Details

Vehicle No.: SCV7712G

Vehicle to be Exported: No

Intended De-registration Date: 06 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA 1.3M

Primary Colour: Green

Manufacturing Year: 1998

Engine No.: 4E2720209

Chassis No.: EE1115050675

Maximum Power Output: -

Open Market Value: \$13,616.00

Original Registration Date: 02 Jan 1999

First Registration Date: 02 Jan 1999

Transfer Count: 1

Actual ARF Paid: \$19,063.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$8,195.00
COE Rebate Amount:	\$740.00
Total Rebate Amount:	\$740.00

The information contained herein is correct as at 06 Feb 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

NG NGOH HENG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/02/2018

TPEgo

xiao chun

EE1115050675

Accident date: 05/02/2018

Estimated repair cost for vehicle no: SCV7712G TOYOTA COROLLA 1.3 M '99

CHASSIS: EE1115050675

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid		\$799.90
2	2	Rear Boot Lid Hinge	\$79.90	\$159.80
3	1	Rear Boot Lid Emblem Logo		\$59.90
4	1	Rear Boot Lid Xli Logo		\$59.90
5	1	Rear Boot Lid Toyota Logo		\$59.90
6	1	Rear Boot Lid Corolla Logo		\$59.90
7	2	Rear Boot Lid Side Reflector	\$89.90	\$179.80
8	1	Rear Boot Lid Inner Lock		\$298.90
9	1	Rear Boot Lid Inner Rubber		\$169.90
10	1	Rear R/H Tail Lamp		\$489.90
11	4	Rear R/H Tail Lamp Clip	\$8.00	\$32.00
12	1	Rear R/H Tail Lamp Panel		\$269.90
13	1	Rear R/H Tail Lamp Lower Panel		\$389.90
14	4	Rear R/H Tail Lamp Lower Panel Rivet	\$6.90	\$27.60
15	1	Rear Bumper		\$798.90
16	8	Rear Bumper Clip	\$6.90	\$55.20
17	1	Rear Bumper Beam		\$289.90
18	1	Rear R/H Bumper Side Retainer		\$79.90
19	1	Rear R/H Bumper Mud Flap		\$179.90
20	1	Rear End Panel		\$898.90
21	1	Rear End Panel Top Garnish		\$259.90
22	1	Rear R/H Fender		\$1,045.90
23	1	Rear R/H Fender Air Duct		\$89.90
24	1	Rear R/H Fender Inner Panel		\$629.80
25	1	Rear R/H Fender Inner Trim Board		\$649.90
26	8	Rear R/H Fender Inner Trim Board Clip	\$6.90	\$55.20
27	1	Rear R/H Rim (Special Nett)		\$650.00
28	1	Rear R/H Tyre (Special Nett)		\$450.00

29	1	Rear R/H Lower Arm	2	\$279.90	x
30	1	Rear R/H Knuckle Arm	2	\$339.90	x
31	1	Rear R/H Knuckle Arm Bearing	1	\$249.90	x
32	1	Rear R/H Shock Absorber	1	\$289.90	x
33	1	Rear R/H Stabilizer Bar	1	\$129.90	x
34	1	Rear Windscreen Moulding	1	\$149.90	✓

2051.60
1538.70

Subtotal:- \$10,629.90

Labour charges

To remove & refit cushion	\$280.00	60
To remove & refit rear windscreen	\$120.00	100
Gum	\$50.00	✓
To remove & refit rear R/H undercarriage	\$380.00	x
To check wheel alignment	\$150.00	x
To check wiring	\$100.00	30
Towing fee	\$100.00	x
Tuff kote	\$150.00	40
Panel beating	\$1,800.00	60
Spray painting	\$1,600.00	60
Subtotal:-	<u>\$4,730.00</u>	

Total:- \$15,359.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3118.70
L/S: 2.5K
05 Days.
2.5K
05 Days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18002362/Aqbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 20-07-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9019H	Veh. Inspected	SCV 7712G	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD9019H/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	1999	
Chassis No.	EE1115050675	Colour	GREEN	
Odometer	324068	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R14	MICHELIN	6 mm	
L/H Front Tyre	185/60 R14	MICHELIN	6 mm	
R/H Rear Tyre	185/60 R14	MICHELIN	6 mm	
L/H Rear Tyre	185/60 R14	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2018	Inspection Date	07/02/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCV 7712G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	NOT NECESSARY	799.90	-
2	REAR BOOT LID HINGE @\$79.90	NOT NECESSARY	159.80	-
1	REAR BOOT LID EMBLEM LOGO	NOT NECESSARY	59.90	-
1	REAR BOOT LID XLI LOGO	NOT NECESSARY	59.90	-
1	REAR BOOT LID TOYOTA LOGO	NOT NECESSARY	59.90	-
1	REAR BOOT LID COROLLA LOGO	NOT NECESSARY	59.90	-
2	REAR BOOT LID SIDE REFLECTOR @\$89.90	NOT NECESSARY	179.80	-
1	REAR BOOT LID INNER LOCK	NOT NECESSARY	298.90	-
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	169.90	-
1	REAR R/H TAIL LAMP	CRACKED	489.90	350.10
4	REAR R/H TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	10.00
1	REAR R/H TAIL LAMP PANEL	DENTED	269.90	125.40
1	REAR R/H TAIL LAMP LOWER PANEL	DEFORMED	389.90	70.50
4	REAR R/H TAIL LAMP LOWER PANEL RIVET @\$6.90	NECESSARY	27.60	10.00
1	REAR BUMPER	DEFORMED	798.90	493.00
8	REAR BUMPER CLIP @\$6.90	NECESSARY	55.20	30.00
1	REAR BUMPER BEAM	NOT NECESSARY	289.90	-
1	REAR R/H BUMPER SIDE RETAINER	DAMAGED	79.90	35.20
1	REAR R/H BUMPER MUD FLAP	NOT NECESSARY	179.90	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	898.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	259.90	-
1	REAR R/H FENDER	DISTORTED	1,045.90	757.50
1	REAR R/H FENDER AIR DUCT	NOT NECESSARY	89.90	-
1	REAR R/H FENDER INNER PANEL	TO REPAIR SEE LABOUR	629.80	-
1	REAR R/H FENDER INNER TRIM BOARD	NOT NECESSARY	649.90	-
8	REAR R/H FENDER INNER TRIM BOARD CLIP @\$6.90	NOT NECESSARY	55.20	-
1	REAR R/H LOWER ARM	NOT NECESSARY	279.90	-
1	REAR R/H KNUCKLE ARM	NOT NECESSARY	339.90	-
1	REAR R/H KNUCKLE ARM BEARING	NOT NECESSARY	249.90	-

Report Ref No. CS/EG18002362/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR R/H SHOCK ABSORBER	NOT NECESSARY	289.90	-
1	REAR R/H STABILIZER BAR	NOT NECESSARY	129.90	-
1	REAR WINDSCREEN MOULDING	NECESSARY	149.90	149.90
	LESS 25% DISCOUNT		-	-507.90
			9,529.90	1,523.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR R/H RIM (SN)	NOT NECESSARY	650.00	-
1	REAR R/H TYRE (SN)	NOT NECESSARY	450.00	-
1	GUM (SN)	NECESSARY	50.00	50.00
			1,150.00	50.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		280.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	100.00
	TO REMOVE & REFIT REAR R/H UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR R/H FENDER INNER PANEL.		1,800.00	650.00
	SPRAY PAINTING.		1,600.00	650.00
			4,680.00	1,530.00
	GRAND TOTAL		15,359.90	3,103.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS/EGI18002362/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.