

20/03/2001

REF: CS/FCI18002366/Ad3⁷² Special Instruction:

ASS. REC. BY:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Lureng jawof FCIDate/Time: 5/2/18 @ 3:15pm

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No:

SKN 7010X

Insured:

SHC 7229B

at Workshop m/s:

T&C Automotive

Tel:

67415197 / 90075148

of

No. 1 Kaki Bkt Ave 6 # 01-171 Autobay

Policy No:

Claim No:

D18001052 MFSH

Sum Insured:

Excess:

D.O.A.

4/2/18

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time: 2:36pm @ 6/2/18

Person Contacted:

Ah ChaiVehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SKN 7010X - xSHC 7229B - xlump sum \$5200/- CRed 889690; 73%
3200.

Summary

REF:

ASSIGNMENT

05/05/08
2008 May

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKN 2010X Yr Regn: 2008 May
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota AHIS c.c. 1598
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 172394 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MROS3ZEE106108088
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: 195/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Haida
Front _____ Rear _____
R/Bal. 06 mm R/Bal. 06 mm
L/Bal. 06 mm L/Bal. 06 mm
D.O.A. _____ D.O.I. 06/02/18
Survey held at T and C.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TP 1st Cap.

MV: 12500/- LTA: 8764 NV: 3736

MV: 12.51K
PV: 8.8K.
Nett: 3.7K

RECEIVED 09 NOV 2018

Date/Time, File Pass to? _____
1/9/11 Typist
Date/Time, File Return to? _____
2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 7
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS: _____
Photos _____
Others _____

Report Format: TP
Lump Sum / I.B.I: (\$ 1,3200)

TOTAL

2x15: 30
170+30
50
50
50
350

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002366/Atd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7229B	Veh. Inspected	SKN 7010X
Policy No.		Coverage (\$)	0.00
Claim No.	D18001052MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/02/2018	Inspection Date	06/02/2018
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-02-2018	Our Ref No. D18001052MFSH
Accident Date	04-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7229B	Third Party Vehicle. SKN7010X
Survey Location	NO 1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY	
Contact Person.	NA	
Contact No.	67415197/ 67415197	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	T&C AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	ONG & SHAN LLC	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234647)



PRI Documents



Close



PRI Header Details

Claim No	D18001052MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ONG & St
Workshop Name	T&C AUTOMOTIVE (Contact Person : NA)	Survey Location & Contact Details	NO 1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY Mobile: 67415197 , Phone: 67415197 , Fax: 0 EmailId: ONGSHANLLC@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7229B	TP Vehicle No	SKN7010X
PRI Recieved Date	05-02-2018 04:21:26 PM	Surveyor Appointed Date	05-02-2018 03:14:34 PM	Surveyor Accept Date	06-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68% P.A. @ GV Cars Financing.
GV Credit Pte Ltd [StarAd](#)


[Browse by Category](#)
[Back \(1 2 3 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

60 vehicles

altis

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	altis	Any	Any	2008	Any	Any	Any	Available



Toyota Corolla Altis 1.6A

\$13,800

N.A

06-Jun-2008

1,598 cc

-

Sedan

Available

\$0 Drive Away! Free Insurance, Unlimited Warranty! High Trade In! Very Well Kept By Previous Owner! View To Believe! An Elegant Styled Sedan Known For Its Reliability And Comes With Roomy Interior Too...

Dickson Automobile

Posted: 04-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$36,800

\$7,360 /yr

18-Jun-2008

1,598 cc

-

Sedan

Available

Low Interest By In House Financing. 100% Loan Approval. Well Maintained, Good Condition, Fuel Efficient And Reliable Mid Sized Sedan.

Posted: 29-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$38,800

\$7,760 /yr

23-Jun-2008

1,598 cc

-

Sedan

Available

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 21-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$38,788

\$7,750 /yr

23-Jun-2008

1,598 cc

147,016 km

Sedan

Available

We Are The COE Specialist, No Gimmicks, Honest Dealing, 2008 New Facelift Model, 2 Owners With Low Mileage Clock, Car In Superb Condition, No Repairs Needed, High Loan With \$3000 Down Payment Drive Aw...

Posted: 09-Dec-2017 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM AD

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)


Toyota Corolla Altis 1.6A

\$14,200

N.A

25-Jun-2008

1,598 cc

-

Sedan

Available

5 Year COE Renewal At \$36.8K, Careful Owner, Immaculate Condition, Low Depreciation, Low Mileage, Value For Money, High Trade In, View To Believe, Price Negotiable. Call Now.

Posted: 03-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE)

\$38,800

\$7,760 /yr

17-Jul-2008

1,598 cc

103,500 km

Sedan

Available

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!

Boeki Auto & Marine

Posted: 25-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$15,800

\$14,620 /yr

12-Aug-2008

1,598 cc

120,000 km

Sedan

Available

Posted: 03-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

DIRECT OWNER

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9705W
Vehicle Details	
Vehicle No.:	SKN7010X
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4763148
Chassis No.:	MR053ZEE106108088
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	05 May 2008
First Registration Date:	05 May 2008
Transfer Count:	3
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 May 2018
PARF Rebate Amount:	\$8,388.00
Intended COE Rebate Details	
COE Expiry Date:	04 May 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,600.00
COE Rebate Amount:	\$376.00
Total Rebate Amount:	\$8,764.00

The information contained herein is correct as at 07 Feb 2018

ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49, SINGAPORE 417883

MR053ZEE106108088

Date : 06/02/2018

Vehicle no.: SKN7010X

Chassis no.: MR053ZEE106108088

TP 1st Cap.
Denise.

Descriptions	Qty	Unit Price	Amount
Spare Parts			
Rear bumper <i>Distorted</i>	1	\$587.81	\$587.81 ✓
Rear bumper clip <i>new</i>	10	\$4.30	\$43.00 20
Rear bumper side retainer RH (long) <i>new</i>	1	\$75.70	\$75.70 ✓
Rear bumper side retainer RH (short) <i>new</i>	1	\$69.80	\$69.80 ✓
Rear bumper corner retainer RH (L) <i>new</i>	1	\$72.10	\$72.10 ✓
Rear bumper side retainer LH (long) <i>new</i>	1	\$75.70	\$75.70 ✓
Rear bumper side retainer LH (short) <i>new</i>	1	\$69.80	\$69.80 ✓
Rear bumper corner retainer LH (L) <i>new</i>	1	\$72.10	\$72.10 ✓
Rear bumper reinforcement <i>Dist</i>	1	\$379.30	\$379.30 ✓
Rear bumper foam <i>cracked</i>	1	\$123.50	\$123.50 ✓
Rear bumper bracket RH <i>new</i>	1	\$85.00	\$85.00 ✓
Rear bumper bracket LH <i>Dist</i>	1	\$85.00	\$85.00 ✓
Rear bumper reflector RH <i>new</i>	1	\$46.50	\$46.50 ✓
Rear bumper reflector LH <i>new</i>	1	\$46.50	\$46.50 ✓
Rear boot lid <i>Dist</i>	1	\$731.70	\$731.70 639.40
Rear boot lid lock <i>Dist</i>	1	\$155.60	\$155.60 ✓
Rear boot lid lower catch <i>new</i>	1	\$25.10	\$25.10 ✓
Rear boot lid "Corolla" emblem <i>new</i>	1	\$47.26	\$47.26 ✓
Rear boot lid "Altis" emblem <i>new</i>	1	\$55.80	\$55.80 ✓
Rear boot lid "1.6" emblem <i>new</i>	1	\$55.80	\$55.80 ✓
Rear boot lid "Toyota" logo <i>new</i>	1	\$58.30	\$58.30 ✓
Rear boot lid weatherstrip <i>it</i>	1	\$166.40	\$166.40 ✓
Rear boot lid reflector LH <i>cracked</i>	1	\$181.50	\$181.50 ✓
Tail lamp LH <i>cracked</i>	1	\$442.30	\$442.30 364.50
Tail lamp panel LH <i>Dist</i>	1	\$83.50	\$83.50 ✓
Tail lamp lower bracket LH <i>Dist</i>	1	\$56.20	\$56.20 ✓
Tail lamp gasket LH <i>new</i>	1	\$25.20	\$25.20 ✓
Rear fender LH	1	repair	repair
Rear fender inner garnish LH <i>new</i>	1	\$351.70	\$351.70 ✓
Rear fender inner garnish clip <i>new</i>	10	\$4.30	\$43.00 ✓
Rear air vent LH <i>cracked</i>	1	\$128.00	\$128.00 ✓
Rear end panel <i>Dist</i>	1	\$580.60	\$580.60 ✓
Rear end panel garnish <i>new</i>	1	\$198.38	\$198.38 ✓
Rear end panel garnish clip <i>new</i>	10	\$4.30	\$43.00 ✓
Spare tyre panel <i>new</i>	1	\$857.00	\$857.00 ✓
Spare tyre board <i>new</i>	1	\$348.10	\$348.10 ✓
			\$6,466.25
		Less 25%	\$1,616.56
		Sub Total 1	\$4,849.69

Special Nett

Reverse sensor (set) <i>Dist</i>	1	\$280.00	\$280.00 200
Rear number plate <i>new</i>	1	\$35.00	\$35.00 ✓
Rear number plate casing <i>new</i>	1	\$50.00	\$50.00 ✓
		Sub-Total 2	\$365.00

200

Descriptions	Unit Price	Amount
Labour		
Panel beating and straighten affected parts/area.		\$1,400.00 1000
Putty and spray painting affected parts/area.	2030	\$1,400.00 2000
Spray anti-rust undercoat.		\$150.00 40
Check wiring.		\$120.00 30
Remove, refit/replace rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repair.		\$350.00 60
Total Labour		\$3,420.00
Total Cost		\$8,634.69

12096.90

Supplementary: 44047

total: 6632.34

h/s: S.3K

07 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.3K

07 days

ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49, SINGAPORE 417883

Date :

Vehicle no.: SKN7010X

Chassis no.: MR053ZEE106108088

Descriptions	Qty	Unit Price	Amount	
Spare Parts				
Rear end panel <i>Repaired.</i>	1	\$781.40	\$781.40 <i>x.</i>	987.30
Rear fender LH <i>Replaced.</i>	1	\$987.30	\$987.30 <i>✓</i>	740.47
Tail lamp panel LH <i>Repaired.</i>	1	\$278.20	\$278.20 <i>x.</i>	
			\$2,046.90	
		Less 10%	\$204.69	
		Sub Total 1	\$1,842.21	
Labour				
To remove and refit rear windscreen glass.			\$120.00 <i>-100.</i>	700.
Panel beating and straighten affected parts/area.			\$800.00 <i>400.</i>	
Putty and spray painting affected parts/area.			\$700.00 <i>-200.</i>	
		Total Labour	\$1,620.00	
		Total Supplementary Repair Cost	\$3,462.21	

Supplementary: 1440.47



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002366/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7229B	Veh. Inspected	SKN 7010X
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D18001052MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign Date	05/02/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053ZEE106108088	Colour	GREY
	Odometer	172394	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	HAIDA	6 mm
	L/H Front Tyre	195/65 R15	HAIDA	6 mm
	R/H Rear Tyre	195/65 R15	HAIDA	6 mm
	L/H Rear Tyre	195/65 R15	HAIDA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/02/2018	Inspection Date	06/02/2018
	Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 7010X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	587.81	587.81
10	REAR BUMPER CLIP @\$4.30	NECESSARY	43.00	30.00
1	REAR BUMPER SIDE RETAINER RH (LONG)	NOT NECESSARY	75.70	-
1	REAR BUMPER SIDE RETAINER RH (SHORT)	NOT NECESSARY	69.80	-
1	REAR BUMPER CORNER RETAINER RH (L)	NOT NECESSARY	72.10	-
1	REAR BUMPER SIDE RETAINER LH (LONG)	DAMAGED	75.70	75.70
1	REAR BUMPER SIDE RETAINER LH (SHORT)	DAMAGED	69.80	69.80
1	REAR BUMPER CORNER RETAINER LH (L)	NOT NECESSARY	72.10	-
1	REAR BUMPER REINFORCEMENT	BENT	379.30	379.30
1	REAR BUMPER FOAM	CRACKED	123.50	123.50
1	REAR BUMPER BRACKET RH	NOT NECESSARY	85.00	-
1	REAR BUMPER BRACKET LH	DENTED	85.00	85.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	46.50	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	46.50	-
1	REAR BOOT LID	DENTED	731.70	639.40
1	REAR BOOT LID LOCK	DAMAGED	155.60	155.60
1	REAR BOOT LID LOWER CATCH	NOT NECESSARY	25.10	-
1	REAR BOOT LID "COROLLA" EMBLEM	NECESSARY	47.26	47.26
1	REAR BOOT LID "ALTIS" EMBLEM	NECESSARY	55.80	55.80
1	REAR BOOT LID "1.6" EMBLEM	NECESSARY	55.80	55.80
1	REAR BOOT LID "TOYOTA" LOGO	NECESSARY	58.30	58.30
1	REAR BOOT LID WEATHERSTRIP	CUT	166.40	166.40
1	REAR BOOT LID REFLECTOR LH	CRACKED	181.50	181.50
1	TAIL LAMP LH	CRACKED	442.30	364.50
1	TAIL LAMP PANEL LH	DENTED	83.50	83.50
1	TAIL LAMP LOWER BRACKET LH	DAMAGED	56.20	56.20
1	TAIL LAMP GASKET LH	NECESSARY	25.20	25.20
1	REAR FENDER INNER GARNISH LH	NOT NECESSARY	351.70	-
10	REAR FENDER INNER GARNISH CLIP @\$4.30	NOT NECESSARY	43.00	-
1	REAR AIR VENT LH	CRACKED	128.00	128.00
1	REAR END PANEL	DENTED	580.60	580.60

Report Ref No. CS/FCI18002366/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL GARNISH	NOT NECESSARY	198.38	-
10	REAR END PANEL GARNISH CLIP @\$4.30	NOT NECESSARY	43.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	857.00	-
1	SPARE TYRE BOARD	NOT NECESSARY	348.10	-
	LESS 25% DISCOUNT		-1,616.56	-987.29
			4,849.69	2,961.88
1	REAR END PANEL (ADDITIONAL)	REPEATED	781.40	-
1	REAR FENDER LH (ADDITIONAL)	BUCKLED	987.30	987.30
1	TAIL LAMP PANEL LH (ADDITIONAL)	REPEATED	278.20	-
	LESS 10% DISCOUNT		-204.69	-
	LESS 25% DISCOUNT		-	-246.83
			1,842.21	740.47
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	REAR NUMBER PLATE CASING (SN)	NOT NECESSARY	50.00	-
			365.00	200.00
	LABOUR			
	PANEL BEATING AND STRAIGHTEN AFFECTED PARTS/AREA.		1,400.00	1,000.00
	PUTTY AND SPRAY PAINTING AFFECTED PARTS/AREA.		1,400.00	900.00
	SPRAY ANTI-RUST UNDERCOAT.		150.00	40.00
	CHECK WIRING.		120.00	30.00
	REMOVE,REFIT/REPLACE REAR SEATS,REAR WHEELHOUSE INNER GARNISH,FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIR.		350.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS. (ADDITIONAL).		120.00	100.00
	PANEL BEATING AND STRAIGHTEN AFFECTED PARTS/AREA. (ADDITIONAL).		800.00	400.00
	PUTTY AND SPRAY PAINTING AFFECTED PARTS/AREA. (ADDITIONAL).		700.00	200.00
			5,040.00	2,730.00

Report Ref No. CS/FCI18002366/Atd3n2



GRAND TOTAL		12,096.90	6,632.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/FCI18002366/Atd3n2

MARKET VALUE: \$12,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,764.00=NETT VALUE: \$3,736.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.