

# ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49, SINGAPORE 417883

Date :

Vehicle no.: SKN7010X

Chassis no.: MR053ZEE106108088

Descriptions	Qty	Unit Price	Amount	
<b>Spare Parts</b>				
Rear end panel <i>Repaired.</i>	1	\$781.40	\$781.40 <i>x</i>	987.30
Rear fender LH <i>Buckled.</i>	1	\$987.30	\$987.30 <i>✓</i>	740.47
Tail lamp panel LH <i>Repaired.</i>	1	\$278.20	\$278.20 <i>x</i>	
			<b>\$2,046.90</b>	
		Less 10%	\$204.69	
		<b>Sub Total 1</b>	<b>\$1,842.21</b>	
<b>Labour</b>				
To remove and refit rear windscreen glass.			\$120.00 <i>-100.</i>	700
Panel beating and straighten affected parts/area.			\$800.00 <i>400.</i>	
Putty and spray painting affected parts/area.			\$700.00 <i>-200.</i>	
		<b>Total Labour</b>	<b>\$1,620.00</b>	
		<b>Total Supplementary Repair Cost</b>	<b>\$3,462.21</b>	

*Supplementary: 1440.47*