

INS. CASE OWNER

ongli/i | CC 4, LPC 1800 2369; Kea3n2

FILE

DATE

Surveyor:

KSC

DOI:

6/2/18

Date / Time:

8/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJR 7723M

Claim No.:

17/18/18/VPOS-1020372

Name of Insured:

MUHAMMAD MUMAR BIN ABUL LATIFF

Policy No.:

2/17/VPOS/014477

Insured Tel No.:

HP: 8611 2704

Make / Model:

H. AVANTE-1-6(A)

Excess Sec II :SS

D.O.A: 4/2/18

Place of Accident:

KPE AFTER AIRPORT RD EXIT

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJR 7723M

SJR 2471Y

SJD 44120




INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: Accord Auto Tel: Liability: TP RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time		STAGE	DATE / PIC
13/2	SJR 7723M - X ; SJR 2471Y - X	Non-Reporting ltr (1st):	
AW		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
19/2/18	Email WSP LIABILITY CLAIM.	Call OI:	
		After call ltr to OI:	
8.5.18	FILE PASS TO TYPIST TO PREPARE REPORT.	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input checked="" type="checkbox"/>
		Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: 17/2/18 Sent By: HMM			
FINALIZATION Date/Time: - Confirm with: CEUA Confirm by: KSC			
Repair Cost: 46 S\$2,050 (3 days) Reduction: 71 %		Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 29-6-18 Confirm with: CEUA		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 38		If NO or B 28, Ass. Lia : 100%	
Repair Cost: 01/62 S\$2,193.50 3 VEM C-C OI LAPSI			
Loss of Rental (LOR): S\$ 960.00 (6 days) x +160			
Loss of Use (LOU): S\$ - (\$ x days)			
Loss of Income (LOI): S\$ - (\$ x days)			
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search S\$2.00			
Medical: S\$ -		1) Claim status: Normal/Reject/Private Settle	
Disbursement: S\$ - (e.g. Tow/ Independent)		2) Report Format: TP	
Legal Cost S\$ -		3) Survey fee: +50	
Total: S\$ 3,135.50	Global Sum S\$:		
FINAL PAYMENT Date/Time: 29-6-18 Confirm with: CEUA		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1: S\$ 3,135.50	Name 1: ACCORD AUTO SERVICES PTE LTD		
Payee 2: (Strike if N.A.) S\$	Name 2:		
Payee 3: (Strike if N.A.) S\$	Name 3:		

RECEIVED 05 JUL 2018

5/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18002369/Kea3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 06-02-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJR 7723M	Veh. Inspected	SJR 2471Y
Policy No.	Z/17/VP05/014477	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020372	Excess (\$)	0.00
Assign From		Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/02/2018	Inspection Date	06/02/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00890
Our ref: CC4/ASM18002215/R1ua3

Date: 12.02.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


GW 5253A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.02.2018 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$	13,198.37
Revised Estimate Amount	: S\$	10,556.58
"Check" Items Amount	: S\$	510.30
Total (Including Check Items)	: S\$	11,066.88
<hr/>		
Market Value	: S\$	9,000.00
LTA Reimbursement Value	: S\$	2,243.00
Nett Value	: S\$	6,757.00

Description of Damage:
The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 10.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

7369

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Monday, 5 February, 2018 4:51 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018
Attachments: 05022018163955.pdf; SAS2353179.pdf

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SJR 2471Y on without Prejudice Basis.

We look forward to receiving your report soon.

05022018 @ 5:03pm

Thank you

Jessy veh in
Kenneth

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]
Sent: Monday, 5 February, 2018 4:43 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: Re: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

Hi,

Please refer to attached and assist arrange PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 5 February 2018 at 16:37, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Jessy,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Accord Auto(Claims) [<mailto:claims@mycarworkshop.com.sg>]

Sent: Monday, 5 February, 2018 3:08 PM

To: GERALD POH WEE BIN

Cc: Gilbert Ng

Subject: Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

Dear Gerald,

Kindly assist arrange Pre-Repair Survey for SJR2471Y, vehicle in workshop.

Please provide us 10 surveyor name list.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Mei Kwan (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 12 February, 2018 11:48 AM
To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018
Attachments: 12022018114136.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan,

We attached a copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, 12 February, 2018 11:15 AM

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG; ONG LI LI; GERALD POH WEE BIN; Asher Sng (LKKAuto); Vic (LKKAuto); Admin A

Subject: RE: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

WITHOUT PREJUDICE

Your Ref : 17/18/18/VP05/020372
LKK Ref : CC4/LPC18002369/Kea3

Dear Sir /Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SJR 2471Y

Date of survey: 06.02.2018

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG

Subject: Re: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

Hi,

Please refer to attached and assist arrange PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 5 February 2018 at 16:37, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Jessy,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 19 February 2018 2:44 PM
To: Accord Auto(Claims); 'Accord Claims(AV)'
Cc: Vic (LKKAuto)
Subject: RE: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Auto(Claims) [<mailto:claims@mycarworkshop.com.sg>]

Sent: Monday, 5 February, 2018 4:43 PM

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG

Subject: Re: Our Ref: 17/18/18/VP05/020372 Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

Hi,

Please refer to attached and assist arrange PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 5 February 2018 at 16:37, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Jessy,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Accord Auto(Claims) [<mailto:claims@mycarworkshop.com.sg>]
Sent: Monday, 5 February, 2018 3:08 PM
To: GERALD POH WEE BIN
Cc: Gilbert Ng
Subject: Accident involving SJR2471Y, SJR7723M & SJD4412D ON 04/02/2018

Dear Gerald,

Kindly assist arrange Pre-Repair Survey for SJR2471Y, vehicle in workshop.

Please provide us 10 surveyor name list.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SJR2471Y
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	ACCORD 2.0L
Chassis No. :	MRHCP16308P020038
Propellant :	Petrol
Engine No. :	R20A31800036
Engine Capacity :	1997 cc
Maximum Power Output :	115.0 kW (154 bhp)
Maximum Laden Weight :	2000 kg
Unladen Weight :	1505 kg
Year Of Manufacture :	2008
Original Registration Date :	16 Jun 2009
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$11,889.00
COE Expiry Date :	15 Jun 2019
Road Tax Expiry Date :	15 Jun 2018
PARF Eligibility Expiry Date :	15 Jun 2019
Inspection Due Date :	15 Jun 2018

**SINGAPORE ARMED FORCES
IDENTITY CARD**

Name
TAY KUAN YONG

NRIC No
S7801839I

This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

REPUBLIC OF SINGAPORE DRIVING LICENCE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

09 Jan 1998

NP 428A

Barcode: 00001839I

SGO 80812578 13044518

NRIC No/Colour	Race	Blood Group
S7801839I / PINK	CHINESE	O+
Date Of Birth	Country Of Birth	Sex
14/02/1978	SINGAPORE	M
	Military Rank Status	
	MILITARY EXPERT M01381	

ADDRESS: APT BLK 553 HOUGANG STREET 51 #12-274 SINGAPORE S30553 DATE: 02.05.2017 S7801839I

Use governed by CaptiCard Terms & Conditions
1111020103912578

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

09 Jan 1998

NP 428A

Barcode: Licence No. S7801839I

\$98084

CERTIFICATE OF INSURANCE

• MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) • MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 • ROAD TRANSPORT ACT, 1987 (MALAYSIA) • MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE No. M0002779

1. **Index Mark and Registration Number of Vehicle** SJR2471Y

2. **Name of Policyholder** Tay Kuan Yong

3. **Effective Date of Commencement of Insurance for the purposes of the Act** 29/12/2017
 Excess: Named Drivers S\$450
 Excess: Unnamed Drivers S\$950

4. **Date of Expiry of Insurance** 28/12/2018

5. **Persons or Classes of Persons entitled to drive**

(A) THE POLICYHOLDER.
 THE POLICYHOLDER MAY ALSO DRIVE A MOTOR CAR NOT BELONGING TO HIM OR HIRED (UNDER A HIRE PURCHASE AGREEMENT OR OTHERWISE) TO HIM OR HIS EMPLOYER OR HIS PARTNER.
 (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

Tay Kuan Yong

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle.

6. **Limitations as to Use**

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
 THE POLICY DOES NOT COVER:
 (i) USE FOR HIRE OR REWARD.
 (ii) USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
 (iii) USE FOR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS.
 (iv) USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.



LQ SERVICES PTE LTD
 180B BENCOOLEN STREET
 #08-04 THE BENCOOLEN
 SINGAPORE 189648
 TEL: 6-333-4116 FAX: 6-333-4108
 Co. Reg. No: 201227819H

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these bindings.

Policy Owner's Protection Scheme

This policy is protected under the Policy Owner's Protection Scheme which is administered by the Singapore Deposit Insurance Corporation (SDIC). Coverage for your policy is automatic and no further action is required from you. For more information on the types of benefits that are covered under the scheme as well as the limits of coverage, where applicable, please contact your insurer or visit the GIA / LIA or SDIC websites (www.gia.org.sg or www.lia.org.sg or www.sdic.org.sg).

I/WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of Etiqa Insurance Pte. Ltd.
 Approved Insurer

Authorised Signature

GOP93167 12/12/2017 18:00:03



ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised ESTIMATE

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Accident Claims Department

*61 Sep @ ?
Resurvey After Paint
4-6 days*

Date : 05/02/2018
Vehicle No : SJR2471Y
Veh Make/Model : Honda Accord 2.0L
YOM : 2008
Chassis No : MRHCP16308P020038
Date of Accident : 04/02/2018

No	Qty	Description	Amount \$
List Items:-			
1	1	Rear bootlid	\$ <i>R</i> 878.10
2	1	Rear bootlid badge	\$ <i>M</i> 32.10
3	1	Rear bootlid "Accord" emblem	\$ <i>M</i> 28.20
4	1	Rear bootlid "i-VTEC" emblem	\$ <i>M</i> 33.20
5	1	Rear bootlid inner lock	\$ <i>R</i> 110.90
6	1	Rear bootlid weatherstrip	\$ <i>Sm</i> 85.00
7	2	Rear bootlid stopper	\$ <i>Sm</i> 18.00
8	1	Rear bootlid refelctor LH	\$ <i>Sm</i> 172.20
9	1	Rear bootlid refelctor RH	\$ <i>Sm</i> 172.20
10	1	LH taillamp	\$ <i>Sm</i> 295.80
11	1	RH taillamp	\$ <i>Sm</i> 295.80
12	1	Rear bumper	\$ <i>R</i> 630.50
13	2	Rear bumper side retainer	\$ <i>RIS D.I</i> 35.00
14	10	Rear bumper clip	\$ <i>M</i> 38.00
15	1	Rear bumper reinforcement	\$ 145.60
16	1	End panel	\$ 287.80
17	1	End panel top garnish	\$ 97.70
18	6	End panel top garnish clip	\$ 22.80
19	1	Rear floor panel board	\$ <i>Sm</i> 133.00
20	1	Front bumper	\$ <i>R</i> 976.00
21	2	Front bumper side retainer	\$ <i>Sm</i> 46.00
22	10	Front bumper clip	\$ 38.00
Total - List Item			\$ 4,571.90
Less 20%			\$ 914.38
Total			\$ 3,657.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ke

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

61 Sep @ 2050h
Resury Atee Paint
5-days

Date : 05/02/2018
Vehicle No : SJR2471Y
Veh Make/Model : Honda Accord 2.0L
YOM : 2008
Chassis No : MRHCP16308P020038
Date of Accident : 04/02/2018

No	Qty	Description	Amount S
		<u>List Items:-</u>	
1	1	Rear bootlid	\$ R 878.10
2	1	Rear bootlid badge	\$ M 32.10
3	1	Rear bootlid "Accord" emblem	\$ M 28.20
4	1	Rear bootlid "i-VTEC" emblem	\$ M 33.20
5	1	Rear bootlid inner lock	\$ R 110.90
6	1	Rear bootlid weatherstrip	\$ S 85.00
7	2	Rear bootlid stopper	\$ S 18.00
8	1	Rear bootlid refelctor LH	\$ S 172.20
9	1	Rear bootlid refelctor RH	\$ S 172.20
10	1	LH taillamp	\$ S 295.80
11	1	RH taillamp	\$ S 295.80
12	1	Rear bumper	\$ R 630.50
13	2	Rear bumper side retainer	\$ M/D 35.00
14	10	Rear bumper clip	\$ M 38.00
15	1	Rear bumper reinforcement	\$ B 145.60
16	1	End panel	\$ R 287.80
17	1	End panel top garnish	\$ M/D 97.70
18	6	End panel top garnish clip	\$ M 22.80
19	1	Rear floor panel board	\$ S 133.00
20	1	Front bumper	\$ R 976.00
21	2	Front bumper side retainer	\$ S 46.00
22	10	Front bumper clip	\$ M 38.00
			Total - List Item \$ 4,571.90
			Less 20% \$ 914.38
			Total \$ 3,657.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey estimate after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications are allowed
- Supplementary charges must be reviewed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18002369/Kea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-07-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 7723M	Veh. Inspected	SJR 2471Y
Policy No.	Z/17/VP05/014477	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020372	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ACCORD (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MRHCP16308P020038	Colour	WHITE
Odometer	172522	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/02/2018	Inspection Date	06/02/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 2471Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	878.10	-
1	REAR BOOTLID BADGE	NECESSARY	32.10	32.10
1	REAR BOOTLID "ACCORD" EMBLEM	NECESSARY	28.20	28.20
1	REAR BOOTLID "I-VTEC" EMBLEM	NECESSARY	33.20	33.20
1	REAR BOOTLID INNER LOCK	TO REPAIR SEE LABOUR	110.90	-
1	REAR BOOTLID WEATHERSTRIP	SERVICEABLE	85.00	-
2	REAR BOOTLID STOPPER	SERVICEABLE	18.00	-
1	REAR BOOTLID REFLECTOR LH	SERVICEABLE	172.20	-
1	REAR BOOTLID REFLECTOR RH	SERVICEABLE	172.20	-
1	LH TAILLAMP	SERVICEABLE	295.80	-
1	RH TAILLAMP	SERVICEABLE	295.80	-
1	REAR BUMPER	BENT	630.50	630.50
2	REAR BUMPER SIDE RETAINER	N/S DISTORTED	35.00	17.50
10	REAR BUMPER CLIP	NECESSARY	38.00	38.00
1	REAR BUMPER REINFORCEMENT	BENT	145.60	145.60
1	END PANEL	TO REPAIR SEE LABOUR	287.80	-
1	END PANEL TOP GARNISH	MTG DISTORTED	97.70	97.70
6	END PANEL TOP GARNISH CLIP	NECESSARY	22.80	22.80
1	REAR FLOOR PANEL BOARD	SERVICEABLE	133.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	976.00	-
2	FRONT BUMPER SIDE RETAINER	SERVICEABLE	46.00	-
10	FRONT BUMPER CLIP	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-914.38	-209.12
			3,657.52	836.48
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE WITH HOLDER (SN)	DENTED	55.00	40.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	55.00	-

Report Ref No. CC4/LPC18002369/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN) <u>LABOUR</u> SPRAY PAINTING ON ALL AFFECTED AREA. LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID INNER LOCK, END PANEL AND FRONT BUMPER. TO APPLY ANTI RUST TREATMENT. TO CHECK WIRING SYSTEM & LIGHT. TO CHECK & ADJUST WHEEL ALIGNMENT. TO REMOVE AND REPLACE REVERSE SENSOR.	SHORTED	380.00	200.00
			490.00	240.00
		NOT NECESSARY	1,200.00	800.00
			1,400.00	600.00
		NOT NECESSARY	120.00	-
			60.00	40.00
		NOT NECESSARY	120.00	-
			120.00	50.00
GRAND TOTAL			7,167.52	2,566.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CC4/LPC18002369/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.