

SMRT Accident Vehicle Repair Estimates

China Taipei

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5377A
 Ref. No : TAX/01/18/2184
 Reg. Date : 03/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : MOHAMMED AYUB S/O SALIHEEN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 31/01/2018 09:11:00 AM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094394
 Special Instruction to ARC, if any :
 GBB8844U
 Prepared Date : 31/01/2018 02:22:41 PM



*Sebastian.
1/2/2018.*

- Part by part repair.

- Question Mark Item Photo

- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403573979

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,674.00	0.00
Total Material Charges :	9,879.90	9,879.90
Other Charges :	820.00	0.00
TOTAL :	13,387.90	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sign Off Date :	01/02/2018 10:50:21 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 10:50:21 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY SPOILER	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	820.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No ☒ CRK
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ?
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No ☒ CRK
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No ☒ R
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No ☒ NEC
5246247030			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	2.85	Replace	Replace	No ?
5246247020			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	2.85	Replace	Replace	No ?
5246247010			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	2.85	Replace	Replace	No ?
5219147030			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	8.25	Replace	Replace	No ?
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ☒ NEC
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ☒ BT
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No ?
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No ☒ R
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No ☒ CRK
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ☒ NEC
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No ☒ NEC
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ☒ NEC
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ☒ NEC
	COMMON		STICKER DECAL 65558888	1	21.60	0.00	21.60	Replace	Replace	No ☒ NEC
3480147031			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace	No ☒
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ☒
3810547231			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	25.00	1,177.27	Replace	Replace	No ☒
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No ☒
3788147030			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No ☒
312703310			LAMP ASSY, LICENSE PLATE	2	63.70	10.00	114.66	Replace	Replace	No ?

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
-			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No X
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No X
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No ?
6932147010			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.97	Replace	Replace	No X
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace	No X
6775047080C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.62	Replace	Replace	No ?
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace	No ✓CRK
8100647030			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	Replace	Replace	No ?
7505647010			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	52.70	25.00	39.52	Replace	Replace	No ✓CRK
7560747010			MOULDING SUB-ASSY, ROOF TOP	1	637.40	25.00	478.05	Replace	Replace	No ✓CRK
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No K
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No ?
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No ✓CRK
TOTAL MATERIALS							9,485.69	9,485.61		
TOTAL MATERIALS(Discounted)							9,879.90	9,879.90		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									