

# STAR AUTOMOBILE SERVICES PTE. LTD.

Block 5033, Ang Mo Kio Industrial Park 2 # 01-255

Singapore 569536

Tel: 83488858, Fax:

## ESTIMATED COST OF REPAIR

Insurance: AXA Insurance Singapore Pte. Ltd.

Vehicle Registration Number: SDT 8998R (Toyota Estima 2.4 Aeras)

Date of accident: 01 February 2018

Replacement Of Damaged Panels/Parts		S\$ Price
<b>REPLACEMENT OF DAMAGED PANELS/PARTS</b>		<b>LESS 25%</b>
01.	1 pc rear LH taillamp	706.68 <i>See</i>
		-----
		706.68
		176.67
		-----
		<b>530.01</b>
		-----
<b>LABOUR CHARGES</b>		
01.	To remove damaged parts and attachments, to repair rear LH fender.	100.00
02.	To respray paint on rear LH fender, fender protector, LH sliding door protector and rear bumper.	900.00
		-----
		<b>1,000.00</b>
		-----
<b>TOTAL REPLACEMENT OF DAMAGED PANELS/PARTS</b>		530.01
<b>TOTAL LABOUR CHARGES</b>		1,000.00
		-----
<b>GRAND TOTAL</b>		<b>1,530.01</b>
		-----

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Same*  
*HP 90010068*

*2 days*

*HP 4/5*

*06/02/18 P1600hrs*  
*after*  
*Reg by repairer*